

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

60.0

2.0

Intersection ID: N/A Main Street: Cross Street: N/A Location: N/A

ADA ID: 81F83884C7DA Signal Type: Two Push Buttons-Non APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

Button Count

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button2 N/A Distant to Additional Button (in)

Additional Button ID

N/A N/A Additional Ped Posts Required

Data



Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign. Provide PAR As Indicated. Provide Clear Space.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R404.3, R404.7.1, R404.7.2

Total Cost:

N/A N/A B 2 Tone Audible Range?

\$ 1450.00

NonAPS N/A

> N/A N/A N/A

N/A

N/A N/A

N/A

N/A

N/A

No B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)





		•			•	
		How Many Ped Street Xings?	2		Located In An Island/Median?	No
	N/A	B 1 Sign Present?	Yes	N/A	B 2 Sign Present?	Yes
	Yes	B 1 Sign Purpose?	Yes	Yes	B 2 Sign Purpose?	Yes
	Yes	B 1 Sign Lettering & Contrast?	Yes	Yes	B 2 Sign Lettering & Contrast?	Yes
	Yes	B 1 Parallel To XWalk?	Yes	Yes	B 2 Parallel To XWalk?	Yes
	Yes	B 1 PAR to Button?	No	Yes	B 2 PAR to Button?	No
	No	B 1 PAR to XWalk?	Yes	No	B 2 PAR to XWalk?	Yes
	Yes	B 1 Clear Floor Space?	Yes	Yes	B 2 Clear Floor Space?	Yes
	No	B 1 FWD Approach?	No	No	B 2 FWD Approach?	No
0	N/A	B 1 FWD Approach Constrained?	N/A	N/A	B 2 FWD Approach Constrained?	N/A
	N/A	B 1 FWD Approach Reach (in)	N/A	N/A	B 2 FWD Approach Reach (in)	N/A
á	N/A	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)	N/A
	N/A	B 1 FWD Approach Obstruction?	N/A	N/A	B 2 FWD Approach Obstruction?	N/A
	N/A	B 1 FWD Approach Obstruction Dist (in)	N/A	N/A	B 2 FWD Approach ObstructionDist (in)	N/A
34	No	B 1 PARA Approach?	No	No	B 2 PARA Approach?	No
	N/A	B 1 PARA Approach Constrained?	N/A	N/A	B 2 PARA Approach Constrained?	N/A
	N/A	B 1 PARA Approach Reach (in)	N/A	N/A	B 2 PARA Approach Reach (in)	N/A
N.	N/A	B 1 PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)	N/A
	N/A	B 1 PARA Approach Obstruction?	N/A	N/A	B 2 PARA Approach Obstruction?	N/A
	N/A	B 1 PARA Approach Obstruction Dist (in)	N/A	N/A	B 2 PARA Approach ObstructionDist (in)	N/A
	Yes	B 1 Clear Floor Space Slope (%)	0.6	Yes	B 2 Clear Floor Space Slope (%)	0.4
	Yes	B 1 Clear Floor Space XSlope (%)	1.7	Yes	B 2 Clear Floor Space XSlope (%)	1.6
	N/A	B 1 PAR Slope (%)	5.7	N/A	B 2 PAR Slope (%)	2.6
	Yes	B 1 Height (in)	39.0	Yes	B 2 Height (in)	40.0
	Yes	B 1 Pressure (#)	2.0	Yes	B 2 Pressure (#)	2.0
	Yes	B 1 Closed Fist Operation?	Yes	Yes	B 2 Closed Fist Operation?	Yes
	MUTCD Compliance					
	Yes				B 2 Clear Xing Direction? ClearlyMa	
		B 1 Crossing Direction To	o NW		B 2 Crossing Direction	To S
	Yes	B 1 DistanceTo XWalk (in)	0.0	Yes	B 2 DistanceTo XWalk (in)	58.0

118.0 Yes B 2 DistanceTo Curb (in)

2.0 Yes B 2 Diameter (in)

	APS Compliance		
Is Button 1 APS or Non-APS?	NonAPS Is Button 2 APS or Non-APS?		
N/A B 1 VibroTact Arrow?	N/A N/A B 2 VibroTact Arrow?		
N/A B 1 VibroTact Parallel to Xing?	N/A N/A B 2 VibroTact Parallel to Xing?		
N/A B 1 VibroTact Contrast	N/A N/A B 2 VibroTact Contrast		
N/A B 1 Pilot Light?	N/A N/A B 2 Pilot Light?		
N/A B 1 Pilot Light Illumination?	N/A N/A B 2 Pilot Light Illumination?		
N/A B 1 Verbal Walk Cycle?	N/A N/A B 2 Verbal Walk Cycle?		
N/A B 1 Verbal Message Audible?	N/A N/A B 2 Verbal Message Audible?		
N/A B 1 Locator Tone?	N/A N/A B 2 Locator Tone?		
N/A B 1 Percussive Walk Cycle?	N/A N/A B 2 Percussive Walk Cycle?		
N/A B 1 Extended Press Feature?	N/A N/A B 2 Extended Press Feature?		

N/A B 1 Tone Audible Range?