cole

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Intersection ID: N/A	ection ID: N/A Main Street: Cro						Loca	tion: N/A	
ADA ID: 82018BD18A78	Signal Type: O	ne Push Button-Non APS	Overall Co	ompliance: No	Severity Score: I	BTN 1:N//	A BTN 2: N/A	No BTN:	N/A
Code	s/Mitigation Info		Field Measurements/Component Compliance						
Bossible Solutions: Benlace Signal			nal Buch	Compliance Description		Data Compliance Description		on	Data
AUDITATE FOR	Sec 1	Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.		Button Count	Bu	utton1 Yes	Distant to Additiona	al Button (in)	128.0
MAROLLI I				Additional Button Present?		Yes	Additional Button I	43D5	0AE34AA9
CLESSON - AVIA	7.			N/A Signal Buttons Required?		N/A N/A	Additional Ped Pos	ts Required	N/A
		Surveyor Notes: N/A		How Many Ped Street Xings?		1	Located In An Islan	d/Median?	No
				N/A B 1 Sign Present?		Yes N/A	B 2 Sign Present?		N/A
	10			Yes B 1 Sign Purpose?		Yes N/A	B 2 Sign Purpose?		N/A
				g & Contrast?	Yes N/A	B 2 Sign Lettering	& Contrast?	N/A	
	ALIFUE			Yes B 1 Parallel To XWalk?		Yes N/A	B 2 Parallel To XW	alk?	N/A
		PROW/ADA: TMUTCD 4e.08, R404.2, R406.2		Yes B 1 PAR to Button?		Yes N/A	B 2 PAR to Button?	,	N/A
ENG?			Yes B 1 PAR to XWalk?		Yes N/A	B 2 PAR to XWalk?	•	N/A	
				Yes B 1 Clear Floor Space?		Yes N/A	B 2 Clear Floor Spa	ace?	N/A
				ch?	Yes N/A	B 2 FWD Approach	?	N/A	
		Total Cost: \$	650.00	N/A B 1 FWD Approac	ch Constrained?	No N/A	B 2 FWD Approach	Constrained?	N/A
				No B 1 FWD Approac	ch Reach (in)	6.0 N/A	B 2 FWD Approach	Reach (in)	N/A
				N/A B 1 FWD Approac	ch Width (in)	N/A N/A	B 2 FWD Approach	ı Width (in)	N/A
			11 1 1	N/A B 1 FWD Approac	ch Obstruction?	Yes N/A	B 2 FWD Approach	Obstruction?	N/A
				N/A B 1 FWD Approac	ch Obstruction Dist (in)	2.0 N/A	B 2 FWD Approach	ObstructionDis	t (in) N/A
				N/A B 1 PARA Approach?		Yes N/A	B 2 PARA Approac	h?	N/A
				N/A B 1 PARA Approach Constrained?		No N/A	B 2 PARA Approac	h Constrained?	N/A
				Yes B1 PARA Approach Reach (in)		6.0 N/A	B 2 PARA Approac	h Reach (in)	N/A
				N/A B1 PARA Approach Width (in)		N/A N/A	B 2 PARA Approac	h Width (in)	N/A
				N/A B 1 PARA Approach Obstruction?		Yes N/A	B 2 PARA Approac	h Obstruction?	N/A
	APS Complian	ce		N/A B 1 PARA Approa	ach Obstruction Dist (in)	2.0 N/A	B 2 PARA Approac	h ObstructionDis	st (in) N/A
Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	N/A	Yes B 1 Clear Floor S	pace Slope (%)	4.4 N/A	B 2 Clear Floor Spa	ace Slope (%)	N/A
N/A B 1 VibroTact Arrow?	N/A N/A	B 2 VibroTact Arrow?	N/A	No B 1 Clear Floor S	pace XSlope (%)	5.7 N/A	B 2 Clear Floor Spa	ace XSlope (%)	N/A
N/A B 1 VibroTact Parallel to Xing?	N/A N/A	B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%	%)	5.5 N/A	B 2 PAR Slope (%)		N/A
N/A B 1 VibroTact Contrast	N/A N/A	B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)		39.0 N/A	B 2 Height (in)		N/A
N/A B 1 Pilot Light?	N/A N/A	B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)		2.0 N/A	B 2 Pressure (#)		N/A
N/A B 1 Pilot Light Illumination?	N/A N/A	B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist O	peration?	Yes N/A	B 2 Closed Fist Op	eration?	N/A
N/A B 1 Verbal Walk Cycle?	N/A N/A	A B 2 Verbal Walk Cycle? N/A				MUTCD Compliance			
N/A B 1 Verbal Message Audible?	N/A N/A	B 2 Verbal Message Audible?	N/A	Yes B1 Clear Xing Dir	rection? ClearlyM	arked N/A	B 2 Clear Xing Dire	ection?	N/A
N/A B 1 Locator Tone?	N/A N/A	B 2 Locator Tone?	N/A	B 1 Crossing Dire	ection	To NE	B 2 Crossing Direc	tion	N/A
N/A B 1 Percussive Walk Cycle?	N/A N/A	B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo X	Walk (in)	10.0 N/A	B 2 DistanceTo XW	/alk (in)	N/A
N/A B 1 Extended Press Feature?	N/A N/A	B 2 Extended Press Feature?	N/A	No B 1 DistanceTo C	urb (in)	81.0 N/A	B 2 DistanceTo Cu	rb (in)	N/A
N/A B 1 Tone Audible Range?	N/A N/A	B 2 Tone Audible Range?	N/A	Yes B 1 Diameter (in)		2.0 N/A	B 2 Diameter (in)		N/A