
		Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.			
		Surveyor Notes: N/A		PROW/ADA: TMUTCD 4e.08, R404.1, R404.7.1, R404.7.2	
Total Cost:		\$ 650.00			
APS Compliance					
Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	N/A		
N/A B 1 VibroTact Arrow?	No	N/A B 2 VibroTact Arrow?	N/A		
N/A B 1 VibroTact Parallel to Xing?	No	N/A B 2 VibroTact Parallel to Xing?	N/A		
N/A B 1 VibroTact Contrast	No	N/A B 2 VibroTact Contrast	N/A		
N/A B 1 Pilot Light?	No	N/A B 2 Pilot Light?	N/A		
N/A B 1 Pilot Light Illumination?	No	N/A B 2 Pilot Light Illumination?	N/A		
N/A B 1 Verbal Walk Cycle?	No	N/A B 2 Verbal Walk Cycle?	N/A		
N/A B 1 Verbal Message Audible?	No	N/A B 2 Verbal Message Audible?	N/A		
N/A B 1 Locator Tone?	No	N/A B 2 Locator Tone?	N/A		
N/A B 1 Percussive Walk Cycle?	No	N/A B 2 Percussive Walk Cycle?	N/A		
N/A B 1 Extended Press Feature?	No	N/A B 2 Extended Press Feature?	N/A		
N/A B 1 Tone Audible Range?	No	N/A B 2 Tone Audible Range?	N/A		
MUTCD Compliance					
Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	N/A		
N/A B 1 VibroTact Arrow?	No	N/A B 2 VibroTact Arrow?	N/A		
N/A B 1 VibroTact Parallel to Xing?	No	N/A B 2 VibroTact Parallel to Xing?	N/A		
N/A B 1 VibroTact Contrast	No	N/A B 2 VibroTact Contrast	N/A		
N/A B 1 Pilot Light?	No	N/A B 2 Pilot Light?	N/A		
N/A B 1 Pilot Light Illumination?	No	N/A B 2 Pilot Light Illumination?	N/A		
N/A B 1 Verbal Walk Cycle?	No	N/A B 2 Verbal Walk Cycle?	N/A		
N/A B 1 Verbal Message Audible?	No	N/A B 2 Verbal Message Audible?	N/A		
N/A B 1 Locator Tone?	No	N/A B 2 Locator Tone?	N/A		
N/A B 1 Percussive Walk Cycle?	No	N/A B 2 Percussive Walk Cycle?	N/A		
N/A B 1 Extended Press Feature?	No	N/A B 2 Extended Press Feature?	N/A		
N/A B 1 Tone Audible Range?	No	N/A B 2 Tone Audible Range?	N/A		