

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

No

N/A N/A

N/A N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Main Street: Location: N/A Intersection ID: N/A Cross Street: N/A

ADA ID: 85BA5A0D15D2 Signal Type: One Push Button-Non APS **Overall Compliance: No** Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

Additional Button Present?

N/A B 1 PARA Approach Constrained? Yes B 1 PARA Approach Reach (in)

N/A B 1 PARA Approach Width (in)

B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)

Button Count

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 N/A Distant to Additional Button (in)

Additional Button ID

No N/A B 2 PARA Approach Constrained?

8.0 N/A B 2 PARA Approach Reach (in)

N/A N/A B 2 PARA Approach Width (in)

74.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)

Data

No



N/A B 1 Extended Press Feature? N/A B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Replace Sign.

Surveyor Notes: N/A


N/A B 2 Extended Press Feature?

N/A N/A B 2 Tone Audible Range?

PROW/ADA: R410.6, TMUTCD 4e.08, R404.2, R406.2

Total Cost:







N/A B 1 PARA Approach Obstruction? Yes N/A B 2 PARA Approach Obstruction? **APS Compliance** N/A B 1 PARA Approach Obstruction Dist (in) **8.0 N/A** B 2 PARA Approach Obstruction Dist (in) Is Button 1 APS or Non-APS? NonAPS Is Button 2 APS or Non-APS? N/A Yes B 1 Clear Floor Space Slope (%) **0.6 N/A** B 2 Clear Floor Space Slope (%) N/A B 1 VibroTact Arrow? N/A N/A B 2 VibroTact Arrow? N/A No B 1 Clear Floor Space XSlope (%) 9.0 N/A B 2 Clear Floor Space XSlope (%) N/A B 1 VibroTact Parallel to Xing? N/A B 2 VibroTact Parallel to Xing? N/A N/A B 1 PAR Slope (%) **0.3** N/A B 2 PAR Slope (%) N/A 48.0 N/A B 2 Height (in) N/A B 1 VibroTact Contrast N/A N/A B 2 VibroTact Contrast Yes B 1 Height (in) N/A B 1 Pilot Light? N/A N/A B 2 Pilot Light? N/A Yes B 1 Pressure (#) 2.0 N/A B 2 Pressure (#) N/A B 2 Pilot Light Illumination? N/A Yes B 1 Closed Fist Operation? Yes N/A B 2 Closed Fist Operation? N/A B 1 Pilot Light Illumination? N/A B 1 Verbal Walk Cycle? N/A B 2 Verbal Walk Cycle? N/A **MUTCD Compliance** ClearlyMarked N/A B 2 Clear Xing Direction? N/A B 1 Verbal Message Audible? N/A B 2 Verbal Message Audible? N/A Yes B 1 Clear Xing Direction? N/A B 1 Locator Tone? N/A N/A B 2 Locator Tone? N/A **B 1 Crossing Direction** To S **B 2 Crossing Direction** N/A B 1 Percussive Walk Cycle? N/A B 2 Percussive Walk Cycle? N/A Yes B 1 DistanceTo XWalk (in) N/A B 2 DistanceTo XWalk (in)

N/A

N/A