

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A N/A No

N/A N/A N/A

N/A

N/A N/A N/A

N/A N/A N/A

N/A N/A

> N/A N/A

N/A

N/A

N/A

Intersection ID: N/A Main Street: Cross Street: N/A Location: N/A

ADA ID: 8F65C888C8D8 Signal Type: One Push Button-Non APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



N/A B 1 Extended Press Feature?N/A B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Replace Sign.

Surveyor Notes: TEXT HT 1/2

PROW/ADA: R410.6, R209.1, TMUTCD 4e.08, R404.2, R404.3, R406.2, R404.7.3

Total Cost:

700.00

N/A

N/A

N/A B 1 PARA Approach Width (in)

No B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)



Con	npliance	Description	Data	Com	pliance	Description	D
	Button C	ount	Button1	N/A	Distant t	to Additional Button (in)	
	Additiona	al Button Present?	No		Addition	al Button ID	
N/A	Signal B	uttons Required?	N/A	N/A	Addition	al Ped Posts Required	
	How Mar	ny Ped Street Xings?	2		Located	In An Island/Median?	
N/A	B 1 Sign	Present?	Yes	N/A	B 2 Sign	Present?	
Yes	B 1 Sign	Purpose?	Yes	N/A	B 2 Sign	Purpose?	
No	B 1 Sign	Lettering & Contrast?	No	N/A	B 2 Sign	Lettering & Contrast?	
No	B 1 Para	illel To XWalk?	No	N/A	B 2 Para	allel To XWalk?	
Yes	B 1 PAR	to Button?	Yes	N/A	B 2 PAR	R to Button?	
Yes	B 1 PAR	to XWalk?	Yes	N/A	B 2 PAR	to XWalk?	
Yes	B 1 Clea	r Floor Space?	Yes	N/A	B 2 Clea	ar Floor Space?	
N/A	B 1 FWD	Approach?	Yes	N/A	B 2 FWI	O Approach?	
N/A	B 1 FWD	Approach Constrained?	No	N/A	B 2 FWI	O Approach Constrained?	
No	B 1 FWD	Approach Reach (in)	12.0	N/A	B 2 FWI	O Approach Reach (in)	
N/A	B 1 FWD	Approach Width (in)	N/A	N/A	B 2 FWI	O Approach Width (in)	
N/A	B 1 FWD	Approach Obstruction?	Yes	N/A	B 2 FWI	O Approach Obstruction?	
N/A	B 1 FWD	Approach Obstruction Dist (in) 3.5	N/A	B 2 FWI	O Approach ObstructionDist (in)
N/A	B 1 PAR	A Approach?	Yes	N/A	B 2 PAR	RA Approach?	
N/A	B 1 PAR	A Approach Constrained?	No	N/A	B 2 PAR	RA Approach Constrained?	
No	B 1 PAR	A Approach Reach (in)	12.0	N/A	B 2 PAR	RA Approach Reach (in)	
				I			



APS Compliance Is Button 1 APS or Non-APS? **NonAPS** Is Button 2 APS or Non-APS? N/A N/A N/A B 2 VibroTact Arrow? N/A N/A B 1 VibroTact Arrow? N/A B 1 VibroTact Parallel to Xing? N/A B 2 VibroTact Parallel to Xing? N/A N/A B 2 VibroTact Contrast N/A B 1 VibroTact Contrast N/A N/A N/A B 1 Pilot Light? N/A N/A B 2 Pilot Light? N/A N/A N/A B 2 Pilot Light Illumination? **N/A** B 1 Pilot Light Illumination? N/A N/A B 1 Verbal Walk Cycle? N/A B 2 Verbal Walk Cycle? N/A N/A B 1 Verbal Message Audible? N/A N/A B 2 Verbal Message Audible? N/A N/A B 1 Locator Tone? N/A N/A B 2 Locator Tone? N/A N/A B 1 Percussive Walk Cycle? N/A N/A B 2 Percussive Walk Cycle? N/A

N/A N/A B 2 Extended Press Feature?

N/A N/A B 2 Tone Audible Range?

	,			, ,							
N/A	B 1 PARA Approach Obstruction?	Yes	N/A	B 2 PARA Approach Obstruction?	N/A						
N/A	B 1 PARA Approach Obstruction Di	ist (in) 3.5	N/A	B 2 PARA Approach ObstructionDist (in)	N/A						
No	B 1 Clear Floor Space Slope (%)	4.0	N/A	B 2 Clear Floor Space Slope (%)	N/A						
No	B 1 Clear Floor Space XSlope (%)	3.5	N/A	B 2 Clear Floor Space XSlope (%)	N/A						
N/A	B 1 PAR Slope (%)	2.2	N/A	B 2 PAR Slope (%)	N/A						
Yes	B 1 Height (in)	36.0	N/A	B 2 Height (in)	N/A						
Yes	B 1 Pressure (#)	2.0	N/A	B 2 Pressure (#)	N/A						
Yes	B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A						
MUTCD Compliance											
Yes	B 1 Clear Xing Direction?	earlyMarked	N/A	B 2 Clear Xing Direction?	N/A						
	B 1 Crossing Direction	To N		B 2 Crossing Direction	N/A						
Yes	B 1 DistanceTo XWalk (in)	0.0	N/A	B 2 DistanceTo XWalk (in)	N/A						
			ı								

N/A N/A B 2 PARA Approach Width (in)

94.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)