

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

DC1EA7A0CB24

222.0

N/A

No

N/A

N/A

N/A

N/A

N/A

Location: N/A Intersection ID: N/A **Main Street:** Cross Street: N/A

Signal Type: One Push Button-Non APS **Overall Compliance: No** Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A ADA ID: 9238E0550A0C

Compliance Description

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?


N/A Signal Buttons Required?

Button Count

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Codes/Mitigation Info/Possible Solution



Compliance Description

Button1 Yes Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes N/A B 2 Sign Lettering & Contrast?

99.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)

Located In An Island/Median?

Data

Yes



Possible Solutions: Replace Signal Push **Button With APS Button on New Post.** Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R404.7.2

Total Cost:

650.00

N/A

N/A

No B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)





	.00	B 1 oigh Lottoning & Contract:		117/7	b 2 digit Lottorning & Contract:	14//-			
	Yes	Yes B 1 Parallel To XWalk? Yes B 1 PAR to Button? Yes B 1 PAR to XWalk? Yes B 1 Clear Floor Space? N/A B 1 FWD Approach?		N/A	B 2 Parallel To XWalk?	N/A			
	Yes			N/A	B 2 PAR to Button?	N/A			
	Yes			N/A	B 2 PAR to XWalk?	N/A			
	Yes			N/A	B 2 Clear Floor Space?	N/A			
	N/A			N/A	B 2 FWD Approach?	N/A			
N/A		B 1 FWD Approach Constrained?	N/A	N/A	B 2 FWD Approach Constrained?	N/A			
	N/A	B 1 FWD Approach Reach (in)	N/A	N/A	B 2 FWD Approach Reach (in)	N/A			
	N/A	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)	N/A			
	N/A	I/A B 1 FWD Approach Obstruction?		N/A	B 2 FWD Approach Obstruction?	N/A			
	N/A	B 1 FWD Approach Obstruction Dist (in)	N/A	N/A	B 2 FWD Approach ObstructionDist (in)	N/A			
	N/A	/A B 1 PARA Approach?		N/A	B 2 PARA Approach?	N/A			
	N/A	A B 1 PARA Approach Constrained?		N/A	B 2 PARA Approach Constrained?	N/A			
	Yes	s B 1 PARA Approach Reach (in)		N/A	B 2 PARA Approach Reach (in)	N/A			
	No	B 1 PARA Approach Width (in)		N/A	B 2 PARA Approach Width (in)	N/A			
	N/A	I/A B 1 PARA Approach Obstruction?I/A B 1 PARA Approach Obstruction Dist (in)i/es B 1 Clear Floor Space Slope (%)		N/A	B 2 PARA Approach Obstruction?	N/A			
	N/A			N/A	B 2 PARA Approach ObstructionDist (in)	N/A			
	Yes			N/A	B 2 Clear Floor Space Slope (%)	N/A			
	Yes	s B 1 Clear Floor Space XSlope (%)		N/A	B 2 Clear Floor Space XSlope (%)	N/A			
	N/A	/A B 1 PAR Slope (%)		N/A	B 2 PAR Slope (%)	N/A			
	Yes	es B1 Height (in)		N/A B 2 Height (in)		N/A			
	Yes	s B 1 Pressure (#)		N/A	B 2 Pressure (#)	N/A			
	Yes	B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A			
MUTCD Compliance									
	Yes	B 1 Clear Xing Direction? ClearlyMan	rked	N/A	B 2 Clear Xing Direction?	N/A			
		B 1 Crossing Direction To	o NE		B 2 Crossing Direction	N/A			
	Yes	B 1 DistanceTo XWalk (in)	0.0	N/A	B 2 DistanceTo XWalk (in)	N/A			

	Is Button 1 APS or Non-APS?
N/A	B 1 VibroTact Arrow?
N/A	B 1 VibroTact Parallel to Xing?
N/A	B 1 VibroTact Contrast
N/A	B 1 Pilot Light?
N/A	B 1 Pilot Light Illumination?
N/A	B 1 Verbal Walk Cycle?
N/A	B 1 Verbal Message Audible?
N/A	B 1 Locator Tone?
N/A	B 1 Percussive Walk Cycle?
N/A	B 1 Extended Press Feature?

N/A B 1 Tone Audible Range?

APS Compliance						
NonAPS		Is Button 2 APS or Non-APS?	N/A			
N/A	N/A	B 2 VibroTact Arrow?	N/A			
N/A	N/A	B 2 VibroTact Parallel to Xing?	N/A			
N/A	N/A	B 2 VibroTact Contrast	N/A			
N/A	N/A	B 2 Pilot Light?	N/A			
N/A	N/A	B 2 Pilot Light Illumination?	N/A			
N/A	N/A	B 2 Verbal Walk Cycle?	N/A			
N/A	N/A	B 2 Verbal Message Audible?	N/A			
N/A	N/A	B 2 Locator Tone?	N/A			
N/A	N/A	B 2 Percussive Walk Cycle?	N/A			

N/A N/A B 2 Extended Press Feature?

N/A N/A B 2 Tone Audible Range?