

## **Access Compliance Report Public Rights-of-Way** (Pedestrian Signals)



Data

3E19A671DAB7

292.0

N/A

No

N/A N/A

N/A N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

**Main Street:** Intersection ID: N/A Cross Street: N/A Location: N/A

ADA ID: 93103BD9D207 Signal Type: One Push Button-APS **Overall Compliance: No** Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

N/A B 1 FWD Approach Reach (in) N/A B 1 FWD Approach Width (in)

N/A B 1 FWD Approach Obstruction?

Yes B 1 DistanceTo XWalk (in)

Yes B 1 Diameter (in)

B 1 DistanceTo Curb (in)

N/A B 1 FWD Approach Obstruction Dist (in)

**Button Count** 

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 Parallel To XWalk?

Yes B 1 PAR to Button?

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Compliance Description

**Button1 Yes** Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Yes N/A B 2 Parallel To XWalk?

N/A B 2 PAR to Button?

N/A B 2 PAR to XWalk?

Yes N/A B 2 Clear Floor Space? No N/A B 2 FWD Approach?

Additional Button ID

Yes N/A B 2 Sign Lettering & Contrast?

**No N/A** B 2 FWD Approach Constrained?

N/A B 2 FWD Approach Obstruction?

N/A N/A B 2 FWD Approach ObstructionDist (in)

N/A N/A B 2 FWD Approach Reach (in)

N/A N/A B 2 FWD Approach Width (in)

0.0 N/A B 2 DistanceTo XWalk (in)

76.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)

N/A Additional Ped Posts Required

Located In An Island/Median?

Data

Yes

N/A



Yes B 1 Percussive Walk Cycle?

Yes B 1 Extended Press Feature?

Yes B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A


N/A B 2 Percussive Walk Cycle?

Yes N/A B 2 Extended Press Feature?

Yes N/A B 2 Tone Audible Range?

PROW/ADA: TMUTCD 4e.08, R404.2, R404.3, R209.1, MUTCD 4e.10

Total Cost:





N/A B 1 PARA Approach? Yes N/A B 2 PARA Approach? N/A No N/A B 2 PARA Approach Constrained? N/A **N/A** B 1 PARA Approach Constrained? Yes B 1 PARA Approach Reach (in) 9.0 N/A B 2 PARA Approach Reach (in) N/A N/A N/A B 1 PARA Approach Width (in) N/A N/A B 2 PARA Approach Width (in) N/A B 1 PARA Approach Obstruction? Yes N/A B 2 PARA Approach Obstruction? N/A APS Compliance N/A B 1 PARA Approach Obstruction Dist (in) 4.0 N/A B 2 PARA Approach Obstruction Dist (in) N/A Is Button 2 APS or Non-APS? Is Button 1 APS or Non-APS? **APS** No B 1 Clear Floor Space Slope (%) N/A 4.7 N/A B 2 Clear Floor Space Slope (%) N/A Yes B 1 VibroTact Arrow? Yes N/A B 2 VibroTact Arrow? N/A B 1 Clear Floor Space XSlope (%) 7.8 N/A B 2 Clear Floor Space XSlope (%) N/A Yes N/A B 2 VibroTact Parallel to Xing? Yes B 1 VibroTact Parallel to Xing? N/A N/A B 1 PAR Slope (%) 3.3 N/A B 2 PAR Slope (%) N/A N/A N/A Yes B 1 VibroTact Contrast Yes N/A B 2 VibroTact Contrast Yes B 1 Height (in) 35.0 N/A B 2 Height (in) Yes B 1 Pilot Light? Yes N/A B 2 Pilot Light? N/A Yes B 1 Pressure (#) 2.0 N/A B 2 Pressure (#) N/A **N/A** B 2 Pilot Light Illumination? Yes B 1 Closed Fist Operation? Yes N/A B 2 Closed Fist Operation? N/A Yes B 1 Pilot Light Illumination? N/A No B 1 Verbal Walk Cycle? N/A B 2 Verbal Walk Cycle? N/A **MUTCD Compliance** ClearlyMarked N/A B 2 Clear Xing Direction? N/A B 1 Verbal Message Audible? N/A B 2 Verbal Message Audible? N/A Yes B 1 Clear Xing Direction? N/A To NE N/A Yes B 1 Locator Tone? Yes N/A B 2 Locator Tone? N/A **B 1 Crossing Direction B 2 Crossing Direction** 

N/A

N/A

N/A