## cole

N/A B 1 Tone Audible Range?

## Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



2.0 N/A B 2 Diameter (in)

N/A

(										
Intersection ID: N/A Main Street: Cross Street: N/A						Location: N/A				
ADA ID: 946A4A653465 Signal Type:One Push Button-Non APS C				ompliance: No	Severity Score:	BTN 1:N//	A BTN 2: N/A	No BTN:	N/A	
Code	s/Mitigation I	nfo/Possible Solution		Field Measurements/Component Compliance						
		Possible Solutions: Replace Sig		Compliance Desc	ription	Data Com	npliance Descripti	on	Data	
		Button With APS Button on New		Button Count	В	utton1 Yes	Distant to Addition	al Button (in)	176.0	
	D.	Remove & Relocate Sign.		Additional Button Present?		Yes	Additional Button I	D 9754	105D6013	
		A. C.		N/A Signal Buttons Required?		N/A N/A	Additional Ped Pos	sts Required	N/A	
	HE ALL			How Many Ped	Street Xings?	1	Located In An Isla	nd/Median?	No	
A A A		Surveyor Notes: N/A		N/A B 1 Sign Preser	N/A B 1 Sign Present?		B 2 Sign Present?		N/A	
	les (			Yes B 1 Sign Purpos	Yes B 1 Sign Purpose?		B 2 Sign Purpose?	,	N/A	
				Yes B 1 Sign Lettering & Contrast?		Yes N/A	B 2 Sign Lettering	& Contrast?	N/A	
S S AND				Yes B 1 Parallel To XWalk?		Yes N/A	B 2 Parallel To XW	/alk?	N/A	
ESTO MARCA		PROW/ADA: TMUTCD 4e.08, R4	04.2,	Yes B 1 PAR to Button?		Yes N/A	B 2 PAR to Button	?	N/A	
	and a	R404.7.3, R404.7.2		Yes B 1 PAR to XWalk?		Yes N/A	B 2 PAR to XWalk	?	N/A	
				Yes B1 Clear Floor Space?		Yes N/A	B 2 Clear Floor Sp	ace?	N/A	
		N/A B 1 FWD Approach?		No N/A	B 2 FWD Approac	n?	N/A			
an A A A	1 1 1	Total Cost: \$	650.0	0 N/A B 1 FWD Appro	ach Constrained?	No N/A	B 2 FWD Approac	n Constrained?	N/A	
				N/A B 1 FWD Appro	ach Reach (in)	N/A N/A	B 2 FWD Approac	n Reach (in)	N/A	
				N/A B 1 FWD Appro	ach Width (in)	N/A N/A	B 2 FWD Approac	n Width (in)	N/A	
				<b>N/A</b> B 1 FWD Approach Obstruction?		Yes N/A	B 2 FWD Approac	n Obstruction?	N/A	
-				N/A B 1 FWD Appro	ach Obstruction Dist (in)	4.0 N/A	B 2 FWD Approac	n ObstructionDist	t (in) <b>N/A</b>	
			1	N/A B 1 PARA Appro	bach?	Yes N/A	B 2 PARA Approac	h?	N/A	
				N/A B 1 PARA Approach Constrained?		Yes N/A	B 2 PARA Approac	h Constrained?	N/A	
				<b>No</b> B 1 PARA Approach Reach (in)		16.0 N/A	B 2 PARA Approac	h Reach (in)	N/A	
				No B 1 PARA Appro	oach Width (in)		B 2 PARA Approac		N/A	
				N/A B 1 PARA Appro	oach Obstruction?	Yes N/A	B 2 PARA Approac	h Obstruction?	N/A	
	APS Com			N/A B 1 PARA Appro	oach Obstruction Dist (in)	4.0 N/A	B 2 PARA Approac	h ObstructionDis	st (in) <b>N/A</b>	
Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	N/A	Yes B 1 Clear Floor	Space Slope (%)	4.1 N/A	B 2 Clear Floor Sp	ace Slope (%)	N/A	
N/A B 1 VibroTact Arrow?		N/A B 2 VibroTact Arrow?	N/A	No B 1 Clear Floor			B 2 Clear Floor Sp		N/A	
<b>N/A</b> B 1 VibroTact Parallel to Xing?		<b>N/A</b> B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope	(%)		B 2 PAR Slope (%	)	N/A	
N/A B 1 VibroTact Contrast		N/A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)			B 2 Height (in)		N/A	
N/A B 1 Pilot Light?	No	N/A B 2 Pilot Light?	N/A	Yes B 1 Pressure (#			B 2 Pressure (#)		N/A	
N/A B 1 Pilot Light Illumination?		N/A B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist	•	•	B 2 Closed Fist Op	peration?	N/A	
N/A B 1 Verbal Walk Cycle?		N/A B 2 Verbal Walk Cycle? N/A				UTCD Comp				
N/A B 1 Verbal Message Audible?		N/A B 2 Verbal Message Audible?	N/A	Yes B 1 Clear Xing I	-		B 2 Clear Xing Dir		N/A	
N/A B 1 Locator Tone?		N/A B 2 Locator Tone?	N/A	B 1 Crossing Di		To NW	B 2 Crossing Direc		N/A	
N/A B 1 Percussive Walk Cycle?		N/A B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo	( )		B 2 DistanceTo XV	. ,	N/A	
N/A B1 Extended Press Feature?	No	N/A B 2 Extended Press Feature?	N/A	No B 1 DistanceTo	Curb (in)	129.0 N/A	B 2 DistanceTo Cu	ırb (in)	N/A	

N/A

**Yes** B 1 Diameter (in)

No N/A B 2 Tone Audible Range?