

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

No

N/A

N/A

Intersection ID: N/A Main Street: Cross Street: N/A Location: N/A

ADA ID: 95BCA23B4100 Signal Type: One Push Button-Non APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Button Count

N/A B 1 Sign Present?

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 N/A Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

2.0 N/A B 2 Diameter (in)

Additional Button ID

N/A N/A Additional Ped Posts Required

Located In An Island/Median?

Data



Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Replace Sign.

Surveyor Notes: N/A

PROW/ADA: R410.6, TMUTCD 4e.08, R404.2, R406.2

Total Cost:

700.0





		•			•		
	Yes	B 1 Sign Purpose?	Yes	N/A	B 2 Sign Purpose?	N/A	
	No	B 1 Sign Lettering & Contrast?	No	N/A	B 2 Sign Lettering & Contrast?	N/A	
	Yes	B 1 Parallel To XWalk?	Yes	N/A	B 2 Parallel To XWalk?	N/A	
	Yes	B 1 PAR to Button?	Yes	N/A	B 2 PAR to Button?	N/A	
	Yes	B 1 PAR to XWalk?	Yes	N/A	B 2 PAR to XWalk?	N/A	
	Yes	B 1 Clear Floor Space?	Yes	N/A	B 2 Clear Floor Space?	N/A	
	N/A	B 1 FWD Approach?	Yes	N/A	B 2 FWD Approach?	N/A	
00	N/A	B 1 FWD Approach Constrained?	No	N/A	B 2 FWD Approach Constrained?	N/A	
	No	B 1 FWD Approach Reach (in)	5.0	N/A	B 2 FWD Approach Reach (in)	N/A	
4	N/A	B 1 FWD Approach Width (in)	60.0	N/A	B 2 FWD Approach Width (in)	N/A	
	N/A	B 1 FWD Approach Obstruction?	Yes	N/A	B 2 FWD Approach Obstruction?	N/A	
	N/A	B 1 FWD Approach Obstruction Dist (in)	3.0	N/A	B 2 FWD Approach ObstructionDist (in)	N/A	
	N/A	B 1 PARA Approach?	Yes	N/A	B 2 PARA Approach?	N/A	
	N/A	B 1 PARA Approach Constrained?	No	N/A	B 2 PARA Approach Constrained?	N/A	
	Yes	B 1 PARA Approach Reach (in)	5.0	N/A	B 2 PARA Approach Reach (in)	N/A	
	N/A	B 1 PARA Approach Width (in)	60.0	N/A	B 2 PARA Approach Width (in)	N/A	
	N/A	B 1 PARA Approach Obstruction?	Yes	N/A	B 2 PARA Approach Obstruction?	N/A	
	N/A	B 1 PARA Approach Obstruction Dist (in)	3.0	N/A	B 2 PARA Approach ObstructionDist (in)	N/A	
	Yes	B 1 Clear Floor Space Slope (%)	2.0	N/A	B 2 Clear Floor Space Slope (%)	N/A	
	No	B 1 Clear Floor Space XSlope (%)	4.1	N/A	B 2 Clear Floor Space XSlope (%)	N/A	
	N/A	B 1 PAR Slope (%)	2.0	N/A	B 2 PAR Slope (%)	N/A	
	Yes	B 1 Height (in)	42.0	N/A	B 2 Height (in)	N/A	
	Yes	B 1 Pressure (#)	2.0	N/A	B 2 Pressure (#)	N/A	
	Yes	B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A	
MUTCD Compliance							
	Yes	B 1 Clear Xing Direction? ClearlyM	arked	N/A	B 2 Clear Xing Direction?	N/A	
		B 1 Crossing Direction	To SE		B 2 Crossing Direction	N/A	
	No	B 1 DistanceTo XWalk (in)	66.0	N/A	B 2 DistanceTo XWalk (in)	N/A	
	No	B 1 DistanceTo Curb (in)	92.0	N/A	B 2 DistanceTo Curb (in)	N/A	

Is Button 1 APS or Non-APS?	
N/A	B 1 VibroTact Arrow?
N/A	B 1 VibroTact Parallel to Xing?
N/A	B 1 VibroTact Contrast
N/A	B 1 Pilot Light?
N/A	B 1 Pilot Light Illumination?
N/A	B 1 Verbal Walk Cycle?
N/A	B 1 Verbal Message Audible?
N/A	B 1 Locator Tone?
N/A	B 1 Percussive Walk Cycle?
N/A	B 1 Extended Press Feature?

N/A B 1 Tone Audible Range?

APS Compilar	APS Compliance	
NonAPS	Is Button 2 APS or Non-APS?	N/A
No N/A	B 2 VibroTact Arrow?	N/A
No N/A	B 2 VibroTact Parallel to Xing?	N/A
No N/A	B 2 VibroTact Contrast	N/A
No N/A	B 2 Pilot Light?	N/A
No N/A	B 2 Pilot Light Illumination?	N/A
No N/A	B 2 Verbal Walk Cycle?	N/A
No N/A	B 2 Verbal Message Audible?	N/A
No N/A	B 2 Locator Tone?	N/A
No N/A	B 2 Percussive Walk Cycle?	N/A
No N/A	B 2 Extended Press Feature?	N/A

No N/A B 2 Tone Audible Range?

N/A		
N/A	Yes	B 1 Clear Xing Dir
N/A		B 1 Crossing Dire
N/A	No	B 1 DistanceTo X
N/A	No	B 1 DistanceTo C
N/A	Yes	B 1 Diameter (in)