

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A N/A No

N/A N/A N/A N/A

N/A

N/A N/A N/A

N/A N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Signal Type: One Push Button-Non APS Severity Score: BTN 1:N/A BTN 2: N/A No BTN: ADA ID: 967F2CC7A046 **Overall Compliance: No** N/A

Compliance Description

N/A B 1 FWD Approach Obstruction?

N/A B 1 FWD Approach Obstruction Dist (in)

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

No N/A B 2 FWD Approach Obstruction?

N/A N/A B 2 FWD Approach ObstructionDist (in)

Data



Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R404.3, R404.2, R406.2, R406.3, R404.7.3

Total Cost:

650.00

	Button Count	Button1	N/A	Distant to Additional Button (in)		
	Additional Button Present?	No		Additional Button ID		
N/A	Signal Buttons Required?	N/A	N/A	Additional Ped Posts Required		
	How Many Ped Street Xings?	2		Located In An Island/Median?		
N/A	B 1 Sign Present?	Yes	N/A	B 2 Sign Present?		
Yes	B 1 Sign Purpose?	Yes	N/A	B 2 Sign Purpose?		
Yes	B 1 Sign Lettering & Contrast?	Yes	N/A	B 2 Sign Lettering & Contrast?		
Yes	B 1 Parallel To XWalk?	Yes	N/A	B 2 Parallel To XWalk?		
No	B 1 PAR to Button?	Yes	N/A	B 2 PAR to Button?		
Yes	B 1 PAR to XWalk?	No	N/A	B 2 PAR to XWalk?		
Yes	B 1 Clear Floor Space?	Yes	N/A	B 2 Clear Floor Space?		
N/A	B 1 FWD Approach?	Yes	N/A	B 2 FWD Approach?		
N/A	B 1 FWD Approach Constrained?	N/A	N/A	B 2 FWD Approach Constrained?		
No	B 1 FWD Approach Reach (in)	17.0	N/A	B 2 FWD Approach Reach (in)		
No	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)		



N/A B 1 PARA Approach? Yes N/A B 2 PARA Approach? **No N/A** B 2 PARA Approach Constrained? **N/A** B 1 PARA Approach Constrained? No B 1 PARA Approach Reach (in) 17.0 N/A B 2 PARA Approach Reach (in) N/A B 1 PARA Approach Width (in) N/A N/A B 2 PARA Approach Width (in) No N/A B 2 PARA Approach Obstruction? N/A B 1 PARA Approach Obstruction? N/A B 1 PARA Approach Obstruction Dist (in) N/A N/A B 2 PARA Approach ObstructionDist (in) **APS Compliance**

Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	N/A	No B 1 Clear Floor Space Slope (%) 7.0 N/A	B 2 Clear Floor Space Slope (%)	N/A
N/A B 1 VibroTact Arrow?	N/A N/A	B 2 VibroTact Arrow?	N/A	No B 1 Clear Floor Space XSlope (%) 4.5 N/A	B 2 Clear Floor Space XSlope (%)	N/A
N/A B 1 VibroTact Parallel to Xing?	N/A N/A	A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	0.5 N/A	B 2 PAR Slope (%)	N/A
N/A B 1 VibroTact Contrast	N/A N/A	B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	40.0 N/A	B 2 Height (in)	N/A
N/A B 1 Pilot Light?	N/A N/A	B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	0.5 N/A	B 2 Pressure (#)	N/A
N/A B 1 Pilot Light Illumination?	N/A N/A	A B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes N/A	B 2 Closed Fist Operation?	N/A
N/A B 1 Verbal Walk Cycle? N/A		A B 2 Verbal Walk Cycle?	N/A	MUTCD Compliance			
N/A B 1 Verbal Message Audible?	N/A N/A	A B 2 Verbal Message Audible?	N/A	Yes B 1 Clear Xing Direction?	ClearlyMarked N/	B 2 Clear Xing Direction?	N/A
N/A B 1 Locator Tone?	N/A N/A	B 2 Locator Tone?	N/A	B 1 Crossing Direction	To NW	B 2 Crossing Direction	N/A
N/A B 1 Percussive Walk Cycle?	N/A N/A	A B 2 Percussive Walk Cycle?	N/A	No B 1 DistanceTo XWalk (in)	120.0 N/A	B 2 DistanceTo XWalk (in)	N/A
N/A B 1 Extended Press Feature?	N/A N/A	B 2 Extended Press Feature?	N/A	Yes B 1 DistanceTo Curb (in)	26.0 N/A	A B 2 DistanceTo Curb (in)	N/A
N/A B 1 Tone Audible Range?	N/A N/A	B 2 Tone Audible Range?	N/A	Yes B 1 Diameter (in)	2.0 N/A	B 2 Diameter (in)	N/A