

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



N/A

N/A N/A

N/A

N/A

N/A

Intersection ID: N/A Main Street: Cross Street: N/A Location: N/A

ADA ID: 9754105D6013 Signal Type: One Push Button-Non APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



N/A B 1 Extended Press Feature?

N/A B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R404.2, R404.3, R404.7.2

Total Cost:

N/A N/A B 2 Extended Press Feature?

N/A N/A B 2 Tone Audible Range?

650.00

N/A B 1 FWD Approach Obstruction Dist (in)

N/A B 1 PARA Approach Constrained?

Yes B 1 PARA Approach Reach (in)

B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)

N/A B 1 PARA Approach?



	Con	npliance Description	Data	Com	pliance	Description	Data
		Button Count	Button1	Yes	Distant t	o Additional Button (in) 176.0
		Additional Button Present?	Yes		Addition	al Button ID	946A4A653465
	N/A	Signal Buttons Required?	N/A	N/A	Addition	al Ped Posts Required	N/A
		How Many Ped Street Xings?	N/A		Located	In An Island/Median?	N/A
	N/A	B 1 Sign Present?	Yes	N/A	B 2 Sign	Present?	N/A
	Yes	B 1 Sign Purpose?	Yes	N/A	B 2 Sign	Purpose?	N/A
	Yes	B 1 Sign Lettering & Contrast?	Yes	N/A	B 2 Sign	Lettering & Contrast?	N/A
	Yes	B 1 Parallel To XWalk?	Yes	N/A	B 2 Para	allel To XWalk?	N/A
	Yes	B 1 PAR to Button?	Yes	N/A	B 2 PAR	to Button?	N/A
	Yes	B 1 PAR to XWalk?	Yes	N/A	B 2 PAR	to XWalk?	N/A
	Yes	B 1 Clear Floor Space?	Yes	N/A	B 2 Clea	r Floor Space?	N/A
	N/A	B 1 FWD Approach?	No	N/A	B 2 FWI	O Approach?	N/A
0	N/A	B 1 FWD Approach Constrained?	N/A	N/A	B 2 FWI	O Approach Constraine	ed? N/A
	N/A	B 1 FWD Approach Reach (in)	N/A	N/A	B 2 FWI	O Approach Reach (in)	N/A
	N/A	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWI	Approach Width (in)	N/A
1	N/A	B 1 FWD Approach Obstruction?	No	N/A	B 2 FWI	O Approach Obstructio	n? N/A

N/A N/A B 2 FWD Approach ObstructionDist (in)

Yes N/A B 2 PARA Approach Constrained?

8.0 N/A B 2 PARA Approach Reach (in)

Yes N/A B 2 PARA Approach?

118.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)



B 1 PARA Approach Width (in) **48.0** N/A B 2 PARA Approach Width (in) N/A N/A B 1 PARA Approach Obstruction? No N/A B 2 PARA Approach Obstruction? N/A APS Compliance N/A B 1 PARA Approach Obstruction Dist (in) N/A N/A B 2 PARA Approach Obstruction Dist (in) N/A Is Button 1 APS or Non-APS? NonAPS Is Button 2 APS or Non-APS? No B 1 Clear Floor Space Slope (%) N/A 3.0 N/A B 2 Clear Floor Space Slope (%) N/A N/A N/A B 2 VibroTact Arrow? N/A No B 1 Clear Floor Space XSlope (%) 5.6 N/A B 2 Clear Floor Space XSlope (%) N/A N/A B 1 VibroTact Arrow? N/A N/A B 2 PAR Slope (%) N/A B 1 VibroTact Parallel to Xing? N/A B 2 VibroTact Parallel to Xing? N/A N/A B 1 PAR Slope (%) N/A N/A B 2 VibroTact Contrast N/A 40.0 N/A B 2 Height (in) N/A N/A B 1 VibroTact Contrast N/A Yes B 1 Height (in) N/A B 1 Pilot Light? N/A N/A B 2 Pilot Light? N/A Yes B 1 Pressure (#) 2.0 N/A B 2 Pressure (#) N/A Yes N/A B 2 Closed Fist Operation? N/A B 2 Pilot Light Illumination? N/A Yes B 1 Closed Fist Operation? N/A **N/A** B 1 Pilot Light Illumination? N/A B 1 Verbal Walk Cycle? N/A B 2 Verbal Walk Cycle? N/A **MUTCD Compliance** Yes N/A B 2 Clear Xing Direction? N/A B 1 Verbal Message Audible? N/A B 2 Verbal Message Audible? N/A N/A B 1 Clear Xing Direction? N/A N/A N/A B 1 Locator Tone? N/A N/A B 2 Locator Tone? N/A **B 1 Crossing Direction** To NE **B 2 Crossing Direction** N/A N/A B 1 Percussive Walk Cycle? N/A B 2 Percussive Walk Cycle? N/A Yes B 1 DistanceTo XWalk (in) 35.0 N/A B 2 DistanceTo XWalk (in)

N/A

N/A