

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Intersection ID: N/A	section ID: N/A Main Street: Cr				ross Street: N/A			Location: N/A		
ADA ID: 9BEE5ACD992F	Signal Type:O	ne Push Button-Non APS	Overall Co	mpliance: No	Severity Score: B	TN 1:N//	A BTN 2: N/A	No BTN:	N/A	
Code	Field Measurements/Component Compliance									
Possible Solutions: Replace Signa				Compliance Descrip	otion Da	ata Com	pliance Descript	on	Data	
		Button With APS Button on New Post		Button Count	Butt	ton1 N/A	Distant to Addition	al Button (in)	N/A	
2 1 3 1 5 1 c.	R.RD	Remove & Replace Sign.		Additional Button Present?		No	Additional Button I	D	N/A	
	FINANC			N/A Signal Buttons Required?		N/A N/A	Additional Ped Pos	sts Required	N/A	
1 COMP	the last			How Many Ped Street Xings?		1	Located In An Isla	nd/Median?	No	
	A STATE OF STATE	Surveyor Notes: TEXT HT 7/16		N/A B 1 Sign Present?		Yes N/A	B 2 Sign Present?		N/A	
	25 M			Yes B 1 Sign Purpose?		Yes N/A	B 2 Sign Purpose?	,	N/A	
ETTER A	meter sm			No B 1 Sign Lettering & Contrast?		No N/A	B 2 Sign Lettering	& Contrast?	N/A	
	CONCE 1			Yes B 1 Parallel To XWalk?		Yes N/A	B 2 Parallel To XW	/alk?	N/A	
	2 Dan Brin	PROW/ADA: R410.6, TMUTCD 4e.08, R404.2, R404.3, R406.2, R404.7.3		Yes B 1 PAR to Button?		Yes N/A	B 2 PAR to Button	?	N/A	
The second second	a Salar in			Yes B 1 PAR to XWalk?		Yes N/A	B 2 PAR to XWalk	?	N/A	
	12 Mar. 4			Yes B 1 Clear Floor Space?		Yes N/A	B 2 Clear Floor Sp	ace?	N/A	
South And				N/A B 1 FWD Approach?		Yes N/A	B 2 FWD Approac	n?	N/A	
	A THE REAL PROPERTY AND	Total Cost: \$	700.00	N/A B 1 FWD Approac	h Constrained?	No N/A	B 2 FWD Approac	n Constrained?	N/A	
				No B1 FWD Approac	h Reach (in)	10.5 N/A	B 2 FWD Approac	n Reach (in)	N/A	
				N/A B 1 FWD Approac	h Width (in)	N/A N/A	B 2 FWD Approac	n Width (in)	N/A	
				N/A B 1 FWD Approac	h Obstruction?	Yes N/A	B 2 FWD Approac	n Obstruction?	N/A	
				N/A B1 FWD Approach Obstruction Dist (ir		4.0 N/A	I/A B 2 FWD Approach ObstructionDist (st (in) N/A	
				N/A B 1 PARA Approach?		Yes N/A	s N/A B 2 PARA Approach?		N/A	
				N/A B 1 PARA Approach Constrained?		No N/A B 2 PARA Approach Constrained?		N/A		
				No B 1 PARA Approach Reach (in)		10.5 N/A B 2 PARA Approach Reach (in)		N/A		
				N/A B 1 PARA Approach Width (in)		N/A N/A	B 2 PARA Approac	h Width (in)	N/A	
				N/A B 1 PARA Approach Obstruction?		Yes N/A	B 2 PARA Approac	h Obstruction?	N/A	
	APS Complian	ce		N/A B 1 PARA Approa	ch Obstruction Dist (in)	4.0 N/A	B 2 PARA Approac	h ObstructionDi	st (in) N/A	
Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	N/A	No B 1 Clear Floor Sp	pace Slope (%)	8.2 N/A	B 2 Clear Floor Sp	ace Slope (%)	N/A	
N/A B 1 VibroTact Arrow?	N/A N/A	B 2 VibroTact Arrow?	N/A	Yes B 1 Clear Floor Sp	pace XSlope (%)	0.1 N/A	B 2 Clear Floor Sp	ace XSlope (%)	N/A	
N/A B1 VibroTact Parallel to Xing?	N/A N/A	B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%	b)	1.3 N/A	B 2 PAR Slope (%)	N/A	
N/A B 1 VibroTact Contrast	N/A N/A	B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)		37.0 N/A	B 2 Height (in)		N/A	
N/A B 1 Pilot Light?	N/A N/A	B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)		2.0 N/A	B 2 Pressure (#)		N/A	
N/A B 1 Pilot Light Illumination?	N/A N/A	B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist O	peration?	Yes N/A	B 2 Closed Fist Op	peration?	N/A	
N/A B 1 Verbal Walk Cycle?	N/A N/A	N/A B 2 Verbal Walk Cycle? N/A		МИТС		TCD Compliance				
N/A B 1 Verbal Message Audible?	N/A N/A	B 2 Verbal Message Audible?	N/A	Yes B1 Clear Xing Dir	ection? ClearlyMan	rked N/A	B 2 Clear Xing Dir	ection?	N/A	
N/A B 1 Locator Tone?	N/A N/A	B 2 Locator Tone?	N/A	B 1 Crossing Dire	ction	To N	B 2 Crossing Direc	tion	N/A	
N/A B 1 Percussive Walk Cycle?	N/A N/A	B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo X	Walk (in)	0.0 N/A	B 2 DistanceTo XV	Valk (in)	N/A	
N/A B 1 Extended Press Feature?	N/A N/A	B 2 Extended Press Feature?	N/A	No B 1 DistanceTo Cu	urb (in) 1	10.0 N/A	B 2 DistanceTo Cu	ırb (in)	N/A	
N/A B 1 Tone Audible Range?	N/A N/A	B 2 Tone Audible Range?	N/A	Yes B 1 Diameter (in)		2.0 N/A	B 2 Diameter (in)		N/A	