

## **Access Compliance Report Public Rights-of-Way** (Pedestrian Signals)



Data

N/A

N/A

N/A

No

N/A

N/A

N/A

N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A

N/A

N/A

N/A

**No N/A** B 2 PARA Approach Constrained?

21.0 N/A B 2 PARA Approach Reach (in)

123.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Signal Type: One Push Button-Non APS Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A ADA ID: 9CFE5C347BFA **Overall Compliance: No** 

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



N/A B 1 Extended Press Feature?

N/A B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Replace Sign.

Surveyor Notes: N/A

PROW/ADA: R410.6. TMUTCD 4e.08. R404.2. R404.3, R406.2, R404.7.3

Total Cost:

N/A N/A B 2 Extended Press Feature?

N/A N/A B 2 Tone Audible Range?



Compliance Description Data Compliance Description **Button Count Button1 N/A** Distant to Additional Button (in) Additional Button Present? Additional Button ID N/A Signal Buttons Required? N/A N/A Additional Ped Posts Required Located In An Island/Median? How Many Ped Street Xings? N/A B 1 Sign Present? Yes N/A B 2 Sign Present? Yes N/A B 2 Sign Purpose? Yes B 1 Sign Purpose? No B 1 Sign Lettering & Contrast? No N/A B 2 Sign Lettering & Contrast? Yes B 1 Parallel To XWalk? Yes N/A B 2 Parallel To XWalk? Yes B 1 PAR to Button? Yes N/A B 2 PAR to Button? Yes B 1 PAR to XWalk? Yes N/A B 2 PAR to XWalk? Yes B 1 Clear Floor Space? Yes N/A B 2 Clear Floor Space? N/A B 1 FWD Approach? Yes N/A B 2 FWD Approach? 700.00 N/A B 1 FWD Approach Constrained? **No N/A** B 2 FWD Approach Constrained? No B 1 FWD Approach Reach (in) 24.0 N/A B 2 FWD Approach Reach (in) N/A B 1 FWD Approach Width (in) N/A N/A B 2 FWD Approach Width (in) N/A B 1 FWD Approach Obstruction? Yes N/A B 2 FWD Approach Obstruction? N/A B 1 FWD Approach Obstruction Dist (in) **24.0** N/A B 2 FWD Approach ObstructionDist (in) N/A B 1 PARA Approach? Yes N/A B 2 PARA Approach?

**N/A** B 1 PARA Approach Constrained?

B 1 PARA Approach Reach (in)

No B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)



|                                     |         |                                   |     | N/A B 1 PARA Approach Width (in)    | N/A            | N/A | B 2 PARA Approach Width (in)           | N/A          |
|-------------------------------------|---------|-----------------------------------|-----|-------------------------------------|----------------|-----|--|--------------|
|                                     |         |                                   |     | N/A B 1 PARA Approach Obstruction?  | ? Yes          | N/A | B 2 PARA Approach Obstruction?         | N/A          |
| APS Compliance                      |         |                                   |     | N/A B 1 PARA Approach Obstruction   | Dist (in) 21.0 | N/A | B 2 PARA Approach ObstructionDist (in) | ) <b>N/A</b> |
| Is Button 1 APS or Non-APS?         | NonAPS  | Is Button 2 APS or Non-APS?       | N/A | No B 1 Clear Floor Space Slope (%)  | ) 7.5          | N/A | B 2 Clear Floor Space Slope (%)        | N/A          |
| N/A B 1 VibroTact Arrow?            | N/A N// | A B 2 VibroTact Arrow?            | N/A | Yes B 1 Clear Floor Space XSlope (% | %) <b>1.6</b>  | N/A | B 2 Clear Floor Space XSlope (%)       | N/A          |
| N/A B 1 VibroTact Parallel to Xing? | N/A N// | A B 2 VibroTact Parallel to Xing? | N/A | N/A B 1 PAR Slope (%)               | 6.0            | N/A | B 2 PAR Slope (%)                      | N/A          |
| N/A B 1 VibroTact Contrast          | N/A N// | A B 2 VibroTact Contrast          | N/A | Yes B 1 Height (in)                 | 40.0           | N/A | B 2 Height (in)                        | N/A          |
| N/A B 1 Pilot Light?                | N/A N// | A B 2 Pilot Light?                | N/A | Yes B 1 Pressure (#)                | 2.0            | N/A | B 2 Pressure (#)                       | N/A          |
| N/A B 1 Pilot Light Illumination?   | N/A N// | A B 2 Pilot Light Illumination?   | N/A | Yes B 1 Closed Fist Operation?      | Yes            | N/A | B 2 Closed Fist Operation?             | N/A          |
| N/A B 1 Verbal Walk Cycle?          | N/A N// | A B 2 Verbal Walk Cycle?          | N/A | MUTCD Compliance                    |                |     |  |              |
| N/A B 1 Verbal Message Audible?     | N/A N// | A B 2 Verbal Message Audible?     | N/A | Yes B 1 Clear Xing Direction?       | ClearlyMarked  | N/A | B 2 Clear Xing Direction?              | N/A          |
| N/A B 1 Locator Tone?               | N/A N// | A B 2 Locator Tone?               | N/A | B 1 Crossing Direction              | То Е           |     | B 2 Crossing Direction                 | N/A          |
| N/A B 1 Percussive Walk Cycle?      | N/A N// | A B 2 Percussive Walk Cycle?      | N/A | Yes B 1 DistanceTo XWalk (in)       | 0.0            | N/A | B 2 DistanceTo XWalk (in)              | N/A          |

N/A

N/A