# Access Compliance Report
# Public Rights-of-Way
# (Pedestrian Signals)

**cole**     **CHARLOTTE**

| Intersection ID: N/A | Main Street: | Cross Street: N/A | Location: N/A |
|---|---|---|---|

**ADA ID:** A0F1131E58DF    **Signal Type:** One Push Button-Non APS    **Overall Compliance:** No    **Severity Score: BTN 1:** N/A    **BTN 2:** N/A    **No BTN:** N/A

## Codes/Mitigation Info/Possible Solution     Field Measurements/Component Compliance



**Possible Solutions:** Provide Push Button Extension. Remove and Replace Clear Space.

**Surveyor Notes:** N/A

**PROW/ADA:** R404.2, R404.3, R404.7.3

Total Cost:    **$ 900.00**





| Compliance | Description | Data | Compliance | Description | Data |
|---|---|---|---|---|---|
| | Button Count | Button1 | Yes | Distant to Additional Button (in) | 200.0 |
| | Additional Button Present? | Yes | | Additional Button ID | 623566AE025F |
| N/A | Signal Buttons Required? | N/A | N/A | Additional Ped Posts Required | N/A |
| | How Many Ped Street Xings? | 3 | | Located In An Island/Median? | Yes |
| N/A | B 1 Sign Present? | Yes | N/A | B 2 Sign Present? | N/A |
| Yes | B 1 Sign Purpose? | Yes | N/A | B 2 Sign Purpose? | N/A |
| Yes | B 1 Sign Lettering & Contrast? | Yes | N/A | B 2 Sign Lettering & Contrast? | N/A |
| Yes | B 1 Parallel To XWalk? | Yes | N/A | B 2 Parallel To XWalk? | N/A |
| Yes | B 1 PAR to Button? | Yes | N/A | B 2 PAR to Button? | N/A |
| Yes | B 1 PAR to XWalk? | Yes | N/A | B 2 PAR to XWalk? | N/A |
| Yes | B 1 Clear Floor Space? | Yes | N/A | B 2 Clear Floor Space? | N/A |
| N/A | B 1 FWD Approach? | No | N/A | B 2 FWD Approach? | N/A |
| N/A | B 1 FWD Approach Constrained? | No | N/A | B 2 FWD Approach Constrained? | N/A |
| N/A | B 1 FWD Approach Reach (in) | N/A | N/A | B 2 FWD Approach Reach (in) | N/A |
| N/A | B 1 FWD Approach Width (in) | N/A | N/A | B 2 FWD Approach Width (in) | N/A |
| N/A | B 1 FWD Approach Obstruction? | No | N/A | B 2 FWD Approach Obstruction? | N/A |
| N/A | B 1 FWD Approach Obstruction Dist (in) | N/A | N/A | B 2 FWD Approach ObstructionDist (in) | N/A |
| N/A | B 1 PARA Approach? | Yes | N/A | B 2 PARA Approach? | N/A |
| N/A | B 1 PARA Approach Constrained? | No | N/A | B 2 PARA Approach Constrained? | N/A |
| No | B 1 PARA Approach Reach (in) | 14.0 | N/A | B 2 PARA Approach Reach (in) | N/A |
| N/A | B 1 PARA Approach Width (in) | 60.0 | N/A | B 2 PARA Approach Width (in) | N/A |
| N/A | B 1 PARA Approach Obstruction? | No | N/A | B 2 PARA Approach Obstruction? | N/A |
| N/A | B 1 PARA Approach Obstruction Dist (in) | N/A | N/A | B 2 PARA Approach ObstructionDist (in) | N/A |
| No | B 1 Clear Floor Space Slope (%) | 2.9 | N/A | B 2 Clear Floor Space Slope (%) | N/A |
| Yes | B 1 Clear Floor Space XSlope (%) | 1.2 | N/A | B 2 Clear Floor Space XSlope (%) | N/A |
| N/A | B 1 PAR Slope (%) | 1.3 | N/A | B 2 PAR Slope (%) | N/A |
| Yes | B 1 Height (in) | 31.0 | N/A | B 2 Height (in) | N/A |
| Yes | B 1 Pressure (#) | 1.0 | N/A | B 2 Pressure (#) | N/A |
| Yes | B 1 Closed Fist Operation? | Yes | N/A | B 2 Closed Fist Operation? | N/A |

### APS Compliance

| | | | | | |
|---|---|---|---|---|---|
| Is Button 1 APS or Non-APS? | NonAPS | | Is Button 2 APS or Non-APS? | | N/A |
| N/A | B 1 VibroTact Arrow? | No | N/A | B 2 VibroTact Arrow? | N/A |
| N/A | B 1 VibroTact Parallel to Xing? | No | N/A | B 2 VibroTact Parallel to Xing? | N/A |
| N/A | B 1 VibroTact Contrast | No | N/A | B 2 VibroTact Contrast | N/A |
| N/A | B 1 Pilot Light? | No | N/A | B 2 Pilot Light? | N/A |
| N/A | B 1 Pilot Light Illumination? | No | N/A | B 2 Pilot Light Illumination? | N/A |
| N/A | B 1 Verbal Walk Cycle? | No | N/A | B 2 Verbal Walk Cycle? | N/A |
| N/A | B 1 Verbal Message Audible? | No | N/A | B 2 Verbal Message Audible? | N/A |
| N/A | B 1 Locator Tone? | No | N/A | B 2 Locator Tone? | N/A |
| N/A | B 1 Percussive Walk Cycle? | No | N/A | B 2 Percussive Walk Cycle? | N/A |
| N/A | B 1 Extended Press Feature? | No | N/A | B 2 Extended Press Feature? | N/A |
| N/A | B 1 Tone Audible Range? | No | N/A | B 2 Tone Audible Range? | N/A |

### MUTCD Compliance

| Compliance | Description | Data | Compliance | Description | Data |
|---|---|---|---|---|---|
| Yes | B 1 Clear Xing Direction? | ClearlyMarked | N/A | B 2 Clear Xing Direction? | N/A |
| | B 1 Crossing Direction | To N | | B 2 Crossing Direction | |
| Yes | B 1 DistanceTo XWalk (in) | 0.0 | N/A | B 2 DistanceTo XWalk (in) | N/A |
| Yes | B 1 DistanceTo Curb (in) | 32.0 | N/A | B 2 DistanceTo Curb (in) | N/A |
| Yes | B 1 Diameter (in) | 2.0 | N/A | B 2 Diameter (in) | N/A |