

## Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: N/A Main Street: Cross Street: N/A Location: N/A

ADA ID: A36D3EEA0F64 Signal Type: One Push Button-Non APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

**Button Count** 

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

**Compliance Description** 

**Button1 N/A** Distant to Additional Button (in)



N/A B 1 Extended Press Feature?N/A B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Replace Sign.

Surveyor Notes: TEXT HT 1/2

PROW/ADA: R410.6, TMUTCD 4e.08, R404.2, R406.2, R404.7.3

Total Cost:

N/A N/A B 2 Extended Press Feature?

N/A N/A B 2 Tone Audible Range?

700.00

N/A N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Yes B 1 Pressure (#)

Yes B 1 Closed Fist Operation?

Yes B 1 Clear Xing Direction?

**B 1 Crossing Direction** 

Yes B 1 DistanceTo XWalk (in)

No B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)





		Additional Button Present?	No		Additional Button ID	N/A
	N/A	Signal Buttons Required?	N/A	N/A	Additional Ped Posts Required	N/A
		How Many Ped Street Xings?	1		Located In An Island/Median?	No
	N/A	B 1 Sign Present?	Yes	N/A	B 2 Sign Present?	N/A
	Yes	B 1 Sign Purpose?	Yes	N/A	B 2 Sign Purpose?	N/A
	No	B 1 Sign Lettering & Contrast?	No	N/A	B 2 Sign Lettering & Contrast?	N/A
	Yes	B 1 Parallel To XWalk?	Yes	N/A	B 2 Parallel To XWalk?	N/A
	Yes	B 1 PAR to Button?	Yes	N/A	B 2 PAR to Button?	N/A
	Yes	B 1 PAR to XWalk?	Yes	N/A	B 2 PAR to XWalk?	N/A
	Yes	B 1 Clear Floor Space?	Yes	N/A	B 2 Clear Floor Space?	N/A
	N/A	B 1 FWD Approach?	Yes	N/A	B 2 FWD Approach?	N/A
)	N/A	B 1 FWD Approach Constrained?	No	N/A	B 2 FWD Approach Constrained?	N/A
	No	B 1 FWD Approach Reach (in)	21.0	N/A	B 2 FWD Approach Reach (in)	N/A
	N/A	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)	N/A
	N/A	B 1 FWD Approach Obstruction?	No	N/A	B 2 FWD Approach Obstruction?	N/A
	N/A	B 1 FWD Approach Obstruction Dist (in)	N/A	N/A	B 2 FWD Approach ObstructionDist (in)	N/A
	N/A	B 1 PARA Approach?	Yes	N/A	B 2 PARA Approach?	N/A
	N/A	B 1 PARA Approach Constrained?	No	N/A	B 2 PARA Approach Constrained?	N/A
	No	B 1 PARA Approach Reach (in)	11.0	N/A	B 2 PARA Approach Reach (in)	N/A
	N/A	B 1 PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)	N/A
	N/A	B 1 PARA Approach Obstruction?	No	N/A	B 2 PARA Approach Obstruction?	N/A
	N/A	B 1 PARA Approach Obstruction Dist (in)	N/A	N/A	B 2 PARA Approach ObstructionDist (in)	N/A
	Yes	B 1 Clear Floor Space Slope (%)	2.9	N/A	B 2 Clear Floor Space Slope (%)	N/A
	No	B 1 Clear Floor Space XSlope (%)	3.2	N/A	B 2 Clear Floor Space XSlope (%)	N/A
	N/A	B 1 PAR Slope (%)	4.5	N/A	B 2 PAR Slope (%)	N/A
	Yes	B 1 Height (in)	37.5	N/A	B 2 Height (in)	N/A
		5 4 5 (W)		1 <i></i> .	<b>5.05</b> (11)	

2.0 N/A B 2 Pressure (#)

ClearlyMarked N/A B 2 Clear Xing Direction?

**MUTCD Compliance** 

To S

Yes N/A B 2 Closed Fist Operation?

26.0 N/A B 2 DistanceTo XWalk (in)

91.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)

**B 2 Crossing Direction** 

	APS Compliance			
Is Button 1 APS or Non-APS?	NonAPS Is Button 2 APS or Non-APS?			
N/A B 1 VibroTact Arrow?	N/A N/A B 2 VibroTact Arrow?			
N/A B 1 VibroTact Parallel to Xing?	N/A N/A B 2 VibroTact Parallel to Xing?			
N/A B 1 VibroTact Contrast	N/A N/A B 2 VibroTact Contrast			
N/A B 1 Pilot Light?	N/A N/A B 2 Pilot Light?			
N/A B 1 Pilot Light Illumination?	N/A N/A B 2 Pilot Light Illumination?			
N/A B 1 Verbal Walk Cycle?	N/A N/A B 2 Verbal Walk Cycle?			
N/A B 1 Verbal Message Audible?	N/A N/A B 2 Verbal Message Audible?			
N/A B 1 Locator Tone?	N/A N/A B 2 Locator Tone?			
N/A B 1 Percussive Walk Cycle?	N/A N/A B 2 Percussive Walk Cycle?			