

## Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

No

N/A N/A

N/A N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: N/A Main Street: Cross Street: N/A Location: N/A

ADA ID: A5A323E67172 Signal Type: One Push Button-Non APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

No B 1 FWD Approach Reach (in)
N/A B 1 FWD Approach Width (in)

N/A B 1 FWD Approach Obstruction?

**N/A** B 1 PARA Approach Constrained?

N/A B 1 FWD Approach Obstruction Dist (in)

**Button Count** 

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 Parallel To XWalk?

Yes B 1 Clear Floor Space?

Yes B 1 PAR to Button?

Yes B 1 PAR to XWalk?

N/A B 1 FWD Approach?

N/A B 1 PARA Approach?

Yes B 1 DistanceTo XWalk (in)

Yes B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Compliance Description

**Button1 N/A** Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Yes N/A B 2 Parallel To XWalk?

N/A B 2 PAR to XWalk?

Yes N/A B 2 Clear Floor Space?
Yes N/A B 2 FWD Approach?

Yes N/A B 2 PAR to Button?

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes N/A B 2 Sign Lettering & Contrast?

**No N/A** B 2 FWD Approach Constrained?

9.0 N/A B 2 FWD Approach Reach (in)

Yes N/A B 2 FWD Approach Obstruction?

**No N/A** B 2 PARA Approach Constrained?

7.0 N/A B 2 FWD Approach ObstructionDist (in)

**60.0 N/A** B 2 FWD Approach Width (in)

Yes N/A B 2 PARA Approach?

0.0 N/A B 2 DistanceTo XWalk (in)

58.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)

Located In An Island/Median?

Data

No



N/A B 1 Percussive Walk Cycle?

N/A B 1 Extended Press Feature?N/A B 1 Tone Audible Range?

Possible Solutions: Provide Push Button Extension. Remove and Replace Clear Space.

Surveyor Notes: N/A

PROW/ADA: R404.2, R404.3, R406.2

Total Cost: \$ 900.00 N/A B 1 FWD Approach Constrained?





No N/A B 2 Percussive Walk Cycle?

No N/A B 2 Extended Press Feature?

No N/A B 2 Tone Audible Range?



N/A

N/A

N/A