

## Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

28B6EA3A780B

317.0

N/A

No

N/A

N/A

N/A

N/A

Intersection ID: N/A Main Street: Cross Street: N/A Location: N/A

ADA ID: A6D3E8CE62C1 Signal Type: One Push Button-Non APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

No B 1 Sign Lettering & Contrast?

**Button Count** 

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 Diameter (in)

## **Codes/Mitigation Info/Possible Solution**

## Field Measurements/Component Compliance

Compliance Description

**Button1** Yes Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

2.0 N/A B 2 Diameter (in)

Additional Button ID

N/A N/A Additional Ped Posts Required

No N/A B 2 Sign Lettering & Contrast?

Located In An Island/Median?

Data

Yes



Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Replace Sign.

Surveyor Notes: TEXT HT 1/2

PROW/ADA: R410.6, R209.1, TMUTCD 4e.08, R404.2, R404.7.3

Total Cost:

700.0





	No	B 1 Parallel To XWalk?	No	N/A	B 2 Parallel To XWalk?	N/A
	Yes	B 1 PAR to Button?	Yes	N/A	B 2 PAR to Button?	N/A
	Yes	B 1 PAR to XWalk?	Yes	N/A	B 2 PAR to XWalk?	N/A
	Yes	B 1 Clear Floor Space?	Yes	N/A	B 2 Clear Floor Space?	N/A
	N/A	B 1 FWD Approach?	No	N/A	B 2 FWD Approach?	N/A
00	N/A	B 1 FWD Approach Constrained?	N/A	N/A	B 2 FWD Approach Constrained?	N/A
	N/A	B 1 FWD Approach Reach (in)	N/A	N/A	B 2 FWD Approach Reach (in)	N/A
	N/A	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)	N/A
	N/A	B 1 FWD Approach Obstruction?	N/A	N/A	B 2 FWD Approach Obstruction?	N/A
	N/A	B 1 FWD Approach Obstruction Dist (in)	N/A	N/A	B 2 FWD Approach ObstructionDist (in)	N/A
	N/A	B 1 PARA Approach?	Yes	N/A	B 2 PARA Approach?	N/A
	N/A	B 1 PARA Approach Constrained?	No	N/A	B 2 PARA Approach Constrained?	N/A
25942	No	B 1 PARA Approach Reach (in)	16.0	N/A	B 2 PARA Approach Reach (in)	N/A
	N/A	B 1 PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)	N/A
	N/A	B 1 PARA Approach Obstruction?	Yes	N/A	B 2 PARA Approach Obstruction?	N/A
	N/A	B 1 PARA Approach Obstruction Dist (in)	6.0	N/A	B 2 PARA Approach ObstructionDist (in)	N/A
	Yes	B 1 Clear Floor Space Slope (%)	0.6	N/A	B 2 Clear Floor Space Slope (%)	N/A
	No	B 1 Clear Floor Space XSlope (%)	8.5	N/A	B 2 Clear Floor Space XSlope (%)	N/A
	N/A	B 1 PAR Slope (%)	2.8	N/A	B 2 PAR Slope (%)	N/A
	Yes	B 1 Height (in)	37.0	N/A	B 2 Height (in)	N/A
	Yes	B 1 Pressure (#)	5.0	N/A	B 2 Pressure (#)	N/A
	Yes	B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A
		ML	JTCD (	Comp	pliance	
	Yes	B 1 Clear Xing Direction? ClearlyM	arked	N/A	B 2 Clear Xing Direction?	N/A
		B 1 Crossing Direction	To SW		B 2 Crossing Direction	N/A
	Yes	B 1 DistanceTo XWalk (in)	0.0	N/A	B 2 DistanceTo XWalk (in)	N/A
	No	B 1 DistanceTo Curb (in)	144.0	N/A	B 2 DistanceTo Curb (in)	N/A

APS Compliance								
Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	N/A					
N/A B 1 VibroTact Arrow?	N/A	N/A B 2 VibroTact Arrow?	N/A					
N/A B 1 VibroTact Parallel to Xing?	N/A	N/A B 2 VibroTact Parallel to Xing?	N/A					
N/A B 1 VibroTact Contrast	N/A	N/A B 2 VibroTact Contrast	N/A					
N/A B 1 Pilot Light?	N/A	N/A B 2 Pilot Light?	N/A					
N/A B 1 Pilot Light Illumination?	N/A	N/A B 2 Pilot Light Illumination?	N/A					
N/A B 1 Verbal Walk Cycle?	N/A	N/A B 2 Verbal Walk Cycle?	N/A					
N/A B 1 Verbal Message Audible?	N/A	N/A B 2 Verbal Message Audible?	N/A					
N/A B 1 Locator Tone?	N/A	N/A B 2 Locator Tone?	N/A					
N/A B 1 Percussive Walk Cycle?	N/A	N/A B 2 Percussive Walk Cycle?	N/A					
N/A B 1 Extended Press Feature?	N/A	N/A B 2 Extended Press Feature?	N/A					
N/A B 1 Tone Audible Range?	N/A	N/A B 2 Tone Audible Range?	N/A					