

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

5ECF7FFDC032

124.0

N/A

No

N/A

N/A

N/A N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Severity Score: BTN 1:N/A BTN 2: N/A No BTN: Signal Type: One Push Button-APS ADA ID: A79A62817CC6 **Overall Compliance: No** N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

No B 1 FWD Approach Reach (in)

N/A B 1 FWD Approach Width (in)

N/A B 1 FWD Approach Obstruction?

Button Count

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 Parallel To XWalk?

Yes B 1 Clear Floor Space?

N/A B 1 FWD Approach?

Yes B 1 Diameter (in)

Yes B 1 PAR to Button?

Yes B 1 PAR to XWalk?

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 Yes Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Yes N/A B 2 PAR to Button?

Yes N/A B 2 PAR to XWalk?

Yes N/A B 2 FWD Approach?

2.0 N/A B 2 Diameter (in)

Yes N/A B 2 Parallel To XWalk?

Yes N/A B 2 Clear Floor Space?

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes N/A B 2 Sign Lettering & Contrast?

No N/A B 2 FWD Approach Constrained?

14.0 N/A B 2 FWD Approach Reach (in)

N/A N/A B 2 FWD Approach Width (in)

Yes N/A B 2 FWD Approach Obstruction?

Located In An Island/Median?

Data

Yes



Yes B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R404.2, R406.2, R404.7.3, R209.1, MUTCD 4e.10

Total Cost:

650.00 N/A B 1 FWD Approach Constrained?



Yes N/A B 2 Tone Audible Range?



			CALLE	N/A B 1 FWD Approach Obstruction D	ist (in) 14.0	N/A	B 2 FWD Approach ObstructionDist (in)	N/A
			N.	N/A B 1 PARA Approach?	Yes	N/A	B 2 PARA Approach?	N/A
		1000	7	N/A B 1 PARA Approach Constrained?	? No	N/A	B 2 PARA Approach Constrained?	N/A
		U	1	No B 1 PARA Approach Reach (in)	14.0	N/A	B 2 PARA Approach Reach (in)	N/A
-			1	N/A B 1 PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)	N/A
				N/A B 1 PARA Approach Obstruction?	Yes	N/A	B 2 PARA Approach Obstruction?	N/A
APS Compliance				N/A B 1 PARA Approach Obstruction [Dist (in) 14.0	N/A	B 2 PARA Approach ObstructionDist (in)	N/A
Is Button 1 APS or Non-APS?	APS Is Button 2 AF	S or Non-APS?	N/A	Yes B 1 Clear Floor Space Slope (%)	0.1	N/A	B 2 Clear Floor Space Slope (%)	N/A
Yes B 1 VibroTact Arrow?	Yes N/A B 2 VibroTact	Arrow?	N/A	No B 1 Clear Floor Space XSlope (%	2.7	N/A	B 2 Clear Floor Space XSlope (%)	N/A
Yes B 1 VibroTact Parallel to Xing?	Yes N/A B 2 VibroTact	Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	1.9	N/A	B 2 PAR Slope (%)	N/A
Yes B 1 VibroTact Contrast	Yes N/A B 2 VibroTact	Contrast	N/A	Yes B 1 Height (in)	37.0	N/A	B 2 Height (in)	N/A
Yes B 1 Pilot Light?	Yes N/A B 2 Pilot Light	!?	N/A	Yes B 1 Pressure (#)	3.0	N/A	B 2 Pressure (#)	N/A
Yes B 1 Pilot Light Illumination?	Yes N/A B 2 Pilot Light	Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A
No B 1 Verbal Walk Cycle?	Yes N/A B 2 Verbal Wa	alk Cycle?	N/A	MUTCD Compliance				
N/A B 1 Verbal Message Audible?	Yes N/A B 2 Verbal Me	essage Audible?	N/A	Yes B 1 Clear Xing Direction?	learlyMarked	N/A	B 2 Clear Xing Direction?	N/A
Yes B 1 Locator Tone?	Yes N/A B 2 Locator To	one?	N/A	B 1 Crossing Direction	To SE		B 2 Crossing Direction	N/A
Yes B 1 Percussive Walk Cycle?	Yes N/A B 2 Percussiv	e Walk Cycle?	N/A	Yes B 1 DistanceTo XWalk (in)	8.0	N/A	B 2 DistanceTo XWalk (in)	N/A
Yes B 1 Extended Press Feature?	Yes N/A B 2 Extended	Press Feature?	N/A	No B 1 DistanceTo Curb (in)	114.0	N/A	B 2 DistanceTo Curb (in)	N/A

N/A