

## Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

No

Yes

Yes

Yes

Yes

No

Yes

No

No

N/A

N/A

N/A

N/A

N/A

No

71.0

2.0

Intersection ID: N/A Main Street: Cross Street: N/A Location: N/A

ADA ID: AE0192A0C943 Signal Type: Two Push Buttons-Non APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

N/A B 1 FWD Approach Reach (in)

N/A B 1 FWD Approach Width (in)

N/A B 1 FWD Approach Obstruction?

N/A B 1 FWD Approach Obstruction Dist (in)

**Button Count** 

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 Parallel To XWalk?

Yes B 1 Clear Floor Space?

Yes B 1 PAR to Button?

No B 1 PAR to XWalk?

No B 1 FWD Approach?

No B 1 PARA Approach?

Yes B 1 DistanceTo Curb (in)

No B 1 Diameter (in)

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Compliance Description

**Button2 N/A** Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes Yes B 2 Sign Purpose?

Yes Yes B 2 Parallel To XWalk?

No B 2 PAR to XWalk?

Yes No B 2 Clear Floor Space?

No No B 2 FWD Approach?

No Yes B 2 PAR to Button?

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes Yes B 2 Sign Lettering & Contrast?

N/A N/A B 2 FWD Approach Constrained?

N/A N/A B 2 FWD Approach Reach (in)

N/A N/A B 2 FWD Approach Width (in)

N/A N/A B 2 FWD Approach Obstruction?

B 2 PARA Approach?

69.0 Yes B 2 DistanceTo Curb (in)

2.2 Yes B 2 Diameter (in)

N/A N/A B 2 FWD Approach ObstructionDist (in)

Located In An Island/Median?

Data



N/A B 1 Extended Press Feature?

N/A B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button. Provide PAR As Indicated. Provide Clear Space. Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

**N/A N/A** B 2 Extended Press Feature?

N/A N/A B 2 Tone Audible Range?

PROW/ADA: R404.3, R404.2, R404.7.1, R404.7.2, DMS-11132, TMUTCD 4e.08, R404.1

Total Cost: \$ 1900.00 N/A B 1 FWD Approach Constrained?







				N/A B 1 PARA Approach Constrained	d? <b>N/A</b>	N/A	B 2 PARA Approach Constrain	ned?	N/A
				N/A B 1 PARA Approach Reach (in)	N/A	N/A	B 2 PARA Approach Reach (in	1)	N/A
				N/A B 1 PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)	)	N/A
				N/A B 1 PARA Approach Obstruction	? <b>N/A</b>	N/A	B 2 PARA Approach Obstruction	on?	N/A
APS Compliance				N/A B 1 PARA Approach Obstruction	Dist (in) N/A	N/A	B 2 PARA Approach Obstruction	onDist (in)	N/A
Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	NonAPS	No B 1 Clear Floor Space Slope (%	) 5.7	N/A	B 2 Clear Floor Space Slope (	%)	N/A
N/A B 1 VibroTact Arrow?	N/A N/	A B 2 VibroTact Arrow?	N/A	No B 1 Clear Floor Space XSlope (9	%) 7.6	N/A	B 2 Clear Floor Space XSlope	(%)	N/A
N/A B 1 VibroTact Parallel to Xing?	N/A N/	A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	1.9	N/A	B 2 PAR Slope (%)		4.8
N/A B 1 VibroTact Contrast	N/A N/	A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	39.5	Yes	B 2 Height (in)	;	39.0
N/A B 1 Pilot Light?	N/A N/	A B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	2.0	Yes	B 2 Pressure (#)		2.0
N/A B 1 Pilot Light Illumination?	N/A N/	A B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes	Yes	B 2 Closed Fist Operation?		Yes
N/A B 1 Verbal Walk Cycle?	N/A N/	A B 2 Verbal Walk Cycle?	N/A	MUTCD Compliance					
N/A B 1 Verbal Message Audible?	N/A N/	A B 2 Verbal Message Audible?	N/A	Yes B 1 Clear Xing Direction?	ClearlyMarked	Yes	B 2 Clear Xing Direction?	ClearlyMar	ked
N/A B 1 Locator Tone?	N/A N/	A B 2 Locator Tone?	N/A	B 1 Crossing Direction	To SW		B 2 Crossing Direction	То	SE
N/A B 1 Percussive Walk Cycle?	N/A N/	A B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo XWalk (in)	21.0	No	B 2 DistanceTo XWalk (in)	1	14.0

N/A

N/A