

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

No

N/A

N/A

N/A

N/A

N/A

Intersection ID: N/A Main Street: Cross Street: N/A Location: N/A

ADA ID: B088A301D0CC Signal Type: One Push Button-APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

Button Count

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 Parallel To XWalk?

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 N/A Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Yes N/A B 2 Parallel To XWalk?

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes N/A B 2 Sign Lettering & Contrast?

Located In An Island/Median?

Data

No



Possible Solutions: Remove & Replace Replace APS Button With New APS Button. Remove and Replace Clear Space.

Surveyor Notes: N/A

PROW/ADA: R404.2, R404.3, R406.2, R404.7.3, R209.1, MUTCD 4e.10

Is Button 2 APS or Non-APS?

Total Cost:

Yes N/A B 2 VibroTact Arrow?

Yes N/A B 2 VibroTact Contrast

Yes N/A B 2 Pilot Light Illumination?

Yes N/A B 2 Verbal Message Audible?

Yes N/A B 2 Percussive Walk Cycle?

Yes N/A B 2 Tone Audible Range?

Yes N/A B 2 Extended Press Feature?

Yes N/A B 2 Verbal Walk Cycle?

Yes N/A B 2 Locator Tone?

Yes N/A B 2 Pilot Light?

Yes N/A B 2 VibroTact Parallel to Xing?

\$ 1150.00

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A

N/A

N/A

N/A

Yes B 1 Diameter (in)



APS Compliance



	Yes	B 1 PAR to Button?	Yes	N/A	B 2 PAR to Button?	N/A		
	Yes	B 1 PAR to XWalk?	Yes	N/A	B 2 PAR to XWalk?	N/A		
	Yes	B 1 Clear Floor Space?	Yes	N/A	B 2 Clear Floor Space?	N/A		
	N/A	B 1 FWD Approach?	Yes	N/A	B 2 FWD Approach?	N/A		
)	N/A	B 1 FWD Approach Constrained?	No	N/A	B 2 FWD Approach Constrained?	N/A		
	No	B 1 FWD Approach Reach (in)	11.0	N/A	B 2 FWD Approach Reach (in)	N/A		
	N/A	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)	N/A		
	N/A	B 1 FWD Approach Obstruction?	Yes	N/A	B 2 FWD Approach Obstruction?	N/A		
	N/A	B 1 FWD Approach Obstruction Dist (in)	9.0	N/A	B 2 FWD Approach ObstructionDist (in)	N/A		
	N/A	B 1 PARA Approach?	Yes	N/A	B 2 PARA Approach?	N/A		
	N/A	B 1 PARA Approach Constrained?	No	N/A	B 2 PARA Approach Constrained?	N/A		
	No	B 1 PARA Approach Reach (in)	12.0	N/A	B 2 PARA Approach Reach (in)	N/A		
	N/A	B 1 PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)	N/A		
	N/A	B 1 PARA Approach Obstruction?	Yes	N/A	B 2 PARA Approach Obstruction?	N/A		
	N/A	B 1 PARA Approach Obstruction Dist (in)	8.0	N/A	B 2 PARA Approach ObstructionDist (in)	N/A		
	No	B 1 Clear Floor Space Slope (%)	8.7	N/A	B 2 Clear Floor Space Slope (%)	N/A		
	No	B 1 Clear Floor Space XSlope (%)	2.5	N/A	B 2 Clear Floor Space XSlope (%)	N/A		
	N/A	B 1 PAR Slope (%)	1.4	N/A	B 2 PAR Slope (%)	N/A		
	Yes	B 1 Height (in)	40.0	N/A	B 2 Height (in)	N/A		
	Yes	B 1 Pressure (#)	3.0	N/A	B 2 Pressure (#)	N/A		
	Yes	B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A		
	MUTCD Compliance							
	Yes	B 1 Clear Xing Direction? ClearlyMa	arked	N/A	B 2 Clear Xing Direction?	N/A		
		B 1 Crossing Direction To	o SW		B 2 Crossing Direction	N/A		
	Yes	B 1 DistanceTo XWalk (in)	0.0	N/A	B 2 DistanceTo XWalk (in)	N/A		
	Yes	B 1 DistanceTo Curb (in)	38.0	N/A	B 2 DistanceTo Curb (in)	N/A		

2.0 N/A B 2 Diameter (in)

	Is Button 1 APS or Non-APS?
Yes	B 1 VibroTact Arrow?
Yes	B 1 VibroTact Parallel to Xing?
Yes	B 1 VibroTact Contrast
Yes	B 1 Pilot Light?
Yes	B 1 Pilot Light Illumination?
No	B 1 Verbal Walk Cycle?
N/A	B 1 Verbal Message Audible?
Yes	B 1 Locator Tone?
Yes	B 1 Percussive Walk Cycle?
Yes	B 1 Extended Press Feature?
Yes	B 1 Tone Audible Range?