

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A N/A

N/A N/A

N/A N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Main Street: Location: N/A Intersection ID: N/A Cross Street: N/A

ADA ID: B8559DB9BD34 Signal Type: One Push Button-Non APS **Overall Compliance: No** Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 N/A Distant to Additional Button (in)

2.0 N/A B 2 Diameter (in)

Additional Button ID

N/A N/A Additional Ped Posts Required

Data

No



N/A B 1 Extended Press Feature?

N/A B 1 Tone Audible Range?

Compliance Description Possible Solutions: Remove & Replace Sign. Remove and Replace Clear Space. N/A Signal Buttons Required? Surveyor Notes: N/A



How Many Ped Street Xings? N/A Located In An Island/Median? N/A B 1 Sign Present? Yes N/A B 2 Sign Present? Yes B 1 Sign Purpose? Yes N/A B 2 Sign Purpose? No B 1 Sign Lettering & Contrast? N/A B 2 Sign Lettering & Contrast? Yes B 1 Parallel To XWalk? Yes N/A B 2 Parallel To XWalk? PROW/ADA: R410.6, R404.2, R404.3, R404.7.2 Yes B 1 PAR to Button? Yes N/A B 2 PAR to Button? Yes B 1 PAR to XWalk? N/A B 2 PAR to XWalk? Yes B 1 Clear Floor Space? Yes N/A B 2 Clear Floor Space? No N/A B 2 FWD Approach? N/A B 1 FWD Approach? 650.00 N/A B 1 FWD Approach Constrained? Total Cost: N/A N/A B 2 FWD Approach Constrained? N/A B 1 FWD Approach Reach (in) N/A N/A B 2 FWD Approach Reach (in) N/A B 1 FWD Approach Width (in) N/A N/A B 2 FWD Approach Width (in) N/A B 1 FWD Approach Obstruction? Yes N/A B 2 FWD Approach Obstruction? N/A B 1 FWD Approach Obstruction Dist (in) 2.0 N/A B 2 FWD Approach ObstructionDist (in) N/A B 1 PARA Approach? Yes N/A B 2 PARA Approach? Yes N/A B 2 PARA Approach Constrained? **N/A** B 1 PARA Approach Constrained? Yes B 1 PARA Approach Reach (in) 8.0 N/A B 2 PARA Approach Reach (in)

Yes B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)

Button Count

Additional Button Present?

	;
	11 11 11 11
4	

N/A N/A B 2 Tone Audible Range?

B 1 PARA Approach Width (in) N/A **48.0 N/A** B 2 PARA Approach Width (in) N/A B 1 PARA Approach Obstruction? Yes N/A B 2 PARA Approach Obstruction? N/A **APS Compliance** N/A B 1 PARA Approach Obstruction Dist (in) 2.0 N/A B 2 PARA Approach Obstruction Dist (in) N/A Is Button 1 APS or Non-APS? NonAPS Is Button 2 APS or Non-APS? No B 1 Clear Floor Space Slope (%) N/A 3.7 N/A B 2 Clear Floor Space Slope (%) N/A N/A B 1 VibroTact Arrow? N/A N/A B 2 VibroTact Arrow? N/A Yes B 1 Clear Floor Space XSlope (%) 1.3 N/A B 2 Clear Floor Space XSlope (%) N/A N/A B 1 VibroTact Parallel to Xing? N/A B 2 VibroTact Parallel to Xing? N/A N/A B 1 PAR Slope (%) N/A N/A B 2 PAR Slope (%) N/A N/A N/A N/A B 1 VibroTact Contrast N/A N/A B 2 VibroTact Contrast Yes B 1 Height (in) 48.0 N/A B 2 Height (in) N/A B 1 Pilot Light? N/A N/A B 2 Pilot Light? N/A Yes B 1 Pressure (#) 2.0 N/A B 2 Pressure (#) N/A N/A B 2 Pilot Light Illumination? Yes B 1 Closed Fist Operation? Yes N/A B 2 Closed Fist Operation? N/A **N/A** B 1 Pilot Light Illumination? N/A N/A B 1 Verbal Walk Cycle? N/A B 2 Verbal Walk Cycle? N/A **MUTCD Compliance** Yes N/A B 2 Clear Xing Direction? N/A B 1 Verbal Message Audible? N/A B 2 Verbal Message Audible? N/A N/A B 1 Clear Xing Direction? N/A N/A N/A B 1 Locator Tone? N/A N/A B 2 Locator Tone? N/A **B 1 Crossing Direction** To NW **B 2 Crossing Direction** N/A N/A B 1 Percussive Walk Cycle? N/A B 2 Percussive Walk Cycle? N/A Yes B 1 DistanceTo XWalk (in) 12.0 N/A B 2 DistanceTo XWalk (in) N/A B 2 Extended Press Feature? N/A 69.0 N/A B 2 DistanceTo Curb (in) N/A

N/A