

N/A B 1 Tone Audible Range?

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

17324BA4A8EC

253.0

N/A

No

N/A

N/A

N/A

N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Signal Type: One Push Button-Non APS Severity Score: BTN 1:N/A BTN 2: N/A No BTN: ADA ID: BCE121D8BFC7 **Overall Compliance: No** N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

No B 1 FWD Approach Reach (in)

N/A B 1 FWD Approach Width (in)

Button Count

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 Parallel To XWalk?

B 1 PAR to Button?

Yes B 1 Clear Floor Space?

No B 1 PAR to XWalk?

N/A B 1 FWD Approach?

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 Yes Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Yes N/A B 2 Parallel To XWalk?

No N/A B 2 PAR to Button?

No N/A B 2 PAR to XWalk?

Yes N/A B 2 FWD Approach?

2.0 N/A B 2 Diameter (in)

Yes N/A B 2 Clear Floor Space?

Additional Button ID

Yes N/A B 2 Sign Lettering & Contrast?

No N/A B 2 FWD Approach Constrained?

16.0 N/A B 2 FWD Approach Reach (in)

N/A N/A B 2 FWD Approach Width (in)

N/A Additional Ped Posts Required

Located In An Island/Median?

Data

Yes

N/A



Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R404.3, R406.2

Total Cost:



N/A



N/A N/A B 2 Tone Audible Range?



				MA DIT WD Approach Width (iii)	17/0 17/0	D Z I WD Approach Width (iii)	13/4
	WALK			N/A B 1 FWD Approach Obstruction?	Yes N/A	B 2 FWD Approach Obstruction?	N/A
	TO STEADY TURNING VEHICLES			N/A B 1 FWD Approach Obstruction Di	ist (in) 9.0 N/A	B 2 FWD Approach ObstructionDist (in)	N/A
TRUST TO THE PROPERTY OF THE P				N/A B 1 PARA Approach?	Yes N/A	B 2 PARA Approach?	N/A
				N/A B 1 PARA Approach Constrained?	No N/A	B 2 PARA Approach Constrained?	N/A
				Yes B 1 PARA Approach Reach (in)	5.0 N/A	B 2 PARA Approach Reach (in)	N/A
				N/A B 1 PARA Approach Width (in)	N/A N/A	B 2 PARA Approach Width (in)	N/A
				N/A B 1 PARA Approach Obstruction?	Yes N/A	B 2 PARA Approach Obstruction?	N/A
APS Compliance				N/A B 1 PARA Approach Obstruction D	Dist (in) 3.0 N/A	B 2 PARA Approach ObstructionDist (in)) N/A
Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	N/A	Yes B 1 Clear Floor Space Slope (%)	0.0 N/A	B 2 Clear Floor Space Slope (%)	N/A
N/A B 1 VibroTact Arrow?	N/A N/A	B 2 VibroTact Arrow?	N/A	Yes B 1 Clear Floor Space XSlope (%)) 1.9 N/A	B 2 Clear Floor Space XSlope (%)	N/A
N/A B 1 VibroTact Parallel to Xing?	N/A N/A	B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	0.8 N/A	B 2 PAR Slope (%)	N/A
N/A B 1 VibroTact Contrast	N/A N/A	B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	39.0 N/A	B 2 Height (in)	N/A
N/A B 1 Pilot Light?	N/A N/A	B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	3.0 N/A	B 2 Pressure (#)	N/A
N/A B 1 Pilot Light Illumination?	N/A N/A	B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes N/A	B 2 Closed Fist Operation?	N/A
N/A B 1 Verbal Walk Cycle?	N/A N/A	B 2 Verbal Walk Cycle?	N/A	MUTCD Compliance			
N/A B 1 Verbal Message Audible?	N/A N/A	B 2 Verbal Message Audible?	N/A	Yes B 1 Clear Xing Direction?	learlyMarked N/A	B 2 Clear Xing Direction?	N/A
N/A B 1 Locator Tone?	N/A N/A	B 2 Locator Tone?	N/A	B 1 Crossing Direction	To N	B 2 Crossing Direction	N/A
N/A B 1 Percussive Walk Cycle?	N/A N/A	B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo XWalk (in)	0.0 N/A	B 2 DistanceTo XWalk (in)	N/A
N/A B 1 Extended Press Feature?	N/A N/A	B 2 Extended Press Feature?	N/A	No B 1 DistanceTo Curb (in)	137.0 N/A	B 2 DistanceTo Curb (in)	N/A

Yes B 1 Diameter (in)