

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: N/A Main Street: Cross Street: N/A Location: N/A

ADA ID: BE63CAE1A704 Signal Type: One Push Button-Non APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



N/A B 1 Percussive Walk Cycle?

N/A B 1 Extended Press Feature?

N/A B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Replace Sign.

Surveyor Notes: TEXT HT 1.5

N/A B 2 Percussive Walk Cycle?

N/A N/A B 2 Extended Press Feature?

N/A N/A B 2 Tone Audible Range?

PROW/ADA: R410.6, TMUTCD 4e.08, R404.2, R406.2

Total Cost:

\$ 700.00



Compliance Description	Data	Com	pliance	Description	Data	<u>_</u>
Button Count	Button1	N/A	Distant t	o Additional Button (i	in) N	/ A
Additional Button Present	? No		Addition	al Button ID	N	/ A
N/A Signal Buttons Required?	N/A	N/A	Addition	al Ped Posts Require	ed N	/ A
How Many Ped Street Xin	gs? 2		Located	In An Island/Median	? !	No
N/A B 1 Sign Present?	Yes	N/A	B 2 Sign	Present?	N	/ A
Yes B 1 Sign Purpose?	Yes	N/A	B 2 Sign	Purpose?	N	/ A
No B 1 Sign Lettering & Contr	ast? No	N/A	B 2 Sign	Lettering & Contras	t? N	/ A
Yes B 1 Parallel To XWalk?	Yes	N/A	B 2 Para	allel To XWalk?	N	/ A
Yes B 1 PAR to Button?	Yes	N/A	B 2 PAR	to Button?	N	/ A
Yes B 1 PAR to XWalk?	Yes	N/A	B 2 PAR	to XWalk?	N	/ A
Yes B 1 Clear Floor Space?	Yes	N/A	B 2 Clea	ar Floor Space?	N	/ A
N/A B 1 FWD Approach?	Yes	N/A	B 2 FWI	O Approach?	N	/ A
N/A B 1 FWD Approach Const	rained? No	N/A	B 2 FWI	O Approach Constrair	ned? N	/ A
No B 1 FWD Approach Reach	n (in) 4.0	N/A	B 2 FWI	D Approach Reach (ir	n) N	/ A
N/A B 1 FWD Approach Width	(in) N/A	N/A	B 2 FWI	O Approach Width (in	ı) N	/ A

Yes N/A B 2 FWD Approach Obstruction?

No N/A B 2 PARA Approach Constrained?

4.0 N/A B 2 PARA Approach Reach (in)

0.0 N/A B 2 DistanceTo XWalk (in)

112.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)

Yes N/A B 2 PARA Approach?

2.0 N/A B 2 FWD Approach ObstructionDist (in)



N/A B 1 PARA Approach Width (in) N/A N/A B 2 PARA Approach Width (in) N/A N/A B 1 PARA Approach Obstruction? Yes N/A B 2 PARA Approach Obstruction? N/A APS Compliance N/A B 1 PARA Approach Obstruction Dist (in) 2.0 N/A B 2 PARA Approach Obstruction Dist (in) N/A Is Button 1 APS or Non-APS? NonAPS Is Button 2 APS or Non-APS? Yes B 1 Clear Floor Space Slope (%) N/A **0.4 N/A** B 2 Clear Floor Space Slope (%) N/A N/A N/A B 2 VibroTact Arrow? N/A No B 1 Clear Floor Space XSlope (%) 2.1 N/A B 2 Clear Floor Space XSlope (%) N/A N/A B 1 VibroTact Arrow? N/A B 1 VibroTact Parallel to Xing? N/A B 2 VibroTact Parallel to Xing? N/A N/A B 1 PAR Slope (%) **0.1 N/A** B 2 PAR Slope (%) N/A N/A 41.0 N/A B 2 Height (in) N/A N/A B 1 VibroTact Contrast N/A N/A B 2 VibroTact Contrast Yes B 1 Height (in) N/A B 1 Pilot Light? N/A N/A B 2 Pilot Light? N/A Yes B 1 Pressure (#) 2.0 N/A B 2 Pressure (#) N/A **N/A** B 2 Pilot Light Illumination? Yes B 1 Closed Fist Operation? Yes N/A B 2 Closed Fist Operation? N/A **N/A** B 1 Pilot Light Illumination? N/A N/A B 1 Verbal Walk Cycle? N/A B 2 Verbal Walk Cycle? N/A **MUTCD Compliance** ClearlyMarked N/A B 2 Clear Xing Direction? N/A B 1 Verbal Message Audible? N/A B 2 Verbal Message Audible? N/A Yes B 1 Clear Xing Direction? N/A To NW N/A B 1 Locator Tone? N/A N/A B 2 Locator Tone? N/A **B 1 Crossing Direction B 2 Crossing Direction** N/A

N/A

N/A

N/A

N/A B 1 FWD Approach Obstruction?N/A B 1 FWD Approach Obstruction Dist (in)

N/A B 1 PARA Approach Constrained?

Yes B 1 PARA Approach Reach (in)

Yes B 1 DistanceTo XWalk (in)

No B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)

N/A B 1 PARA Approach?