cole

Yes B 1 Tone Audible Range?

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



2.0 N/A B 2 Diameter (in)

N/A

Intersection ID: N/A	D: N/A Main Street: Cross Street: N/A						Location: N/A		
ADA ID: BECAEB9F22BE	Signal Type:O	ne Push Button-APS	Overall Co	mpliance: No	Severity Score: BTN	1:N//	A BTN 2: N/A	No BTN:	N/A
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance									
	Compliance Description Data Compliance Description					Data			
15	Hall Start	Possible Solutions: Replace Signal Button With APS Button on New Po Remove & Replace Sign.		Button Count			Distant to Additiona		N/A
				Additional Button Present?		, , , , , , , , , , , , , , , , , , , ,	Additional Button II	()	N/A
				N/A Signal Buttons Re			Additional Ped Posts Required		N/A
(HENDOW -	4			How Many Ped Street Xings?			Located In An Islan	•	No
AND AND AND	1	Surveyor Notes: TEXT HT 3/8 PROW/ADA: R410.6, TMUTCD 4e.08, R404.2 R404.3, R406.2, R209.1, MUTCD 4e.10		N/A B 1 Sign Present?		N/A	B 2 Sign Present?		N/A
Comment of the owner	-			Yes B 1 Sign Purpose?			B 2 Sign Purpose?		N/A
	and the second s			No B 1 Sign Lettering & Contrast?			B 2 Sign Lettering		N/A
	a man			Yes B 1 Parallel To XWalk?			B 2 Parallel To XW		N/A
A State of the second of the				Yes B 1 PAR to Button?			B 2 PAR to Button?		N/A
A state	Section 11			Yes B 1 PAR to XWalk?			B 2 PAR to XWalk?		N/A
	19 3 18			Yes B1 Clear Floor Space?			B 2 Clear Floor Spa		N/A
	EARLY AND			N/A B1 FWD Approach?			B 2 FWD Approach		N/A
		Total Cost:	5 700.00			N/A	B 2 FWD Approach	Constrained?	N/A
				No B1 FWD Approa			B 2 FWD Approach		N/A
			N/A B1 FWD Approa	ch Width (in) N/A	N/A	B 2 FWD Approach	Width (in)	N/A	
			N/A B1 FWD Approach Obstruction?			B 2 FWD Approach		N/A	
			N/A B 1 FWD Approach Obstruction Dist (in)		N/A	B 2 FWD Approach	ObstructionDis	t (in) N/A	
	215			N/A B 1 PARA Approach?		N/A	N/A B 2 PARA Approach?		N/A
				N/A B 1 PARA Approach Constrained?		N/A	B 2 PARA Approac	h Constrained?	N/A
			Yes B 1 PARA Approach Reach (in)		N/A	B 2 PARA Approac	h Reach (in)	N/A	
			N/A B 1 PARA Approach Width (in)		N/A	B 2 PARA Approac	h Width (in)	N/A	
				N/A B 1 PARA Approach Obstruction?		N/A	B 2 PARA Approac	h Obstruction?	N/A
APS Compliance				N/A B 1 PARA Approa	ach Obstruction Dist (in) 3.0	N/A	B 2 PARA Approac	h ObstructionDis	st (in) N/A
Is Button 1 APS or Non-APS?	APS	Is Button 2 APS or Non-APS?	N/A	No B 1 Clear Floor S	Space Slope (%) 7.8	N/A	B 2 Clear Floor Spa	ace Slope (%)	N/A
Yes B 1 VibroTact Arrow?	Yes N/A	B 2 VibroTact Arrow?	N/A	Yes B 1 Clear Floor S	Space XSlope (%) 1.5	N/A	B 2 Clear Floor Spa	ace XSlope (%)	N/A
Yes B 1 VibroTact Parallel to Xing?	Yes N/A	B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%	%) 7.6	N/A	B 2 PAR Slope (%)		N/A
Yes B 1 VibroTact Contrast	Yes N/A	B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	33.5	N/A	B 2 Height (in)		N/A
Yes B 1 Pilot Light?	Yes N/A	B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	2.0	N/A	B 2 Pressure (#)		N/A
Yes B 1 Pilot Light Illumination?	Yes N/A	B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist C	Operation? Yes	N/A	B 2 Closed Fist Op	eration?	N/A
No B 1 Verbal Walk Cycle?	Yes N/A	B 2 Verbal Walk Cycle?	al Walk Cycle? N/A				CD Compliance		
N/A B 1 Verbal Message Audible?	Yes N/A	B 2 Verbal Message Audible?	N/A	Yes B 1 Clear Xing Di	rection? ClearlyMarked	N/A	B 2 Clear Xing Dire	ection?	N/A
Yes B 1 Locator Tone?	Yes N/A	B 2 Locator Tone?	N/A	B 1 Crossing Dire	ection To N		B 2 Crossing Direc	tion	N/A
Yes B 1 Percussive Walk Cycle?	Yes N/A	B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo X	Walk (in) 0.0	N/A	B 2 DistanceTo XW	/alk (in)	N/A
Yes B1 Extended Press Feature?	Yes N/A	B 2 Extended Press Feature?	N/A	No B 1 DistanceTo C	urb (in) 95.0	N/A	B 2 DistanceTo Cu	rb (in)	N/A

N/A

Yes B 1 Diameter (in)

Yes N/A B 2 Tone Audible Range?