

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

821750F24301

225.0

N/A

No

N/A N/A

N/A

N/A

N/A N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A N/A

N/A

N/A

N/A

Main Street: Cross Street: N/A Location: N/A Intersection ID: N/A

Signal Type: One Push Button-Non APS **Overall Compliance: No** Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A ADA ID: C1E77AF51C2A

Compliance Description

Additional Button Present?

N/A B 1 PARA Approach Width (in)

Yes B 1 Diameter (in)

Button Count

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 N/A Distant to Additional Button (in)

Additional Button ID

N/A N/A B 2 PARA Approach Width (in)

2.0 N/A B 2 Diameter (in)

Data

No



N/A B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08

Total Cost:

N/A N/A B 2 Tone Audible Range?

650.



	N/A	Signal Buttons Required?		N/A	Additional Ped Posts Required			
		How Many Ped Street Xings?	1		Located In An Island/Median?			
	N/A	B 1 Sign Present?	Yes	N/A	B 2 Sign Present?			
	Yes	B 1 Sign Purpose?	Yes	N/A	B 2 Sign Purpose?			
	Yes	B 1 Sign Lettering & Contrast?	Yes	N/A	B 2 Sign Lettering & Contrast?			
	Yes	B 1 Parallel To XWalk?	Yes	N/A	B 2 Parallel To XWalk?			
	Yes	B 1 PAR to Button?	Yes	N/A	B 2 PAR to Button?			
	Yes	B 1 PAR to XWalk?	Yes	N/A	B 2 PAR to XWalk?			
	Yes	B 1 Clear Floor Space?	Yes	N/A	B 2 Clear Floor Space?			
	N/A	B 1 FWD Approach?	No	N/A	B 2 FWD Approach?			
.00	N/A	B 1 FWD Approach Constrained?	N/A	N/A	B 2 FWD Approach Constrained?			
	N/A	B 1 FWD Approach Reach (in)	N/A	N/A	B 2 FWD Approach Reach (in)			
-	N/A	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)			
TO SECOND	N/A	B 1 FWD Approach Obstruction?	N/A	N/A	B 2 FWD Approach Obstruction?			
	N/A	B 1 FWD Approach Obstruction Dist (in)	N/A	N/A	B 2 FWD Approach ObstructionDist (in)			
	N/A	B 1 PARA Approach?	Yes	N/A	B 2 PARA Approach?			
	N/A	B 1 PARA Approach Constrained?	No	N/A	B 2 PARA Approach Constrained?			
1	Yes	B 1 PARA Approach Reach (in)	7.0	N/A	B 2 PARA Approach Reach (in)			



				Test B 117 ii o 17 ipprodon Widin (iii)			B 2 17 ii ii i i i ippi odoli i i i idaii (iii)	,,
				N/A B 1 PARA Approach Obstruction?	Yes	N/A	B 2 PARA Approach Obstruction?	N/A
	N/A B 1 PARA Approach Obstruction Dist (in)		N/A	B 2 PARA Approach ObstructionDist (in) N/A			
Is Button 1 APS or Non-APS?	Is Button 1 APS or Non-APS? NonAPS Is Button 2 APS or No		N/A	Yes B 1 Clear Floor Space Slope (%)	1.7	N/A	B 2 Clear Floor Space Slope (%)	N/A
N/A B 1 VibroTact Arrow?	N/A N/A	A B 2 VibroTact Arrow?	N/A	Yes B 1 Clear Floor Space XSlope (%)		N/A	B 2 Clear Floor Space XSlope (%)	N/A
N/A B 1 VibroTact Parallel to Xing?	N/A N/A	A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)		N/A	B 2 PAR Slope (%)	N/A
N/A B 1 VibroTact Contrast	N/A N/A	A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)		N/A	B 2 Height (in)	N/A
N/A B 1 Pilot Light?	N/A N/A	A B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)		N/A	B 2 Pressure (#)	N/A
N/A B 1 Pilot Light Illumination?	N/A N/A	A B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?		N/A	B 2 Closed Fist Operation?	N/A
N/A B 1 Verbal Walk Cycle?		A B 2 Verbal Walk Cycle?	N/A		MUTCD	JTCD Compliance		
N/A B 1 Verbal Message Audible?	N/A N/A	A B 2 Verbal Message Audible?	N/A	Yes B 1 Clear Xing Direction?	learlyMarked	N/A	B 2 Clear Xing Direction?	N/A
N/A B 1 Locator Tone?	N/A N/A	A B 2 Locator Tone?	N/A	B 1 Crossing Direction	To SE		B 2 Crossing Direction	N/A
N/A B 1 Percussive Walk Cycle?	N/A N/A	A B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo XWalk (in)	0.0	N/A	B 2 DistanceTo XWalk (in)	N/A
N/A B 1 Extended Press Feature?	N/A N/A	A B 2 Extended Press Feature?	N/A	No B 1 DistanceTo Curb (in)	181.0	N/A	B 2 DistanceTo Curb (in)	N/A

N/A