

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Main Street: Cross Street: N/A Location: N/A Intersection ID: N/A

ADA ID: C28EA1B0F3A2 Signal Type: One Push Button-Non APS **Overall Compliance: No** Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

Button Count

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 Parallel To XWalk?

Yes B 1 Clear Floor Space?

Yes B 1 PAR to Button?

Yes B 1 PAR to XWalk?

N/A B 1 FWD Approach?

Yes B 1 Diameter (in)

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 N/A Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Yes N/A B 2 Parallel To XWalk?

Yes N/A B 2 Clear Floor Space?

Yes N/A B 2 FWD Approach?

2.0 N/A B 2 Diameter (in)

Yes N/A B 2 PAR to Button?

Yes N/A B 2 PAR to XWalk?

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes N/A B 2 Sign Lettering & Contrast?

Located In An Island/Median?

Data

No



Is Button 1 APS or Non-APS?

N/A B 1 VibroTact Parallel to Xing?

N/A B 1 Pilot Light Illumination? N/A B 1 Verbal Walk Cycle?

N/A B 1 Verbal Message Audible?

N/A B 1 Percussive Walk Cycle?

N/A B 1 Extended Press Feature? N/A B 1 Tone Audible Range?

N/A B 1 VibroTact Arrow?

N/A B 1 VibroTact Contrast

N/A B 1 Pilot Light?

N/A B 1 Locator Tone?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R404.2, R406.2



APS Compliance

N/A N/A B 2 Tone Audible Range?

NonAPS



N/A

177	\nearrow	Total Cost: \$	650.00	N/A	B 1 FWD Approach Constrained?	No	N/A	B 2 FWD Approach Constrained?	N/A
			fig. 7	No	B 1 FWD Approach Reach (in)	7.0	N/A	B 2 FWD Approach Reach (in)	N/A
				N/A	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)	N/A
				N/A	B 1 FWD Approach Obstruction?	No	N/A	B 2 FWD Approach Obstruction?	N/A
-	0.0			N/A	B 1 FWD Approach Obstruction Dist (in)	N/A	N/A	B 2 FWD Approach ObstructionDist (in)	N/A
			-/	N/A	B 1 PARA Approach?	Yes	N/A	B 2 PARA Approach?	N/A
				N/A	B 1 PARA Approach Constrained?	No	N/A	B 2 PARA Approach Constrained?	N/A
				Yes	B 1 PARA Approach Reach (in)	6.0	N/A	B 2 PARA Approach Reach (in)	N/A
				N/A	B 1 PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)	N/A
					B 1 PARA Approach Obstruction?	No	N/A	B 2 PARA Approach Obstruction?	N/A
S Compliance					B 1 PARA Approach Obstruction Dist (in)	N/A	N/A	B 2 PARA Approach ObstructionDist (in)	N/A
nAPS		Is Button 2 APS or Non-APS?	N/A	Yes	B 1 Clear Floor Space Slope (%)	3.0	N/A	B 2 Clear Floor Space Slope (%)	N/A
N/A	N/A	B 2 VibroTact Arrow?	N/A	No	B 1 Clear Floor Space XSlope (%)	5.6	N/A	B 2 Clear Floor Space XSlope (%)	N/A
N/A	N/A	B 2 VibroTact Parallel to Xing?	N/A	N/A	B 1 PAR Slope (%)	7.2	N/A	B 2 PAR Slope (%)	N/A
N/A	N/A	B 2 VibroTact Contrast	N/A	Yes	B 1 Height (in)	37.0	N/A	B 2 Height (in)	N/A
N/A	N/A	B 2 Pilot Light?	N/A	Yes	B 1 Pressure (#)	2.0	N/A	B 2 Pressure (#)	N/A
N/A	N/A	B 2 Pilot Light Illumination?	N/A	Yes	B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A
N/A	N/A B 2 Verbal Walk Cycle?			MUTCD Compliance					
N/A	N/A	B 2 Verbal Message Audible?	N/A	Yes	B 1 Clear Xing Direction? ClearlyM	arked	N/A	B 2 Clear Xing Direction?	N/A
N/A	N/A	B 2 Locator Tone?	N/A		B 1 Crossing Direction	To NW		B 2 Crossing Direction	N/A
N/A	N/A	B 2 Percussive Walk Cycle?	N/A	Yes	B 1 DistanceTo XWalk (in)	0.0	N/A	B 2 DistanceTo XWalk (in)	N/A
N/A	N/A	B 2 Extended Press Feature?	N/A	No	B 1 DistanceTo Curb (in)	82.0	N/A	B 2 DistanceTo Curb (in)	N/A