

## **Access Compliance Report Public Rights-of-Way** (Pedestrian Signals)



Data

N/A

N/A

N/A

No

N/A

N/A

N/A N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Signal Type: One Push Button-Non APS Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A ADA ID: C57597DF3369 **Overall Compliance: No** 

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

Yes B 1 FWD Approach Reach (in)

N/A B 1 FWD Approach Width (in)

**Button Count** 

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 Parallel To XWalk?

B 1 PAR to Button?

No B 1 PAR to XWalk?

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Compliance Description

**Button1 N/A** Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Yes N/A B 2 Parallel To XWalk?

No N/A B 2 PAR to Button?

No N/A B 2 PAR to XWalk?

Yes N/A B 2 FWD Approach?

Yes N/A B 2 Clear Floor Space?

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes N/A B 2 Sign Lettering & Contrast?

**No N/A** B 2 FWD Approach Constrained?


**0.0 N/A** B 2 FWD Approach Reach (in)

N/A N/A B 2 FWD Approach Width (in)

Located In An Island/Median?

Data

No



Possible Solutions: Provide PAR As Indicated. Remove and Replace Clear Space. Surveyor Notes: N/A PROW/ADA: R404.3, R404.2

Yes B 1 Clear Floor Space? N/A B 1 FWD Approach?

800.00 N/A B 1 FWD Approach Constrained?

				<b>N/A</b> B11	FWD Approach Obstruction?	? Yes N/A	B 2 FWD Approach Obstruction?	N/A
			WALK MIGH FOR ING VERFOLLS	<b>N/A</b> B11	FWD Approach Obstruction	Dist (in) 0.0 N/A	B 2 FWD Approach ObstructionDist (in)	N/A
		DOM TOTAL TOTAL TO	E TOP	<b>N/A</b> B11	PARA Approach?	Yes N/A	B 2 PARA Approach?	N/A
		TO THE PARTY OF TH	UTTON SIGNAL	<b>N/A</b> B11	PARA Approach Constrained	d? <b>No N/</b>	B 2 PARA Approach Constrained?	N/A
				Yes B11	PARA Approach Reach (in)	0.0 N/A	B 2 PARA Approach Reach (in)	N/A
				<b>N/A</b> B1	PARA Approach Width (in)	N/A N/A	B 2 PARA Approach Width (in)	N/A
				<b>N/A</b> B11	PARA Approach Obstruction	? Yes N/A	B 2 PARA Approach Obstruction?	N/A
APS Compliance				<b>N/A</b> B11	PARA Approach Obstruction	Dist (in) 0.0 N/A	B 2 PARA Approach ObstructionDist (in)	N/A
Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	N/A	<b>No</b> B1	Clear Floor Space Slope (%	) 3.5 N/A	B 2 Clear Floor Space Slope (%)	N/A
N/A B 1 VibroTact Arrow?	N/A N/A	B 2 VibroTact Arrow?	N/A	Yes B1	Clear Floor Space XSlope (	%) <b>0.2 N/</b> A	B 2 Clear Floor Space XSlope (%)	N/A
N/A B 1 VibroTact Parallel to Xing?	N/A N/A	B 2 VibroTact Parallel to Xing?	N/A	<b>N/A</b> B1	PAR Slope (%)	2.1 N/A	B 2 PAR Slope (%)	N/A
N/A B 1 VibroTact Contrast	N/A N/A	B 2 VibroTact Contrast	N/A	Yes B11	Height (in)	36.0 N/A	B 2 Height (in)	N/A
N/A B 1 Pilot Light?	N/A N/A	B 2 Pilot Light?	N/A	Yes B11	Pressure (#)	3.0 N/A	B 2 Pressure (#)	N/A
N/A B 1 Pilot Light Illumination?	N/A N/A	B 2 Pilot Light Illumination?	N/A	Yes B10	Closed Fist Operation?	Yes N/A	B 2 Closed Fist Operation?	N/A
N/A B 1 Verbal Walk Cycle?	N/A N/A	B 2 Verbal Walk Cycle?	N/A	MUTCD Compliance				
N/A B 1 Verbal Message Audible?	N/A N/A	B 2 Verbal Message Audible?	N/A	Yes B10	Clear Xing Direction?	ClearlyMarked N/A	B 2 Clear Xing Direction?	N/A
N/A B 1 Locator Tone?	N/A N/A	B 2 Locator Tone?	N/A	B 1 0	Crossing Direction	To NW	B 2 Crossing Direction	N/A
N/A B 1 Percussive Walk Cycle?	N/A N/A	B 2 Percussive Walk Cycle?	N/A	Yes B11	DistanceTo XWalk (in)	43.0 N/A	B 2 DistanceTo XWalk (in)	N/A
N/A B 1 Extended Press Feature?	N/A N/A	B 2 Extended Press Feature?	N/A	Yes B11	DistanceTo Curb (in)	41.0 N/A	B 2 DistanceTo Curb (in)	N/A
N/A B 1 Tone Audible Range?	N/A N/A	B 2 Tone Audible Range?	N/A	Yes B11	Diameter (in)	2.0 N/A	B 2 Diameter (in)	N/A