cole

N/A B 1 Tone Audible Range?

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



2.0 N/A B 2 Diameter (in)

N/A

(
Intersection ID: N/A	tion ID: N/A Main Street: Cross Street: N/A					Location: N/A		
ADA ID: C65A82EDB219	Signal Type:O	ne Push Button-Non APS	Overall Co	ompliance: No Severity Score	: BTN 1:N/	A BTN 2: N/A No BTN:	N/A	
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance								
			nal Dualt	Compliance Description		npliance Description	Data	
ATTIN		Possible Solutions: Replace Sig Button With APS Button on New Remove & Replace Sign.		Button Count		Distant to Additional Button (in)	N/A	
Shine States St				Additional Button Present?	No	Additional Button ID	N/A	
All some	Set all			N/A Signal Buttons Required?	N/A N/A	Additional Ped Posts Required	N/A	
Carlon Allen	Star Star			How Many Ped Street Xings?	2	Located In An Island/Median?	No	
		Surveyor Notes: N/A		N/A B1 Sign Present?	Yes N/A	B 2 Sign Present?	N/A	
	8 8 1 /	-		No B 1 Sign Purpose?	No N/A	B 2 Sign Purpose?	N/A	
	8			Yes B1 Sign Lettering & Contrast?	Yes N/A	B 2 Sign Lettering & Contrast?	N/A	
Bhr H				Yes B 1 Parallel To XWalk?	Yes N/A	B 2 Parallel To XWalk?	N/A	
VIEW P		PROW/ADA: R209.1, TMUTCD 46	e.08, R404.2,	Yes B 1 PAR to Button?	Yes N/A	B 2 PAR to Button?	N/A	
	J. H.	R404.3, R404.7.1, R404.7.2, R406		Yes B 1 PAR to XWalk?	Yes N/A	B 2 PAR to XWalk?	N/A	
				Yes B1 Clear Floor Space?	Yes N/A	B 2 Clear Floor Space?	N/A	
A CARLER I				No B 1 FWD Approach?	No N/A	B 2 FWD Approach?	N/A	
1981 None	E -	Total Cost: \$	700.00	N/A B 1 FWD Approach Constrained?	N/A N/A	B 2 FWD Approach Constrained?	N/A	
				N/A B 1 FWD Approach Reach (in)	N/A N/A	B 2 FWD Approach Reach (in)	N/A	
				N/A B 1 FWD Approach Width (in)	N/A N/A	B 2 FWD Approach Width (in)	N/A	
				N/A B 1 FWD Approach Obstruction?	N/A N/A	B 2 FWD Approach Obstruction?	N/A	
				N/A B 1 FWD Approach Obstruction Dist (i	n) N/A N/A	B 2 FWD Approach ObstructionDis	st (in) N/A	
			. 0.1	No B 1 PARA Approach?	No N/A	B 2 PARA Approach?	N/A	
				N/A B 1 PARA Approach Constrained?	N/A N/A	B 2 PARA Approach Constrained?	N/A	
APS Compliance				N/A B 1 PARA Approach Reach (in)	N/A N/A	B 2 PARA Approach Reach (in)	N/A	
				N/A B 1 PARA Approach Width (in)	N/A N/A	B 2 PARA Approach Width (in)	N/A	
				N/A B 1 PARA Approach Obstruction?	N/A N/A	B 2 PARA Approach Obstruction?	N/A	
				N/A B 1 PARA Approach Obstruction Dist (in) N/A N/A	B 2 PARA Approach ObstructionDi	st (in) N/A	
Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	N/A	No B 1 Clear Floor Space Slope (%)	4.3 N/A	B 2 Clear Floor Space Slope (%)	N/A	
N/A B 1 VibroTact Arrow?	N/A N/A	B 2 VibroTact Arrow?	N/A	No B 1 Clear Floor Space XSlope (%)	2.4 N/A	B 2 Clear Floor Space XSlope (%)	N/A	
N/A B 1 VibroTact Parallel to Xing?	N/A N/A	B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	3.8 N/A	B 2 PAR Slope (%)	N/A	
N/A B 1 VibroTact Contrast	N/A N/A	B 2 VibroTact Contrast	N/A	No B 1 Height (in)	53.0 N/A	B 2 Height (in)	N/A	
N/A B 1 Pilot Light?	N/A N/A	B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	2.0 N/A	B 2 Pressure (#)	N/A	
N/A B 1 Pilot Light Illumination?	N/A N/A	B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes N/A	B 2 Closed Fist Operation?	N/A	
N/A B 1 Verbal Walk Cycle?	N/A N/A	B 2 Verbal Walk Cycle?	N/A		MUTCD Com	pliance		
N/A B 1 Verbal Message Audible?	N/A N/A	B 2 Verbal Message Audible?	N/A	N/A B1 Clear Xing Direction?	N/A N/A	B 2 Clear Xing Direction?	N/A	
N/A B 1 Locator Tone?	N/A N/A	B 2 Locator Tone?	N/A	B 1 Crossing Direction	To SW	B 2 Crossing Direction	N/A	
N/A B 1 Percussive Walk Cycle?	N/A N/A	B 2 Percussive Walk Cycle?	N/A	No B 1 DistanceTo XWalk (in)	239 N/A	B 2 DistanceTo XWalk (in)	N/A	
N/A B1 Extended Press Feature?	N/A N/A	B 2 Extended Press Feature?	N/A	No B 1 DistanceTo Curb (in)	91.0 N/A	B 2 DistanceTo Curb (in)	N/A	

N/A

Yes B 1 Diameter (in)

N/A N/A B 2 Tone Audible Range?