

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

No

N/A N/A

N/A N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Main Street: Intersection ID: N/A Cross Street: N/A Location: N/A

ADA ID: C88FADB9AA30 Signal Type: One Push Button-APS **Overall Compliance: No** Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Button Count

N/A B 1 Sign Present?

N/A B 1 PARA Approach?

Yes B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)

N/A B 1 PARA Approach Constrained?

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 N/A Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Yes N/A B 2 Parallel To XWalk?

N/A B 2 PAR to XWalk?

Yes N/A B 2 Clear Floor Space? Yes N/A B 2 FWD Approach?

Yes N/A B 2 PARA Approach?

40.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)

Yes N/A B 2 PAR to Button?

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes N/A B 2 Sign Lettering & Contrast?

No N/A B 2 FWD Approach Constrained?

5.0 N/A B 2 FWD Approach Reach (in)

N/A N/A B 2 FWD Approach Width (in)

Yes N/A B 2 FWD Approach Obstruction?

No N/A B 2 PARA Approach Constrained?

3.0 N/A B 2 FWD Approach ObstructionDist (in)

Located In An Island/Median?

Data

No



Yes B 1 Extended Press Feature? Yes B 1 Tone Audible Range?

Possible Solutions: Remove & Replace Replace APS Button With New APS Button.

Surveyor Notes: N/A

Yes N/A B 2 Extended Press Feature?

Yes N/A B 2 Tone Audible Range?

PROW/ADA: R406.2, R209.1, MUTCD 4e.10

Total Cost:



Yes B 1 Sign Purpose? Yes B 1 Sign Lettering & Contrast? Yes B 1 Parallel To XWalk? Yes B 1 PAR to Button? Yes B 1 PAR to XWalk? Yes B 1 Clear Floor Space? N/A B 1 FWD Approach? 750.00 N/A B 1 FWD Approach Constrained? No B 1 FWD Approach Reach (in) N/A B 1 FWD Approach Width (in) N/A B 1 FWD Approach Obstruction? N/A B 1 FWD Approach Obstruction Dist (in)

Yes B 1 PARA Approach Reach (in) 5.0 N/A B 2 PARA Approach Reach (in) N/A N/A B 1 PARA Approach Width (in) N/A N/A N/A B 2 PARA Approach Width (in) N/A B 1 PARA Approach Obstruction? Yes N/A B 2 PARA Approach Obstruction? N/A APS Compliance N/A B 1 PARA Approach Obstruction Dist (in) 3.0 N/A B 2 PARA Approach Obstruction Dist (in) N/A Is Button 2 APS or Non-APS? Is Button 1 APS or Non-APS? **APS** N/A Yes B 1 Clear Floor Space Slope (%) 2.9 N/A B 2 Clear Floor Space Slope (%) N/A Yes B 1 VibroTact Arrow? Yes N/A B 2 VibroTact Arrow? N/A Yes B 1 Clear Floor Space XSlope (%) 2.0 N/A B 2 Clear Floor Space XSlope (%) N/A Yes B 1 VibroTact Parallel to Xing? Yes N/A B 2 VibroTact Parallel to Xing? N/A N/A B 1 PAR Slope (%) 3.3 N/A B 2 PAR Slope (%) N/A N/A N/A Yes B 1 VibroTact Contrast Yes N/A B 2 VibroTact Contrast Yes B 1 Height (in) 36.0 N/A B 2 Height (in) Yes B 1 Pilot Light? Yes N/A B 2 Pilot Light? N/A Yes B 1 Pressure (#) 2.0 N/A B 2 Pressure (#) N/A Yes N/A B 2 Pilot Light Illumination? Yes B 1 Closed Fist Operation? Yes N/A B 2 Closed Fist Operation? N/A Yes B 1 Pilot Light Illumination? N/A No B 1 Verbal Walk Cycle? Yes N/A B 2 Verbal Walk Cycle? N/A **MUTCD Compliance** ClearlyMarked N/A B 2 Clear Xing Direction? N/A B 1 Verbal Message Audible? N/A B 2 Verbal Message Audible? N/A Yes B 1 Clear Xing Direction? N/A N/A Yes B 1 Locator Tone? Yes N/A B 2 Locator Tone? N/A **B 1 Crossing Direction** To NW **B 2 Crossing Direction** N/A Yes B 1 Percussive Walk Cycle? Yes N/A B 2 Percussive Walk Cycle? N/A Yes B 1 DistanceTo XWalk (in) 43.0 N/A B 2 DistanceTo XWalk (in)

N/A

N/A