

## **Access Compliance Report Public Rights-of-Way** (Pedestrian Signals)



Data

840E036C9E7E

348.0

N/A

No

N/A

N/A

N/A N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A

N/A

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Severity Score: BTN 1:N/A BTN 2: N/A No BTN: Signal Type: One Push Button-Non APS ADA ID: C9713A967E0A **Overall Compliance: No** N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

No B 1 FWD Approach Reach (in)

N/A B 1 FWD Approach Width (in)

**N/A** B 1 FWD Approach Obstruction?

**N/A** B 1 PARA Approach Constrained?

N/A B 1 FWD Approach Obstruction Dist (in)

**Button Count** 

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 Parallel To XWalk?

Yes B 1 Clear Floor Space?

Yes B 1 PAR to Button?

Yes B 1 PAR to XWalk?

N/A B 1 FWD Approach?

N/A B 1 PARA Approach?

Yes B 1 Diameter (in)

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Compliance Description

**Button1** Yes Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Yes N/A B 2 Parallel To XWalk?

Yes N/A B 2 Clear Floor Space?

Yes N/A B 2 PAR to Button?

Yes N/A B 2 PAR to XWalk?

Yes N/A B 2 FWD Approach?

Yes N/A B 2 PARA Approach?

2.0 N/A B 2 Diameter (in)

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes N/A B 2 Sign Lettering & Contrast?

**No N/A** B 2 FWD Approach Constrained?

6.0 N/A B 2 FWD Approach Reach (in)

Yes N/A B 2 FWD Approach Obstruction?

**No N/A** B 2 PARA Approach Constrained?

2.0 N/A B 2 FWD Approach ObstructionDist (in)

N/A N/A B 2 FWD Approach Width (in)

Located In An Island/Median?

Data

Yes



N/A B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R404.2, R404.3, R406.2

Total Cost:

**650.00** N/A B 1 FWD Approach Constrained?





N/A N/A B 2 Tone Audible Range?



|                                     |         |                                   |     | Yes              | Yes B 1 PARA Approach Reach (in) |                 | N/A        | B 2 PARA Approach Reach (in)           | N/A          |
|-------------------------------------|---------|-----------------------------------|-----|------------------|----------------------------------|-----------------|------------|--|--------------|
|                                     |         |                                   |     | N/A              | B 1 PARA Approach Width (in)     | N/A             | N/A        | B 2 PARA Approach Width (in)           | N/A          |
|                                     |         |                                   |     | N/A              | B 1 PARA Approach Obstructio     | n? Yes          | N/A        | B 2 PARA Approach Obstruction?         | N/A          |
| APS Compliance                      |         |                                   |     | N/A              | B 1 PARA Approach Obstructio     | n Dist (in) 2.5 | N/A        | B 2 PARA Approach ObstructionDist (in) | ) <b>N/A</b> |
| Is Button 1 APS or Non-APS?         | NonAPS  | Is Button 2 APS or Non-APS?       | N/A | No               | B 1 Clear Floor Space Slope (%   | %) 6.5          | N/A        | B 2 Clear Floor Space Slope (%)        | N/A          |
| N/A B 1 VibroTact Arrow?            | N/A N// | A B 2 VibroTact Arrow?            | N/A | No               | B 1 Clear Floor Space XSlope     | (%) 2.1         | N/A        | B 2 Clear Floor Space XSlope (%)       | N/A          |
| N/A B 1 VibroTact Parallel to Xing? | N/A N// | A B 2 VibroTact Parallel to Xing? | N/A | N/A              | B 1 PAR Slope (%)                | 0.7             | N/A        | B 2 PAR Slope (%)                      | N/A          |
| N/A B 1 VibroTact Contrast          | N/A N// | A B 2 VibroTact Contrast          | N/A | Yes              | B 1 Height (in)                  | 37.0            | N/A        | B 2 Height (in)                        | N/A          |
| N/A B 1 Pilot Light?                | N/A N// | A B 2 Pilot Light?                | N/A | Yes              | B 1 Pressure (#)                 | 2.0             | N/A        | B 2 Pressure (#)                       | N/A          |
| N/A B 1 Pilot Light Illumination?   | N/A N// | A B 2 Pilot Light Illumination?   | N/A | Yes              | B 1 Closed Fist Operation?       | Yes             | N/A        | B 2 Closed Fist Operation?             | N/A          |
| N/A B 1 Verbal Walk Cycle?          | N/A N// | A B 2 Verbal Walk Cycle?          | N/A | MUTCD Compliance |                                  |                 |            |  |              |
| N/A B 1 Verbal Message Audible?     | N/A N// | A B 2 Verbal Message Audible?     | N/A | Yes              | B 1 Clear Xing Direction?        | ClearlyMarked   | N/A        | B 2 Clear Xing Direction?              | N/A          |
| N/A B 1 Locator Tone?               | N/A N// | A B 2 Locator Tone?               | N/A |                  | B 1 Crossing Direction           | To SW           | / <b> </b> | B 2 Crossing Direction                 | N/A          |
| N/A B 1 Percussive Walk Cycle?      | N/A N// | A B 2 Percussive Walk Cycle?      | N/A | No               | B 1 DistanceTo XWalk (in)        | 66.0            | N/A        | B 2 DistanceTo XWalk (in)              | N/A          |
| N/A B 1 Extended Press Feature?     | N/A N// | A B 2 Extended Press Feature?     | N/A | Yes              | B 1 DistanceTo Curb (in)         | 62.0            | N/A        | B 2 DistanceTo Curb (in)               | N/A          |

N/A