cole

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Intersection ID: N/A	on ID: N/A Main Street: Cross Street: N/A						Location: N/A		
ADA ID: CB0BF3F945CA	Signal Type:O	ne Push Button-Non APS	Overall Co	ompliance: No	Severity Score:	BTN 1:N/	A BTN 2: N/A	No BTN:	N/A
Codes		Field Measurements/Component Compliance							
	Douloos Cinn	Compliance Descri	iption	Data Compliance Description Data					
		Possible Solutions: Remove & R Remove and Replace Clear Space		Button Count	В	utton1 Yes	Distant to Additiona	al Button (in)	332.0
		· · ·		Additional Button	Present?	Yes	Additional Button II	361	14842A3874
	- Caller 1			N/A Signal Buttons Required?		N/A N/A	Additional Ped Pos	ts Required	N/A
CENTRAL AN				How Many Ped S	How Many Ped Street Xings?		Located In An Islar	d/Median?	No
		Surveyor Notes: B1 SIGN COVERE GRAFITTI	RED IN	N/A B 1 Sign Present?		Yes N/A	B 2 Sign Present?		N/A
	1 =			No B 1 Sign Purpose?		No N/A	B 2 Sign Purpose?		N/A
				Yes B 1 Sign Lettering & Contrast?		Yes N/A	B 2 Sign Lettering	& Contrast?	N/A
- TEPHSON &				No B 1 Parallel To XWalk?		No N/A B 2 Parallel To XWalk?		alk?	N/A
		PROW/ADA: R209.1, TMUTCD 4e	209.1, TMUTCD 4e.08, R404.2,		Yes B 1 PAR to Button?		B 2 PAR to Button?)	N/A
	1 270	R404.3		Yes B 1 PAR to XWalk?		Yes N/A	B 2 PAR to XWalk?)	N/A
19 31			Yes B 1 Clear Floor Space?		Yes N/A	B 2 Clear Floor Spa	ace?	N/A	
				N/A B 1 FWD Approach?		Yes N/A B 2 FWD Approach?		1?	N/A
		Total Cost: \$	650.00	N/A B1 FWD Approa	ach Constrained?	No N/A	B 2 FWD Approach	Constrained?	N/A
				Yes B1 FWD Approa	ach Reach (in)	0.0 N/A	B 2 FWD Approach	Reach (in)	N/A
				N/A B1 FWD Approa	ach Width (in)	N/A N/A	A N/A B 2 FWD Approach Width (in)		N/A
				ach Obstruction?	No N/A	B 2 FWD Approach	Obstruction?	N/A	
				N/A B 1 FWD Approach Obstruction Dist (in N/A B 1 PARA Approach?		N/A N/A	N/A B 2 FWD Approach ObstructionDist (i		ist (in) N/A
						Yes N/A	B 2 PARA Approac	h?	N/A
				N/A B 1 PARA Approa	PARA Approach Constrained?		B 2 PARA Approac	h Constrained?	? N/A
				Yes B 1 PARA Approach Reach (in)		0.0 N/A	N/A B 2 PARA Approach Reach (in)		N/A
				N/A B 1 PARA Approach Width (in)		N/A N/A B 2 PARA Approach Width (in)		h Width (in)	N/A
	N/A B 1 PARA Approach Obstruction?		No N/A B 2 PARA Approach Obstruction?		N/A				
	APS Complian	ice		N/A B 1 PARA Approa	ach Obstruction Dist (in)) N/A N/A	B 2 PARA Approac	h ObstructionD	Dist (in) N/A
Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	N/A	No B 1 Clear Floor S	Space Slope (%)	5.7 N/A	B 2 Clear Floor Spa	ace Slope (%)	N/A
N/A B 1 VibroTact Arrow?	N/A N/A	B 2 VibroTact Arrow?	N/A	No B 1 Clear Floor S	Space XSlope (%)	4.3 N/A	B 2 Clear Floor Spa	ace XSlope (%) N/A
N/A B 1 VibroTact Parallel to Xing?	N/A N/A	B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	0.4 N/A	B 2 PAR Slope (%)		N/A
N/A B 1 VibroTact Contrast	N/A N/A	B 2 VibroTact Contrast	N/A	Yes B1 Height (in)		37.0 N/A	B 2 Height (in)		N/A
N/A B 1 Pilot Light?	N/A N/A	B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)		2.0 N/A	B 2 Pressure (#)		N/A
N/A B 1 Pilot Light Illumination?	N/A N/A	B 2 Pilot Light Illumination?	N/A	Yes B1 Closed Fist C	Operation?	Yes N/A	B 2 Closed Fist Op	eration?	N/A
N/A B 1 Verbal Walk Cycle?	Yerbal Walk Cycle? N/A N/A B 2 Verbal Walk Cycle? N/A		MUTCD Compliance						
N/A B 1 Verbal Message Audible?	N/A N/A	B 2 Verbal Message Audible?	N/A	Yes B1 Clear Xing D	irection? Clearly	Marked N/A	B 2 Clear Xing Dire	ection?	N/A
N/A B 1 Locator Tone?	N/A N/A	B 2 Locator Tone?	N/A	B 1 Crossing Dire	ection	Το Ν	B 2 Crossing Direc	tion	N/A
N/A B 1 Percussive Walk Cycle?	N/A N/A	B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo X	(Walk (in)	0.0 N/A	B 2 DistanceTo XW	/alk (in)	N/A
N/A B 1 Extended Press Feature?	N/A N/A	B 2 Extended Press Feature?	N/A	Yes B 1 DistanceTo C	Curb (in)		B 2 DistanceTo Cu	rb (in)	N/A
N/A B 1 Tone Audible Range?	N/A N/A	B 2 Tone Audible Range?	N/A	Yes B 1 Diameter (in))	2.0 N/A	B 2 Diameter (in)		N/A