

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

No

N/A

N/A N/A

N/A

N/A

N/A

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Severity Score: BTN 1:N/A BTN 2: N/A No BTN: Signal Type: One Push Button-Non APS N/A ADA ID: CB41A58A4E48 **Overall Compliance: No**

Compliance Description

Additional Button Present?

Button Count

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 N/A Distant to Additional Button (in)

119.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)

Additional Button ID

Data

No



N/A B 1 Tone Audible Range?

N/A B 1 Extended Press Feature?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R404.2, R404.3, R406.2

Total Cost:

No N/A B 2 Extended Press Feature?

No N/A B 2 Tone Audible Range?







N/A Signal Buttons Required? N/A N/A Additional Ped Posts Required Located In An Island/Median? How Many Ped Street Xings? N/A B 1 Sign Present? Yes N/A B 2 Sign Present? Yes N/A B 2 Sign Purpose? Yes B 1 Sign Purpose? Yes B 1 Sign Lettering & Contrast? Yes N/A B 2 Sign Lettering & Contrast? Yes N/A B 2 Parallel To XWalk? Yes B 1 Parallel To XWalk? Yes B 1 PAR to Button? Yes N/A B 2 PAR to Button? Yes B 1 PAR to XWalk? Yes N/A B 2 PAR to XWalk? Yes N/A B 2 Clear Floor Space? Yes B 1 Clear Floor Space? N/A B 1 FWD Approach? Yes N/A B 2 FWD Approach? 650.00 N/A B 1 FWD Approach Constrained? **No N/A** B 2 FWD Approach Constrained? No B 1 FWD Approach Reach (in) 6.0 N/A B 2 FWD Approach Reach (in) N/A B 1 FWD Approach Width (in) **60.0 N/A** B 2 FWD Approach Width (in) N/A B 1 FWD Approach Obstruction? Yes N/A B 2 FWD Approach Obstruction? N/A B 1 FWD Approach Obstruction Dist (in) 4.0 N/A B 2 FWD Approach ObstructionDist (in) Yes N/A B 2 PARA Approach? N/A B 1 PARA Approach? **N/A** B 1 PARA Approach Constrained? **No N/A** B 2 PARA Approach Constrained? Yes B 1 PARA Approach Reach (in) 6.0 N/A B 2 PARA Approach Reach (in)



				N/A B 1 PARA Approach Width (in)	60.0 N//	A B 2 PARA Approach Width (in)	N/A
				N/A B 1 PARA Approach Obstruction	ı? Yes N //	A B 2 PARA Approach Obstruction?	N/A
APS Compliance				N/A B 1 PARA Approach Obstruction	ı Dist (in) 4.0 N//	A B 2 PARA Approach ObstructionDist (i	in) N/A
Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	N/A	No B 1 Clear Floor Space Slope (%) 5.8 N //	A B 2 Clear Floor Space Slope (%)	N/A
N/A B 1 VibroTact Arrow?	No N/	/A B 2 VibroTact Arrow?	N/A	No B 1 Clear Floor Space XSlope (9	%) 9.8 N//	A B 2 Clear Floor Space XSlope (%)	N/A
N/A B 1 VibroTact Parallel to Xing?	No N/	/A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	2.0 N//	A B 2 PAR Slope (%)	N/A
N/A B 1 VibroTact Contrast	No N/	/A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	38.0 N//	A B 2 Height (in)	N/A
N/A B 1 Pilot Light?	No N/	/A B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	1.5 N//	A B 2 Pressure (#)	N/A
N/A B 1 Pilot Light Illumination?	No N/	/A B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes N//	A B 2 Closed Fist Operation?	N/A
N/A B 1 Verbal Walk Cycle?	No N/	/A B 2 Verbal Walk Cycle?	N/A	MUTCD Compliance			
N/A B 1 Verbal Message Audible?	No N/	/A B 2 Verbal Message Audible?	N/A	Yes B 1 Clear Xing Direction?	ClearlyMarked N//	A B 2 Clear Xing Direction?	N/A
N/A B 1 Locator Tone?	No N/	/A B 2 Locator Tone?	N/A	B 1 Crossing Direction	To W	B 2 Crossing Direction	N/A
N/A B 1 Percussive Walk Cycle?	No N/	/A B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo XWalk (in)	54.0 N//	A B 2 DistanceTo XWalk (in)	N/A

N/A

N/A

No B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)