

## **Access Compliance Report Public Rights-of-Way** (Pedestrian Signals)



Data

1C3223FE803F

271.0

N/A

N/A N/A

N/A

N/A

N/A

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Severity Score: BTN 1:N/A BTN 2: N/A No BTN: Signal Type: One Push Button-APS ADA ID: D1717D12B833 **Overall Compliance: No** N/A

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Compliance Description

**Button1** Yes Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

106.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)

Additional Button ID

N/A N/A Additional Ped Posts Required

Located In An Island/Median?

Data

Yes

N/A



Yes B 1 Extended Press Feature?

Yes B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R404.7.1, R404.7.2, R209.1, MUTCD 4e.10

Total Cost:

Yes N/A B 2 Extended Press Feature?

Yes N/A B 2 Tone Audible Range?



Yes B 1 Sign Lettering & Contrast? Yes N/A B 2 Sign Lettering & Contrast? Yes B 1 Parallel To XWalk? Yes N/A B 2 Parallel To XWalk? Yes B 1 PAR to Button? Yes N/A B 2 PAR to Button? Yes B 1 PAR to XWalk? Yes N/A B 2 PAR to XWalk? Yes N/A B 2 Clear Floor Space? Yes B 1 Clear Floor Space? No B 1 FWD Approach? No N/A B 2 FWD Approach? 650.00 N/A B 1 FWD Approach Constrained? N/A N/A B 2 FWD Approach Constrained? N/A B 1 FWD Approach Reach (in) N/A N/A B 2 FWD Approach Reach (in) N/A B 1 FWD Approach Width (in) N/A N/A B 2 FWD Approach Width (in) N/A B 1 FWD Approach Obstruction? Yes N/A B 2 FWD Approach Obstruction? N/A B 1 FWD Approach Obstruction Dist (in) 6.0 N/A B 2 FWD Approach ObstructionDist (in) No B 1 PARA Approach? N/A N/A B 2 PARA Approach? **N/A** B 1 PARA Approach Constrained? **N/A N/A** B 2 PARA Approach Constrained? N/A B 1 PARA Approach Reach (in) 20.0 N/A B 2 PARA Approach Reach (in) R 1 DARA Approach Width (in) P 2 DA DA Annroach Width (in)

B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

**Button Count** 

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

*//	
	44
1	

				N/A B 1 PARA Approach Width (in)	48.0	N/A	B 2 PARA Approach Width (in)	N/A
				N/A B 1 PARA Approach Obstruction?	Yes	N/A	B 2 PARA Approach Obstruction?	N/A
APS Compliance				N/A B 1 PARA Approach Obstruction Dist (in)	6.0	N/A	B 2 PARA Approach ObstructionDist (in)	) <b>N/A</b>
Is Button 1 APS or Non-APS?	APS	Is Button 2 APS or Non-APS?	N/A	Yes B 1 Clear Floor Space Slope (%)	1 8.0	N/A	B 2 Clear Floor Space Slope (%)	N/A
Yes B 1 VibroTact Arrow?	Yes N/A	A B 2 VibroTact Arrow?	N/A	Yes B 1 Clear Floor Space XSlope (%)	2.0 1	N/A	B 2 Clear Floor Space XSlope (%)	N/A
Yes B 1 VibroTact Parallel to Xing?	Yes N/A	A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	N/A I	N/A	B 2 PAR Slope (%)	N/A
Yes B 1 VibroTact Contrast	Yes N/A	A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	34.0	N/A	B 2 Height (in)	N/A
Yes B 1 Pilot Light?	Yes N/A	A B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	2.0 1	N/A	B 2 Pressure (#)	N/A
Yes B 1 Pilot Light Illumination?	Yes N/A	A B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A
No B 1 Verbal Walk Cycle?	Yes N/A	A B 2 Verbal Walk Cycle?	N/A	MUTCD Compliance				
N/A B 1 Verbal Message Audible?	Yes N/A	A B 2 Verbal Message Audible?	N/A	N/A B 1 Clear Xing Direction?	Yes	N/A	B 2 Clear Xing Direction?	N/A
Yes B 1 Locator Tone?	Yes N/A	A B 2 Locator Tone?	N/A	B 1 Crossing Direction	To NE		B 2 Crossing Direction	N/A
Yes B 1 Percussive Walk Cycle?	Yes N/A	A B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo XWalk (in)	1 0.0	N/A	B 2 DistanceTo XWalk (in)	N/A

N/A

N/A