

A photograph of a utility pole with a transformer and a yellow caution sign. The pole is located on a grassy area next to a paved road. The transformer is a large, grey, rectangular unit mounted on the pole. A yellow caution sign with black text is attached to the pole. The background shows a parking lot with several cars and a building.

MUTCD Compliance					
Yes	B 1 Clear Xing Direction?	ClearlyMarked	Yes	B 2 Clear Xing Direction?	ClearlyMarked
	B 1 Crossing Direction	To NW		B 2 Crossing Direction	To SW
Yes	B 1 DistanceTo XWalk (in)	13.0	Yes	B 2 DistanceTo XWalk (in)	0.0
No	B 1 DistanceTo Curb (in)	216.0	No	B 2 DistanceTo Curb (in)	216.0
Yes	B 1 Diameter (in)	2.0	Yes	B 2 Diameter (in)	2.0