

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

No

Yes

Yes

Yes

Yes

Yes

Yes Yes

Yes

No

11.0

N/A

No

N/A

Yes

No

0.0

2.0

130.0

Intersection ID: N/A Main Street: Cross Street: N/A Location: N/A

ADA ID: D465ED58A356 Signal Type: Two Push Buttons-Non APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Button Count

No B 1 Sign Present?

N/A B 1 Sign Purpose?

Yes B 1 Clear Floor Space?

N/A B 1 PARA Approach?

No B 1 DistanceTo XWalk (in)

Yes B 1 Diameter (in)

B 1 DistanceTo Curb (in)

No B 1 FWD Approach Reach (in)

N/A B 1 FWD Approach Width (in)

N/A B 1 FWD Approach Obstruction?

N/A B 1 PARA Approach Constrained?

N/A B 1 FWD Approach Obstruction Dist (in)

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button2 N/A Distant to Additional Button (in)

N/A N/A B 2 Sign Present?

Yes Yes B 2 Sign Purpose?

Yes Yes B 2 Parallel To XWalk?

Yes B 2 PAR to XWalk?

Yes Yes B 2 Clear Floor Space?

Yes N/A B 2 FWD Approach?

Yes N/A B 2 PARA Approach?

75.0 Yes B 2 DistanceTo XWalk (in)

125.0 No B 2 DistanceTo Curb (in)

2.0 Yes B 2 Diameter (in)

Yes Yes B 2 PAR to Button?

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes Yes B 2 Sign Lettering & Contrast?

No N/A B 2 FWD Approach Constrained?

No N/A B 2 FWD Approach Obstruction?

No N/A B 2 PARA Approach Constrained?

N/A N/A B 2 FWD Approach ObstructionDist (in)

11.0 No B 2 FWD Approach Reach (in)

N/A N/A B 2 FWD Approach Width (in)

Located In An Island/Median?

Data

No



N/A B 1 Percussive Walk Cycle?

N/A B 1 Tone Audible Range?

N/A B 1 Extended Press Feature?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

N/A N/A B 2 Percussive Walk Cycle?

N/A N/A B 2 Tone Audible Range?

N/A N/A B 2 Extended Press Feature?

PROW/ADA: R209.1, TMUTCD 4e.08, R404.2, R406.2

Total Cost: \$

N/A B 1 Sign Lettering & Contrast?
N/A B 1 Parallel To XWalk?

Yes B 1 PAR to Button?

Yes B 1 PAR to XWalk?

N/A B 1 FWD Approach?1100.00 N/A B 1 FWD Approach Constrained?





				Yes B 1 PARA Approach Reach (in)	10.0	Yes	B 2 PARA Approach Reach (in	n)	10.0
				N/A B 1 PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in	1)	N/A
				N/A B 1 PARA Approach Obstruction?	? No	N/A	B 2 PARA Approach Obstructi	ion?	No
APS Compliance				N/A B 1 PARA Approach Obstruction	Dist (in) N/A	N/A	B 2 PARA Approach Obstructi	ionDist (in)	N/A
Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	NonAPS	Yes B 1 Clear Floor Space Slope (%)	1.6	Yes	B 2 Clear Floor Space Slope	(%)	1.5
N/A B 1 VibroTact Arrow?	N/A N/A	B 2 VibroTact Arrow?	N/A	No B 1 Clear Floor Space XSlope (%	(o) 3.5	No	B 2 Clear Floor Space XSlope	⊖ (%)	2.1
N/A B 1 VibroTact Parallel to Xing?	N/A N/A	B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	2.0	N/A	B 2 PAR Slope (%)		2.2
N/A B 1 VibroTact Contrast	N/A N/A	B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	40.0	Yes	B 2 Height (in)		39.0
N/A B 1 Pilot Light?	N/A N/A	B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	2.0	Yes	B 2 Pressure (#)		2.0
N/A B 1 Pilot Light Illumination?	N/A N/A	B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes	Yes	B 2 Closed Fist Operation?		Yes
N/A B 1 Verbal Walk Cycle?	N/A N/A	B 2 Verbal Walk Cycle?	N/A	MUTCD Compliance					
N/A B 1 Verbal Message Audible?	N/A N/A	B 2 Verbal Message Audible?	N/A	Yes B 1 Clear Xing Direction?	ClearlyMarked	Yes	B 2 Clear Xing Direction?	ClearlyMa	rked
N/A B 1 Locator Tone?	N/A N/A	B 2 Locator Tone?	N/A	B 1 Crossing Direction	To S		B 2 Crossing Direction	To	o NE

N/A

N/A

N/A