## Cole

## **Access Compliance Report** Public Rights-of-Way (Pedestrian Signals)



Intersection ID: N/A	Main Street:		ross Street: N/A	oss Street: N/A			Location: N/A		
ADA ID: D5609B42DA6B	Signal Type:O	ne Push Button-APS	Overall Co	mpliance: No	Severity Score: B	<u>BTN 1:N//</u>	A BTN 2: N/A	No BTN:	N/A
Code	Field Measurements/Component Compliance								
		Possible Solutions: Replace Signa	l Buch	Compliance Descri	ption D	ata Com	pliance Descripti	on	Data
		Button With APS Button on New Post.		Button Count	But	tton1 N/A	Distant to Addition	al Button (in)	N/A
		Remove & Relocate Sign.		Additional Button Present?		No	Additional Button I	D	N/A
	CHEROKEE RD			N/A Signal Buttons Re	equired?	N/A N/A	Additional Ped Pos	sts Required	N/A
		Surveyor Notes: N/A		How Many Ped Street Xings?		2	Located In An Islar	nd/Median?	No
				N/A B 1 Sign Present?		Yes N/A	B 2 Sign Present?		N/A
				Yes B 1 Sign Purpose?		Yes N/A	B 2 Sign Purpose?	,	N/A
				Yes B 1 Sign Lettering & Contrast?		Yes N/A	B 2 Sign Lettering	& Contrast?	N/A
				Yes B 1 Parallel To XWalk?		Yes N/A B 2 Parallel To XWall		/alk?	N/A
		PROW/ADA: TMUTCD 4e.08, R404	2, R404.3,	Yes B 1 PAR to Button?		Yes N/A	B 2 PAR to Button	?	N/A
	IS The	R404.7.3, R209.1, MUTCD 4e.10		Yes B 1 PAR to XWalk?		Yes N/A	B 2 PAR to XWalk	?	N/A
	2 0			Yes B 1 Clear Floor Space?		Yes N/A	B 2 Clear Floor Sp	ace?	N/A
				N/A B 1 FWD Approach?		No N/A	B 2 FWD Approacl	n?	N/A
	TIN T	Total Cost: \$	\$ 650.00	N/A B 1 FWD Approad	ch Constrained?	N/A N/A	B 2 FWD Approacl	n Constrained?	N/A
				N/A B1 FWD Approach Reach (in)		N/A N/A	B 2 FWD Approacl	n Reach (in)	N/A
				N/A B 1 FWD Approac	ch Width (in)	N/A N/A	B 2 FWD Approacl	n Width (in)	N/A
				N/A B 1 FWD Approach Obstruction?		N/A N/A	B 2 FWD Approacl	n Obstruction?	N/A
				N/A B 1 FWD Approach Obstruction Dist (ir		N/A N/A	B 2 FWD Approacl	n ObstructionDis	st (in) N/A
				N/A B 1 PARA Approach?		Yes N/A	es N/A B 2 PARA Approach?		N/A
				N/A B 1 PARA Approach Constrained?		No N/A B 2 PARA Approach Constrained?		N/A	
				No B 1 PARA Approach Reach (in)		16.0 N/A B 2 PARA Approach Reach (in)		N/A	
				N/A B1 PARA Approach Width (in)		N/A N/A	B 2 PARA Approac	h Width (in)	N/A
		N/A B 1 PARA Approach Obstruction?		Yes N/A	B 2 PARA Approac	h Obstruction?	N/A		
	N/A B 1 PARA Approa	ach Obstruction Dist (in)	9.0 N/A	B 2 PARA Approac	h ObstructionDi	ist (in) N/A			
Is Button 1 APS or Non-APS?	APS	Is Button 2 APS or Non-APS?	N/A	No B1 Clear Floor S	Space Slope (%)	6.3 N/A	B 2 Clear Floor Sp	ace Slope (%)	N/A
Yes B 1 VibroTact Arrow?	Yes N/A	B 2 VibroTact Arrow?	N/A	No B1 Clear Floor S	Space XSlope (%)	5.7 N/A	B 2 Clear Floor Sp	ace XSlope (%)	N/A
Yes B1 VibroTact Parallel to Xing?	Yes N/A	B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%	%)	4.0 N/A	B 2 PAR Slope (%	)	N/A
Yes B 1 VibroTact Contrast	Yes N/A	B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)		41.0 N/A	B 2 Height (in)		N/A
Yes B 1 Pilot Light?	Yes N/A	B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)		1.0 N/A	B 2 Pressure (#)		N/A
Yes B 1 Pilot Light Illumination?	Yes N/A	B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist O	Dperation?	Yes N/A	B 2 Closed Fist Op	peration?	N/A
No B 1 Verbal Walk Cycle?	Yes N/A	Yes N/A B 2 Verbal Walk Cycle? N/A		MU'		IUTCD Compliance			
N/A B 1 Verbal Message Audible?	Yes N/A	B 2 Verbal Message Audible?	N/A	Yes B1 Clear Xing Di	irection? ClearlyMa	arked N/A	B 2 Clear Xing Dire	ection?	N/A
Yes B 1 Locator Tone?	Yes N/A	B 2 Locator Tone?	N/A	B 1 Crossing Dire	ection	To E	B 2 Crossing Direc	tion	N/A
Yes B 1 Percussive Walk Cycle?	Yes N/A	B 2 Percussive Walk Cycle?	N/A	No B 1 DistanceTo X	Walk (in)	89.0 N/A	B 2 DistanceTo XV	Valk (in)	N/A
Yes B1 Extended Press Feature?	Yes N/A	B 2 Extended Press Feature?	N/A	Yes B 1 DistanceTo C	Curb (in)	52.0 N/A	B 2 DistanceTo Cu	ırb (in)	N/A
Yes B 1 Tone Audible Range?	Yes N/A	B 2 Tone Audible Range?	N/A	Yes B 1 Diameter (in)		2.0 N/A	B 2 Diameter (in)		N/A