

## **Access Compliance Report Public Rights-of-Way** (Pedestrian Signals)



Data

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A

N/A N/A N/A

N/A

N/A N/A N/A

N/A

N/A

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Severity Score: BTN 1:N/A BTN 2: N/A No BTN: Signal Type: One Push Button-Non APS N/A ADA ID: D61D3B9D8935 **Overall Compliance: No** 

Compliance Description

**N/A** B 1 PARA Approach Constrained?

N/A B 1 PARA Approach Reach (in)

N/A B 1 PARA Approach Width (in)

No B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)

**Button Count** 

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Compliance Description

**Button1 N/A** Distant to Additional Button (in)

**N/A N/A** B 2 PARA Approach Constrained?

N/A N/A B 2 PARA Approach Reach (in)

N/A N/A B 2 PARA Approach Width (in)

74.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)

Data



N/A B 1 Extended Press Feature?

N/A B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R404.1, R404.7.1, R404.7.2

Total Cost:

N/A N/A B 2 Extended Press Feature?

N/A N/A B 2 Tone Audible Range?



N/A Additional Button Present? No Additional Button ID N/A Signal Buttons Required? N/A N/A Additional Ped Posts Required N/A Located In An Island/Median? How Many Ped Street Xings? No N/A B 1 Sign Present? Yes N/A B 2 Sign Present? N/A Yes N/A B 2 Sign Purpose? N/A Yes B 1 Sign Purpose? Yes B 1 Sign Lettering & Contrast? Yes N/A B 2 Sign Lettering & Contrast? N/A Yes N/A B 2 Parallel To XWalk? N/A Yes B 1 Parallel To XWalk? Yes B 1 PAR to Button? Yes N/A B 2 PAR to Button? N/A Yes B 1 PAR to XWalk? Yes N/A B 2 PAR to XWalk? N/A No N/A B 2 Clear Floor Space? N/A No B 1 Clear Floor Space? No B 1 FWD Approach? No N/A B 2 FWD Approach? N/A 650.00 N/A B 1 FWD Approach Constrained? N/A N/A B 2 FWD Approach Constrained? N/A N/A B 1 FWD Approach Reach (in) N/A N/A B 2 FWD Approach Reach (in) N/A N/A B 1 FWD Approach Width (in) N/A N/A B 2 FWD Approach Width (in) N/A N/A B 1 FWD Approach Obstruction? N/A N/A B 2 FWD Approach Obstruction? N/A N/A B 1 FWD Approach Obstruction Dist (in) N/A N/A B 2 FWD Approach ObstructionDist (in) N/A No B 1 PARA Approach? No N/A B 2 PARA Approach? N/A



			1071 2 1171 0 17 pp. 50 511 111 (11.)		2 = 1 / 11 11 / pp: ()	
			N/A B 1 PARA Approach Obstruction?	N/A N/A	B 2 PARA Approach Obstruction?	ı
APS Compliance			N/A B 1 PARA Approach Obstruction Dist (in	) N/A N/A	B 2 PARA Approach ObstructionDist (	n) l
Is Button 1 APS or Non-APS?	NonAPS Is Button 2 APS or Non-APS?	N/A	N/A B 1 Clear Floor Space Slope (%)	N/A N/A	B 2 Clear Floor Space Slope (%)	ı
N/A B 1 VibroTact Arrow?	N/A N/A B 2 VibroTact Arrow?	N/A	N/A B 1 Clear Floor Space XSlope (%)	N/A N/A	B 2 Clear Floor Space XSlope (%)	
N/A B 1 VibroTact Parallel to Xing?	N/A N/A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	0.7 N/A	B 2 PAR Slope (%)	ı
N/A B 1 VibroTact Contrast	N/A N/A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	37.0 N/A	B 2 Height (in)	ı
N/A B 1 Pilot Light?	N/A N/A B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	3.0 N/A	B 2 Pressure (#)	ı
N/A B 1 Pilot Light Illumination?	N/A N/A B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes N/A	B 2 Closed Fist Operation?	
N/A B 1 Verbal Walk Cycle?	N/A N/A B 2 Verbal Walk Cycle?	N/A	MUTCD Compliance			
N/A B 1 Verbal Message Audible?	N/A N/A B 2 Verbal Message Audible?	N/A	Yes B 1 Clear Xing Direction? Clearly	Marked N/A	B 2 Clear Xing Direction?	ı
N/A B 1 Locator Tone?	N/A N/A B 2 Locator Tone?	N/A	B 1 Crossing Direction	To NW	B 2 Crossing Direction	ı
N/A B 1 Percussive Walk Cycle?	N/A N/A B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo XWalk (in)	0.0 N/A	B 2 DistanceTo XWalk (in)	1

N/A

N/A