

## Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

Intersection ID: N/A Main Street: Cross Street: N/A Location: N/A

ADA ID: D748923F0B1E Signal Type: One Push Button-APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

No B 1 PARA Approach Reach (in)

B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Compliance Description

22.0 N/A B 2 PARA Approach Reach (in)

107.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)



Yes B 1 Extended Press Feature?
Yes B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R406.2, R404.7.3, R209.1, MUTCD 4e.10

Total Cost:

Yes N/A B 2 Extended Press Feature?

Yes N/A B 2 Tone Audible Range?

650.00

650.00



		ipilarios Bosonption	Dutu	00111	iphanice Becompaien	Dutu
		Button Count	Button1	N/A	Distant to Additional Button (in)	N/A
		Additional Button Present?	No		Additional Button ID	N/A
	N/A	Signal Buttons Required?	N/A	N/A	Additional Ped Posts Required	N/A
		How Many Ped Street Xings?	3		Located In An Island/Median?	Yes
	N/A	B 1 Sign Present?	Yes	N/A	B 2 Sign Present?	N/A
	Yes	B 1 Sign Purpose?	Yes	N/A	B 2 Sign Purpose?	N/A
	Yes	B 1 Sign Lettering & Contrast?	Yes	N/A	B 2 Sign Lettering & Contrast?	N/A
	Yes	B 1 Parallel To XWalk?	Yes	N/A	B 2 Parallel To XWalk?	N/A
	Yes	B 1 PAR to Button?	Yes	N/A	B 2 PAR to Button?	N/A
	Yes	B 1 PAR to XWalk?	Yes	N/A	B 2 PAR to XWalk?	N/A
	Yes	B 1 Clear Floor Space?	Yes	N/A	B 2 Clear Floor Space?	N/A
	N/A	B 1 FWD Approach?	Yes	N/A	B 2 FWD Approach?	N/A
)	N/A	B 1 FWD Approach Constrained?	No	N/A	B 2 FWD Approach Constrained?	N/A
	No	B 1 FWD Approach Reach (in)	22.0	N/A	B 2 FWD Approach Reach (in)	N/A
	N/A	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)	N/A
	N/A	B 1 FWD Approach Obstruction?	Yes	N/A	B 2 FWD Approach Obstruction?	N/A
	N/A	B 1 FWD Approach Obstruction Dist (i	n) <b>18.0</b>	N/A	B 2 FWD Approach ObstructionDist (in)	N/A
	N/A	B 1 PARA Approach?	Yes	N/A	B 2 PARA Approach?	N/A
	N/A	B 1 PARA Approach Constrained?	No	N/A	B 2 PARA Approach Constrained?	N/A



N/A B 1 PARA Approach Width (in) N/A N/A B 2 PARA Approach Width (in) N/A N/A B 1 PARA Approach Obstruction? Yes N/A B 2 PARA Approach Obstruction? N/A APS Compliance N/A B 1 PARA Approach Obstruction Dist (in) 18.0 N/A B 2 PARA Approach Obstruction Dist (in) N/A Is Button 1 APS or Non-APS? **APS** Is Button 2 APS or Non-APS? N/A Yes B 1 Clear Floor Space Slope (%) 2.5 N/A B 2 Clear Floor Space Slope (%) N/A Yes N/A B 2 VibroTact Arrow? N/A Yes B 1 Clear Floor Space XSlope (%) **0.2 N/A** B 2 Clear Floor Space XSlope (%) N/A Yes B 1 VibroTact Arrow? 3.3 N/A B 2 PAR Slope (%) Yes B 1 VibroTact Parallel to Xing? Yes N/A B 2 VibroTact Parallel to Xing? N/A N/A B 1 PAR Slope (%) N/A N/A N/A Yes B 1 VibroTact Contrast Yes N/A B 2 VibroTact Contrast Yes B 1 Height (in) 36.0 N/A B 2 Height (in) Yes B 1 Pilot Light? Yes N/A B 2 Pilot Light? Yes B 1 Pressure (#) N/A 2.0 N/A B 2 Pressure (#) N/A Yes N/A B 2 Pilot Light Illumination? N/A Yes B 1 Closed Fist Operation? Yes N/A B 2 Closed Fist Operation? N/A Yes B 1 Pilot Light Illumination? No B 1 Verbal Walk Cycle? Yes N/A B 2 Verbal Walk Cycle? N/A **MUTCD Compliance** ClearlyMarked N/A B 2 Clear Xing Direction? N/A B 1 Verbal Message Audible? Yes N/A B 2 Verbal Message Audible? N/A Yes B 1 Clear Xing Direction? N/A Yes B 1 Locator Tone? Yes N/A B 2 Locator Tone? N/A **B 1 Crossing Direction** To NW **B 2 Crossing Direction** N/A N/A Yes B 1 Percussive Walk Cycle? Yes N/A B 2 Percussive Walk Cycle? N/A No B 1 DistanceTo XWalk (in) 63.0 N/A B 2 DistanceTo XWalk (in)

N/A

N/A