

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Severity Score: BTN 1:N/A BTN 2: N/A No BTN: Signal Type: One Push Button-APS ADA ID: E14F1AD1E28C **Overall Compliance: No** N/A

Compliance Description

N/A B 1 FWD Approach Obstruction Dist (in)

N/A B 1 PARA Approach Constrained?

Yes B 1 PARA Approach Reach (in)

N/A B 1 PARA Approach Width (in)

B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)

N/A B 1 PARA Approach?

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

N/A N/A B 2 FWD Approach ObstructionDist (in)

No N/A B 2 PARA Approach Constrained?

7.0 N/A B 2 PARA Approach Reach (in)

N/A N/A B 2 PARA Approach Width (in)

Yes N/A B 2 PARA Approach?

125.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)

Data



B 1 Extended Press Feature?

No B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: OUT OF SERVICE

PROW/ADA: TMUTCD 4e.08, R209.1, TMUTCD 4e.10, MUTCD 4e.08, R104.2,

Total Cost:

No N/A B 2 Extended Press Feature?

Yes N/A B 2 Tone Audible Range?



Button Count Button1 Yes Distant to Additional Button (in) 186.0 Additional Button Present? Yes Additional Button ID 939403F3C653 N/A Signal Buttons Required? N/A N/A Additional Ped Posts Required N/A Located In An Island/Median? How Many Ped Street Xings? N/A B 1 Sign Present? Yes N/A B 2 Sign Present? N/A Yes N/A B 2 Sign Purpose? N/A Yes B 1 Sign Purpose? Yes B 1 Sign Lettering & Contrast? Yes N/A B 2 Sign Lettering & Contrast? N/A N/A Yes B 1 Parallel To XWalk? Yes N/A B 2 Parallel To XWalk? Yes B 1 PAR to Button? Yes N/A B 2 PAR to Button? N/A Yes B 1 PAR to XWalk? Yes N/A B 2 PAR to XWalk? N/A N/A Yes B 1 Clear Floor Space? Yes N/A B 2 Clear Floor Space? N/A B 1 FWD Approach? No N/A B 2 FWD Approach? N/A 650.00 N/A B 1 FWD Approach Constrained? N/A N/A B 2 FWD Approach Constrained? N/A N/A B 1 FWD Approach Reach (in) N/A N/A B 2 FWD Approach Reach (in) N/A N/A B 1 FWD Approach Width (in) N/A N/A B 2 FWD Approach Width (in) N/A N/A B 1 FWD Approach Obstruction? **N/A** B 2 FWD Approach Obstruction? N/A

			N/A B 1 PARA Approach Obstruction?	Yes	N/A	B 2 PARA Approach Obstruction?	N/A
APS Compliance			N/A B 1 PARA Approach Obstruction D	ist (in) 1.5	N/A	B 2 PARA Approach ObstructionDist (in) N/A
Is Button 1 APS or Non-APS?	APS Is Button 2 APS or Non-APS?	N/A	Yes B 1 Clear Floor Space Slope (%)	4.4	N/A	B 2 Clear Floor Space Slope (%)	N/A
No B 1 VibroTact Arrow?	No N/A B 2 VibroTact Arrow?	N/A	Yes B 1 Clear Floor Space XSlope (%)	0.3	N/A	B 2 Clear Floor Space XSlope (%)	N/A
N/A B 1 VibroTact Parallel to Xing?	Yes N/A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	14.8	N/A	B 2 PAR Slope (%)	N/A
N/A B 1 VibroTact Contrast	Yes N/A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	41.0	N/A	B 2 Height (in)	N/A
No B 1 Pilot Light?	No N/A B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	3.0	N/A	B 2 Pressure (#)	N/A
N/A B 1 Pilot Light Illumination?	Yes N/A B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A
N/A B 1 Verbal Walk Cycle?	No N/A B 2 Verbal Walk Cycle?	N/A	MUTCD Compliance				
N/A B 1 Verbal Message Audible?	Yes N/A B 2 Verbal Message Audible?	N/A	Yes B 1 Clear Xing Direction?	earlyMarked	N/A	B 2 Clear Xing Direction?	N/A
No B 1 Locator Tone?	No N/A B 2 Locator Tone?	N/A	B 1 Crossing Direction	To N		B 2 Crossing Direction	N/A
N/A B 1 Percussive Walk Cycle?	No N/A B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo XWalk (in)	0.0	N/A	B 2 DistanceTo XWalk (in)	N/A

N/A

N/A