

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

No

N/A

N/A

N/A

Location: N/A Intersection ID: N/A **Main Street:** Cross Street: N/A

ADA ID: E333E7F6D8DC Signal Type: One Push Button-Non APS **Overall Compliance: No** Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Button Count

N/A B 1 Sign Present?

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 N/A Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

146.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)

Additional Button ID N/A N/A Additional Ped Posts Required

Located In An Island/Median?

Data

No



Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Replace Sign.

Surveyor Notes: TEXT HT 5/16

PROW/ADA: R410.6, TMUTCD 4e.08, R404.2, R406.2, R404.7.3

Total Cost:

700.00





		•			•	
	Yes	B 1 Sign Purpose?	Yes	N/A	B 2 Sign Purpose?	N/A
	No	B 1 Sign Lettering & Contrast?	No	N/A	B 2 Sign Lettering & Contrast?	N/A
	Yes	B 1 Parallel To XWalk?	Yes	N/A	B 2 Parallel To XWalk?	N/A
	Yes	B 1 PAR to Button?	Yes	N/A	B 2 PAR to Button?	N/A
	Yes	B 1 PAR to XWalk?	Yes	N/A	B 2 PAR to XWalk?	N/A
	Yes	B 1 Clear Floor Space?	Yes	N/A	B 2 Clear Floor Space?	N/A
	N/A	B 1 FWD Approach?	Yes	N/A	B 2 FWD Approach?	N/A
0	N/A	B 1 FWD Approach Constrained?	No	N/A	B 2 FWD Approach Constrained?	N/A
	No	B 1 FWD Approach Reach (in)	14.0	N/A	B 2 FWD Approach Reach (in)	N/A
	N/A	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)	N/A
	N/A	B 1 FWD Approach Obstruction?	Yes	N/A	B 2 FWD Approach Obstruction?	N/A
	N/A	B 1 FWD Approach Obstruction Dist (in)	1.0	N/A	B 2 FWD Approach ObstructionDist (in)	N/A
	N/A	B 1 PARA Approach?	Yes	N/A	B 2 PARA Approach?	N/A
	N/A	B 1 PARA Approach Constrained?	No	N/A	B 2 PARA Approach Constrained?	N/A
	No	B 1 PARA Approach Reach (in)	14.0	N/A	B 2 PARA Approach Reach (in)	N/A
	N/A	B 1 PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)	N/A
	N/A	B 1 PARA Approach Obstruction?		N/A	B 2 PARA Approach Obstruction?	N/A
	N/A	B 1 PARA Approach Obstruction Dist (in)		N/A	B 2 PARA Approach ObstructionDist (in)	N/A
	Yes	s B 1 Clear Floor Space Slope (%)		N/A	B 2 Clear Floor Space Slope (%)	N/A
	No	B 1 Clear Floor Space XSlope (%)	3.9	N/A	B 2 Clear Floor Space XSlope (%)	N/A
	N/A	B 1 PAR Slope (%)	8.3 N/A		B 2 PAR Slope (%)	N/A
	Yes	B 1 Height (in)	38.0	N/A	B 2 Height (in)	N/A
	Yes	B 1 Pressure (#)	2.0	N/A	B 2 Pressure (#)	N/A
	Yes	B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A
MUTCD Compliance						
	Yes	B 1 Clear Xing Direction? ClearlyMa	arked	N/A	B 2 Clear Xing Direction?	N/A
		B 1 Crossing Direction	o NW		B 2 Crossing Direction	N/A
	No	B 1 DistanceTo XWalk (in)	104.0	N/A	B 2 DistanceTo XWalk (in)	N/A

Is Button 1 APS or Non-APS?
N/A B 1 VibroTact Arrow?
N/A B 1 VibroTact Parallel to Xing?
N/A B 1 VibroTact Contrast
N/A B 1 Pilot Light?
N/A B 1 Pilot Light Illumination?
N/A B 1 Verbal Walk Cycle?
N/A B 1 Verbal Message Audible?
N/A B 1 Locator Tone?
N/A B 1 Percussive Walk Cycle?

N/A B 1 Extended Press Feature?

N/A B 1 Tone Audible Range?

APS Compliance				
NonAPS		Is Button 2 APS or Non-APS?	N/A	
N/A	N/A	B 2 VibroTact Arrow?	N/A	
N/A	N/A	B 2 VibroTact Parallel to Xing?	N/A	
N/A	N/A	B 2 VibroTact Contrast	N/A	
N/A	N/A	B 2 Pilot Light?	N/A	
N/A	N/A	B 2 Pilot Light Illumination?	N/A	
N/A	N/A	B 2 Verbal Walk Cycle?	N/A	
N/A	N/A	B 2 Verbal Message Audible?	N/A	
N/A	N/A	B 2 Locator Tone?	N/A	
N/A	N/A	B 2 Percussive Walk Cycle?	N/A	
N/A	N/A	B 2 Extended Press Feature?	N/A	

N/A N/A B 2 Tone Audible Range?

N/A N/A	Yes	B 1 Closed Fist Operation
N/A	Yes	B 1 Clear Xing Direction?
N/A		B 1 Crossing Direction
N/A	No	B 1 DistanceTo XWalk (in
N/A	No	B 1 DistanceTo Curb (in)
N/A	Yes	B 1 Diameter (in)