

| Compliance | Description | Data | Compliance | Description | Data |
|------------|---|---------|------------|--|--------------|
| | Button Count | Button1 | Yes | Distant to Additional Button (in) | 177.0 |
| | Additional Button Present? | Yes | | Additional Button ID | 95FBD5FF6686 |
| N/A | Signal Buttons Required? | N/A | N/A | Additional Ped Posts Required | N/A |
| | How Many Ped Street Xings? | 1 | | Located In An Island/Median? | No |
| N/A | B 1 Sign Present? | Yes | N/A | B 2 Sign Present? | N/A |
| Yes | B 1 Sign Purpose? | Yes | N/A | B 2 Sign Purpose? | N/A |
| Yes | B 1 Sign Lettering & Contrast? | Yes | N/A | B 2 Sign Lettering & Contrast? | N/A |
| Yes | B 1 Parallel To XWalk? | Yes | N/A | B 2 Parallel To XWalk? | N/A |
| Yes | B 1 PAR to Button? | Yes | N/A | B 2 PAR to Button? | N/A |
| Yes | B 1 PAR to XWalk? | Yes | N/A | B 2 PAR to XWalk? | N/A |
| Yes | B 1 Clear Floor Space? | Yes | N/A | B 2 Clear Floor Space? | N/A |
| No | B 1 FWD Approach? | No | N/A | B 2 FWD Approach? | N/A |
| N/A | B 1 FWD Approach Constrained? | No | N/A | B 2 FWD Approach Constrained? | N/A |
| N/A | B 1 FWD Approach Reach (in) | 17.0 | N/A | B 2 FWD Approach Reach (in) | N/A |
| N/A | B 1 FWD Approach Width (in) | 60.0 | N/A | B 2 FWD Approach Width (in) | N/A |
| N/A | B 1 FWD Approach Obstruction? | No | N/A | B 2 FWD Approach Obstruction? | N/A |
| N/A | B 1 FWD Approach Obstruction Dist (in) | 15.0 | N/A | B 2 FWD Approach ObstructionDist (in) | N/A |
| No | B 1 PARA Approach? | No | N/A | B 2 PARA Approach? | N/A |
| N/A | B 1 PARA Approach Constrained? | No | N/A | B 2 PARA Approach Constrained? | N/A |
| N/A | B 1 PARA Approach Reach (in) | 17.0 | N/A | B 2 PARA Approach Reach (in) | N/A |
| N/A | B 1 PARA Approach Width (in) | 60.0 | N/A | B 2 PARA Approach Width (in) | N/A |
| N/A | B 1 PARA Approach Obstruction? | No | N/A | B 2 PARA Approach Obstruction? | N/A |
| N/A | B 1 PARA Approach Obstruction Dist (in) | 15.0 | N/A | B 2 PARA Approach ObstructionDist (in) | N/A |
| No | B 1 Clear Floor Space Slope (%) | 7.0 | N/A | B 2 Clear Floor Space Slope (%) | N/A |
| Yes | B 1 Clear Floor Space XSlope (%) | 0.1 | N/A | B 2 Clear Floor Space XSlope (%) | N/A |
| N/A | B 1 PAR Slope (%) | 1.4 | N/A | B 2 PAR Slope (%) | N/A |
| Yes | B 1 Height (in) | 35.0 | N/A | B 2 Height (in) | N/A |
| Yes | B 1 Pressure (#) | 1.5 | N/A | B 2 Pressure (#) | N/A |
| Yes | B 1 Closed Fist Operation? | Yes | N/A | B 2 Closed Fist Operation? | N/A |

| MUTCD Compliance | | | | | |
|------------------|---------------------------|---------------|-----|---------------------------|-----|
| Yes | B 1 Clear Xing Direction? | ClearlyMarked | N/A | B 2 Clear Xing Direction? | N/A |
| | B 1 Crossing Direction | To SE | | B 2 Crossing Direction | N/A |
| Yes | B 1 DistanceTo XWalk (in) | 0.0 | N/A | B 2 DistanceTo XWalk (in) | N/A |
| Yes | B 1 DistanceTo Curb (in) | 60.0 | N/A | B 2 DistanceTo Curb (in) | N/A |
| Yes | B 1 Diameter (in) | 2.0 | N/A | B 2 Diameter (in) | N/A |