

## **Access Compliance Report Public Rights-of-Way** (Pedestrian Signals)



Data

N/A N/A

N/A

Yes

Yes

Yes

Yes

Yes

Yes

Yes

Yes

No

No

N/A

N/A

Yes

6.0

No

No

19.0

21.0

2.0

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Signal Type: Two Push Buttons-Non APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: ADA ID: E81C2D1E66C6 N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

N/A B 1 FWD Approach Reach (in)

N/A B 1 FWD Approach Width (in)

N/A B 1 FWD Approach Obstruction?

**N/A** B 1 PARA Approach Constrained?

N/A B 1 FWD Approach Obstruction Dist (in)

**Button Count** 

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 Parallel To XWalk?

Yes B 1 Clear Floor Space?

Yes B 1 PAR to Button?

Yes B 1 PAR to XWalk?

No B 1 FWD Approach?

No B 1 PARA Approach?

Yes B 1 DistanceTo XWalk (in)

Yes B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Compliance Description

**Button2 N/A** Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes Yes B 2 Sign Purpose?

Yes Yes B 2 Parallel To XWalk?

Yes B 2 PAR to XWalk?

Yes Yes B 2 Clear Floor Space?

No No B 2 FWD Approach?

**No No** B 2 PARA Approach?

34.0 Yes B 2 DistanceTo XWalk (in)

21.0 Yes B 2 DistanceTo Curb (in)

2.0 Yes B 2 Diameter (in)

Yes Yes B 2 PAR to Button?

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes Yes B 2 Sign Lettering & Contrast?

**No N/A** B 2 FWD Approach Constrained?

N/A N/A B 2 FWD Approach Reach (in)

N/A N/A B 2 FWD Approach Width (in)

Yes N/A B 2 FWD Approach Obstruction?

**No N/A** B 2 PARA Approach Constrained?

3.0 N/A B 2 FWD Approach ObstructionDist (in)

Located In An Island/Median?

Data



N/A B 1 Percussive Walk Cycle?

N/A B 1 Extended Press Feature?

N/A B 1 Tone Audible Range?

Possible Solutions: Provide Clear Space.

Surveyor Notes: N/A

No N/A B 2 Percussive Walk Cycle?

No N/A B 2 Tone Audible Range?

No N/A B 2 Extended Press Feature?

PROW/ADA: R404.2, R404.7.1, R404.7.2

Total Cost:





|                                     |        |                                 |        | N/A B 1 PARA Approach Reach (in)      | 48.0       | N/A | B 2 PARA Approach Reach (in)      | 32.0              |
|-------------------------------------|--------|---------------------------------|--------|---------------------------------------|------------|-----|-----------------------------------|-------------------|
|                                     |        |                                 |        | N/A B 1 PARA Approach Width (in)      | 60.0       | N/A | B 2 PARA Approach Width (in)      | 60.0              |
|                                     |        |                                 |        | N/A B 1 PARA Approach Obstruction?    | Yes        | N/A | B 2 PARA Approach Obstruction?    | Yes               |
| APS Compliance                      |        |                                 |        | N/A B 1 PARA Approach Obstruction Dis | t (in) 3.0 | N/A | B 2 PARA Approach Obstruction Dis | t (in) <b>6.0</b> |
| Is Button 1 APS or Non-APS?         | NonAPS | Is Button 2 APS or Non-APS?     | NonAPS | Yes B 1 Clear Floor Space Slope (%)   | 1.8        | Yes | B 2 Clear Floor Space Slope (%)   | 0.6               |
| N/A B 1 VibroTact Arrow?            | No N/A | B 2 VibroTact Arrow?            | No     | No B 1 Clear Floor Space XSlope (%)   | 3.5        | Yes | B 2 Clear Floor Space XSlope (%)  | 0.9               |
| N/A B 1 VibroTact Parallel to Xing? | No N/A | B 2 VibroTact Parallel to Xing? | No     | N/A B 1 PAR Slope (%)                 | 1.8        | N/A | B 2 PAR Slope (%)                 | 1.5               |
| N/A B 1 VibroTact Contrast          | No N/A | B 2 VibroTact Contrast          | No     | Yes B 1 Height (in)                   | 40.0       | Yes | B 2 Height (in)                   | 40.0              |
| N/A B 1 Pilot Light?                | No N/A | B 2 Pilot Light?                | No     | Yes B 1 Pressure (#)                  | 1.0        | Yes | B 2 Pressure (#)                  | 2.0               |
| N/A B 1 Pilot Light Illumination?   | No N/A | B 2 Pilot Light Illumination?   | No     | Yes B 1 Closed Fist Operation?        | Yes        | Yes | B 2 Closed Fist Operation?        | Yes               |
| N/A B 1 Verbal Walk Cycle?          | No N/A | B 2 Verbal Walk Cycle?          | No     | MUTCD Compliance                      |            |     |                                   |                   |
| N/A B 1 Verbal Message Audible?     | No N/A | B 2 Verbal Message Audible?     | No     | Yes B 1 Clear Xing Direction? Clea    | arlyMarked | Yes | B 2 Clear Xing Direction? Clear   | rlyMarked         |
| N/A B 1 Locator Tone?               | No N/A | B 2 Locator Tone?               | No     | B 1 Crossing Direction                | To SW      |     | B 2 Crossing Direction            | To SE             |

No

No

No