

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A N/A No

N/A N/A N/A N/A

N/A

N/A N/A N/A

N/A N/A N/A N/A N/A

> N/A N/A

N/A

N/A

N/A

Main Street: Cross Street: N/A Location: N/A Intersection ID: N/A

Severity Score: BTN 1:N/A BTN 2: N/A No BTN: ADA ID: EDE5D95A6FFC Signal Type: One Push Button-Non APS **Overall Compliance: No** N/A

Compliance Description

B 1 PARA Approach Reach (in)

No B 1 DistanceTo Curb (in)

Yes B 1 Diameter (in)

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

13.0 N/A B 2 PARA Approach Reach (in)

101.0 N/A B 2 DistanceTo Curb (in)

2.0 N/A B 2 Diameter (in)

Data



N/A B 1 Extended Press Feature? N/A B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R404.2, R406.2, R404.7.3

Total Cost:

650.00

N/A

N/A



		Button Count	Button1	N/A	Distant to Additional Button (in)
		Additional Button Present?	No		Additional Button ID
	N/A	Signal Buttons Required?	N/A	N/A	Additional Ped Posts Required
		How Many Ped Street Xings?	1		Located In An Island/Median?
	N/A	B 1 Sign Present?	Yes	N/A	B 2 Sign Present?
	Yes	B 1 Sign Purpose?	Yes	N/A	B 2 Sign Purpose?
	Yes	B 1 Sign Lettering & Contrast?	Yes	N/A	B 2 Sign Lettering & Contrast?
	Yes	B 1 Parallel To XWalk?	Yes	N/A	B 2 Parallel To XWalk?
	Yes	B 1 PAR to Button?	Yes	N/A	B 2 PAR to Button?
	Yes	B 1 PAR to XWalk?	Yes	N/A	B 2 PAR to XWalk?
	Yes	B 1 Clear Floor Space?	Yes	N/A	B 2 Clear Floor Space?
	N/A	B 1 FWD Approach?	Yes	N/A	B 2 FWD Approach?
)	N/A	B 1 FWD Approach Constrained?	No	N/A	B 2 FWD Approach Constrained?
	No	B 1 FWD Approach Reach (in)	13.0	N/A	B 2 FWD Approach Reach (in)
	N/A	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)
	N/A	B 1 FWD Approach Obstruction?	No	N/A	B 2 FWD Approach Obstruction?
	N/A	B 1 FWD Approach Obstruction Dist (in	n) N/A	N/A	B 2 FWD Approach ObstructionDist (in)
	N/A	B 1 PARA Approach?	Yes	N/A	B 2 PARA Approach?
	N/A	B 1 PARA Approach Constrained?	No	N/A	B 2 PARA Approach Constrained?



APS Compliance Is Button 1 APS or Non-APS? **NonAPS** Is Button 2 APS or Non-APS? N/A N/A B 1 VibroTact Arrow? N/A N/A B 2 VibroTact Arrow? N/A N/A B 1 VibroTact Parallel to Xing? N/A B 2 VibroTact Parallel to Xing? N/A N/A B 2 VibroTact Contrast N/A B 1 VibroTact Contrast N/A N/A N/A B 1 Pilot Light? N/A N/A B 2 Pilot Light? N/A **N/A** B 2 Pilot Light Illumination? **N/A** B 1 Pilot Light Illumination? N/A N/A B 1 Verbal Walk Cycle? N/A B 2 Verbal Walk Cycle? N/A N/A B 1 Verbal Message Audible? N/A N/A B 2 Verbal Message Audible? N/A N/A B 1 Locator Tone? N/A N/A B 2 Locator Tone? N/A N/A B 1 Percussive Walk Cycle? N/A B 2 Percussive Walk Cycle? N/A

N/A N/A B 2 Extended Press Feature?

N/A N/A B 2 Tone Audible Range?

	N/A	B 1 PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)	N/A		
	N/A	B 1 PARA Approach Obstruction?	No	N/A	B 2 PARA Approach Obstruction?	N/A		
•	N/A	B 1 PARA Approach Obstruction Dist (in)	N/A	N/A	B 2 PARA Approach ObstructionDist (in)	N/A		
	Yes	B 1 Clear Floor Space Slope (%)	2.9	N/A	B 2 Clear Floor Space Slope (%)	N/A		
	No	B 1 Clear Floor Space XSlope (%)	4.2	N/A	B 2 Clear Floor Space XSlope (%)	N/A		
	N/A	B 1 PAR Slope (%)	4.3	N/A	B 2 PAR Slope (%)	N/A		
	Yes	B 1 Height (in)	40.0	N/A	B 2 Height (in)	N/A		
	Yes	B 1 Pressure (#)	2.0	N/A	B 2 Pressure (#)	N/A		
	Yes	B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A		
	MUTCD Compliance							
	Yes	B 1 Clear Xing Direction? ClearlyMa	rked	N/A	B 2 Clear Xing Direction?	N/A		
		B 1 Crossing Direction To	sw		B 2 Crossing Direction	N/A		
	Yes	B 1 DistanceTo XWalk (in)	0.0	N/A	B 2 DistanceTo XWalk (in)	N/A		
				ı				