

A photograph of a red brick building with a black trash can and a fire hydrant on the sidewalk. The trash can is black and has some white markings. The fire hydrant is yellow and is located on the sidewalk. The sidewalk is made of brick pavers. There is a small white object on the sidewalk near the trash can. The building has a red brick wall and a white door. There are some plants and flowers in front of the building. A person is walking on the sidewalk in the background. A white car is parked on the street.

MUTCD Compliance			
Yes	B 1 Clear Xing Direction?	ClearlyMarked	N/A
	B 1 Crossing Direction	To SE	
Yes	B 1 DistanceTo XWalk (in)	0.0	N/A
Yes	B 1 DistanceTo Curb (in)	60.0	N/A
Yes	B 1 Diameter (in)	2.0	N/A
	B 2 Clear Xing Direction?		N/A
	B 2 Crossing Direction		N/A
	B 2 DistanceTo XWalk (in)		N/A
	B 2 DistanceTo Curb (in)		N/A
	B 2 Diameter (in)		N/A