

## Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

6729E90705EF

205.0

N/A

No

N/A

N/A

N/A

N/A

Intersection ID: N/A Main Street: Cross Street: N/A Location: N/A

ADA ID: F2C1237B824D Signal Type: One Push Button-Non APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

**Compliance Description** 

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

N/A Signal Buttons Required?

**Button Count** 

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

## **Codes/Mitigation Info/Possible Solution**

## Field Measurements/Component Compliance

Compliance Description

**Button1** Yes Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

2.0 N/A B 2 Diameter (in)

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes N/A B 2 Sign Lettering & Contrast?

Located In An Island/Median?

Data

Yes



N/A B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R404.2, R404.3, R406.2

Total Cost:

650.0

N/A N/A N/A N/A N/A N/A N/A N/A

N/A

Yes B 1 Diameter (in)



N/A N/A B 2 Tone Audible Range?



			0			0 0		
	Yes	В 1	Parallel To XWalk?	Yes	N/A	B 2 Parallel To XWalk?	N/A	
3,	Yes	В 1	PAR to Button?	Yes	N/A	B 2 PAR to Button?	N/A	
	Yes	В 1	PAR to XWalk?	Yes	N/A	B 2 PAR to XWalk?	N/A	
	Yes	В 1	Clear Floor Space?	Yes	N/A	B 2 Clear Floor Space?	N/A	
	N/A	B 1	FWD Approach?	Yes	N/A	B 2 FWD Approach?	N/A	
.00	N/A	B 1	FWD Approach Constrained?	No	N/A	B 2 FWD Approach Constrained?	N/A	
	No	B 1	FWD Approach Reach (in)	8.0	N/A	B 2 FWD Approach Reach (in)	N/A	
	N/A	В 1	FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)	N/A	
	N/A	В 1	FWD Approach Obstruction?	Yes	N/A	B 2 FWD Approach Obstruction?	N/A	
	N/A	B 1	FWD Approach Obstruction Dist (in)	4.0	N/A	B 2 FWD Approach ObstructionDist (in)	N/A	
	N/A	В 1	PARA Approach?	Yes	N/A	B 2 PARA Approach?	N/A	
S	N/A	B 1	PARA Approach Constrained?	No	N/A	B 2 PARA Approach Constrained?	N/A	
	Yes	B 1	PARA Approach Reach (in)	6.0	N/A	B 2 PARA Approach Reach (in)	N/A	
	N/A	В 1	PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)	N/A	
	N/A	B 1	PARA Approach Obstruction?	Yes	N/A	B 2 PARA Approach Obstruction?	N/A	
	N/A	B 1	PARA Approach Obstruction Dist (in)	4.0	N/A	B 2 PARA Approach ObstructionDist (in)	N/A	
	No	B 1	Clear Floor Space Slope (%)	4.3	N/A	B 2 Clear Floor Space Slope (%)	N/A	
	No	В 1	Clear Floor Space XSlope (%)	3.0	N/A	B 2 Clear Floor Space XSlope (%)	N/A	
	N/A	В 1	PAR Slope (%)	3.0	N/A	B 2 PAR Slope (%)	N/A	
	Yes	B 1	Height (in)	39.0	N/A	B 2 Height (in)	N/A	
	Yes	B 1	Pressure (#)	1.0	N/A	B 2 Pressure (#)	N/A	
	Yes	В 1	Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A	
	MUTCD Compliance							
	Yes	B 1	Clear Xing Direction? Clearly	/larked	N/A	B 2 Clear Xing Direction?	N/A	
		B 1	Crossing Direction	To SE		B 2 Crossing Direction	N/A	
	No	B 1	DistanceTo XWalk (in)	72.0	N/A	B 2 DistanceTo XWalk (in)	N/A	
	No	B 1	DistanceTo Curb (in)	80.0	N/A	B 2 DistanceTo Curb (in)	N/A	

APS Compliance									
`	Is Button 1 APS or Non-APS?	NonAPS		Is Button 2 APS or Non-APS?					
N/A	B 1 VibroTact Arrow?	N/A	N/A	B 2 VibroTact Arrow?					
N/A	B 1 VibroTact Parallel to Xing?	N/A	N/A	B 2 VibroTact Parallel to Xing?					
N/A	B 1 VibroTact Contrast	N/A	N/A	B 2 VibroTact Contrast					
N/A	B 1 Pilot Light?	N/A	N/A	B 2 Pilot Light?					
N/A	B 1 Pilot Light Illumination?	N/A	N/A	B 2 Pilot Light Illumination?					
N/A	B 1 Verbal Walk Cycle?	N/A	N/A	B 2 Verbal Walk Cycle?					
N/A	B 1 Verbal Message Audible?	N/A	N/A	B 2 Verbal Message Audible?					
N/A	B 1 Locator Tone?	N/A	N/A	B 2 Locator Tone?					
N/A	B 1 Percussive Walk Cycle?	N/A	N/A	B 2 Percussive Walk Cycle?					
N/A	B 1 Extended Press Feature?	N/A	N/A	B 2 Extended Press Feature?					