

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

No

N/A

N/A

N/A N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A

N/A

N/A

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Signal Type: One Push Button-Non APS **Overall Compliance: No** Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A ADA ID: F4DF8E625FE9

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Button1 N/A Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

2.0 N/A B 2 Diameter (in)

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes N/A B 2 Sign Lettering & Contrast?

Located In An Island/Median?

Data

No



N/A B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TM R406.2

Total Cost:

No N/A B 2 Tone Audible Range?



| | Yes B 1 Parallel To XWalk? | Yes N/A | A B 2 Parallel To XWalk? | | |
|------------------------------|--|-------------------|---------------------------------------|--|--|
| MUTCD 4e.08, R404.2, R404.3, | Yes B 1 PAR to Button? | Yes N/A | B 2 PAR to Button? | | |
| | Yes B 1 PAR to XWalk? | Yes N/A | B 2 PAR to XWalk? | | |
| | Yes B 1 Clear Floor Space? | Yes N/A | B 2 Clear Floor Space? | | |
| | N/A B 1 FWD Approach? | Yes N/A | B 2 FWD Approach? | | |
| \$ 650.00 | N/A B 1 FWD Approach Constrained? | No N/A | B 2 FWD Approach Constrained? | | |
| | No B 1 FWD Approach Reach (in) | 8.0 N/A | B 2 FWD Approach Reach (in) | | |
| | N/A B 1 FWD Approach Width (in) | 60.0 N/A | B 2 FWD Approach Width (in) | | |
| | N/A B 1 FWD Approach Obstruction? | Yes N/A | B 2 FWD Approach Obstruction? | | |
| | N/A B 1 FWD Approach Obstruction Dist (i | n) 6.0 N/A | B 2 FWD Approach ObstructionDist (in) | | |
| | N/A B 1 PARA Approach? | Yes N/A | B 2 PARA Approach? | | |
| | N/A B 1 PARA Approach Constrained? | No N/A | B 2 PARA Approach Constrained? | | |
| | Yes B 1 PARA Approach Reach (in) | 8.0 N/A | B 2 PARA Approach Reach (in) | | |
| | N/A B 1 PARA Approach Width (in) | 60.0 N/A | B 2 PARA Approach Width (in) | | |

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

Button Count

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

| | 7 |
|--|---|
| | |

| | | | N/A B 1 PARA Approach Width (in) | 60.0 N/A | B 2 PARA Approach Width (in) | N/A |
|-------------------------------------|--------------------------------------|---------------|--------------------------------------|-------------------|---|---------------|
| | | | N/A B 1 PARA Approach Obstruction? | Yes N/A | B 2 PARA Approach Obstruction? | N/A |
| APS Compliance | | | N/A B 1 PARA Approach Obstruction D | Dist (in) 6.0 N/A | A B 2 PARA Approach ObstructionDist (in | n) N/A |
| Is Button 1 APS or Non-APS? | NonAPS Is Button 2 APS or Non-AP | PS? N/A | No B 1 Clear Floor Space Slope (%) | 2.1 N/A | B 2 Clear Floor Space Slope (%) | N/A |
| N/A B 1 VibroTact Arrow? | No N/A B 2 VibroTact Arrow? | N/A | Yes B 1 Clear Floor Space XSlope (%) |) 1.3 N/A | B 2 Clear Floor Space XSlope (%) | N/A |
| N/A B 1 VibroTact Parallel to Xing? | No N/A B 2 VibroTact Parallel to Xi | King? N/A | N/A B 1 PAR Slope (%) | 1.4 N/A | A B 2 PAR Slope (%) | N/A |
| N/A B 1 VibroTact Contrast | No N/A B 2 VibroTact Contrast | N/A | Yes B 1 Height (in) | 38.0 N/A | B 2 Height (in) | N/A |
| N/A B 1 Pilot Light? | No N/A B 2 Pilot Light? | N/A | Yes B 1 Pressure (#) | 1.5 N/A | B 2 Pressure (#) | N/A |
| N/A B 1 Pilot Light Illumination? | No N/A B 2 Pilot Light Illumination? | n? N/A | Yes B 1 Closed Fist Operation? | Yes N/A | B 2 Closed Fist Operation? | N/A |
| N/A B 1 Verbal Walk Cycle? | No N/A B 2 Verbal Walk Cycle? | N/A | | MUTCD Com | pliance | |
| N/A B 1 Verbal Message Audible? | No N/A B 2 Verbal Message Audib | ble? N/A | Yes B 1 Clear Xing Direction? | learlyMarked N/A | B 2 Clear Xing Direction? | N/A |
| N/A B 1 Locator Tone? | No N/A B 2 Locator Tone? | N/A | B 1 Crossing Direction | To SE | B 2 Crossing Direction | N/A |
| N/A B 1 Percussive Walk Cycle? | No N/A B 2 Percussive Walk Cycle | e? N/A | Yes B 1 DistanceTo XWalk (in) | 0.0 N/A | B 2 DistanceTo XWalk (in) | N/A |
| N/A B 1 Extended Press Feature? | No N/A B 2 Extended Press Featur | ure? N/A | No B 1 DistanceTo Curb (in) | 92.0 N/A | B 2 DistanceTo Curb (in) | N/A |

N/A

Yes B 1 Diameter (in)