

## **Access Compliance Report Public Rights-of-Way** (Pedestrian Signals)



Data

49CA7512F89E

108.0

N/A

Yes

N/A

N/A

N/A N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: N/A **Main Street:** Cross Street: N/A Location: N/A

Signal Type: One Push Button-APS Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A ADA ID: F5FE8562395C **Overall Compliance: No** 

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

Yes B 1 Sign Lettering & Contrast?

**Button Count** 

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 Parallel To XWalk?

Yes B 1 Clear Floor Space?

Yes B 1 PAR to Button?

Yes B 1 PAR to XWalk?

## **Codes/Mitigation Info/Possible Solution**

## Field Measurements/Component Compliance

Compliance Description

Additional Button ID

N/A N/A Additional Ped Posts Required

Yes N/A B 2 Sign Lettering & Contrast?

**No N/A** B 2 FWD Approach Constrained?

10.0 N/A B 2 FWD Approach Reach (in)

N/A N/A B 2 FWD Approach Width (in)

Yes N/A B 2 FWD Approach Obstruction?

7.0 N/A B 2 FWD Approach ObstructionDist (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Yes N/A B 2 Parallel To XWalk?

Yes N/A B 2 Clear Floor Space?

Yes N/A B 2 PAR to Button?

Yes N/A B 2 PAR to XWalk?

Yes N/A B 2 FWD Approach?

Yes N/A B 2 PARA Approach?

2.0 N/A B 2 Diameter (in)

Distant to Additional Button (in)

Located In An Island/Median?

Data

Button1 No

Yes



Yes B 1 Tone Audible Range?

Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: , TMUTCD 4e.08, R406.2

Total Cost:

Yes N/A B 2 Tone Audible Range?





|   |                                 |         | in the second                   |     | N/A B 1 PARA Approach Constrain Yes B 1 PARA Approach Reach (in N/A B 1 PARA Approach Width (in) N/A B 1 PARA Approach Obstruction | ) 10.0 N/A Non? No N | N/A<br>N/A<br>N/A | B 2 PARA Approach Constrained? B 2 PARA Approach Reach (in) B 2 PARA Approach Width (in) B 2 PARA Approach Obstruction? | N/A<br>N/A<br>N/A |
|---|---------------------------------|---------|---------------------------------|-----|--|----------------------|-------------------|---|-------------------|
| Is Button 1 APS or Non-APS?  APS Is Button 2 APS or Non-APS?  N/A |                                 |         |                                 |     | N/A B 1 PARA Approach Obstruction Yes B 1 Clear Floor Space Slope (  | ` '                  |                   | B 2 PARA Approach ObstructionDist (in) B 2 Clear Floor Space Slope (%)  | ) N/A<br>N/A      |
|   | B 1 VibroTact Arrow?            |         | B 2 VibroTact Arrow?            | N/A | Yes B 1 Clear Floor Space XSlope   | •                    |                   | B 2 Clear Floor Space XSlope (%)  | N/A               |
| Yes E   | B 1 VibroTact Parallel to Xing? | Yes N/A | B 2 VibroTact Parallel to Xing? | N/A | N/A B 1 PAR Slope (%)  | 1.1                  | N/A               | B 2 PAR Slope (%)   | N/A               |
| Yes I   | B 1 VibroTact Contrast          | Yes N/A | B 2 VibroTact Contrast          | N/A | Yes B 1 Height (in)  | 44.0 N               | N/A               | B 2 Height (in)   | N/A               |
| Yes I   | B 1 Pilot Light?                | Yes N/A | B 2 Pilot Light?                | N/A | Yes B 1 Pressure (#)   | 2.0                  | N/A               | B 2 Pressure (#)  | N/A               |
| Yes E   | B 1 Pilot Light Illumination?   | Yes N/A | B 2 Pilot Light Illumination?   | N/A | Yes B 1 Closed Fist Operation?   | Yes                  | N/A               | B 2 Closed Fist Operation?  | N/A               |
| Yes E   | B 1 Verbal Walk Cycle?          | Yes N/A | B 2 Verbal Walk Cycle?          | N/A | MUTCD Compliance   |                      |                   |   |                   |
| Yes E   | B 1 Verbal Message Audible?     | Yes N/A | B 2 Verbal Message Audible?     | N/A | Yes B 1 Clear Xing Direction?  | ClearlyMarked N      | N/A               | B 2 Clear Xing Direction?   | N/A               |
| Yes I   | B 1 Locator Tone?               | Yes N/A | B 2 Locator Tone?               | N/A | B 1 Crossing Direction   | То Е                 |                   | B 2 Crossing Direction  | N/A               |
| No E  | B 1 Percussive Walk Cycle?      | Yes N/A | B 2 Percussive Walk Cycle?      | N/A | Yes B 1 DistanceTo XWalk (in)  | 0.0                  | N/A               | B 2 DistanceTo XWalk (in)   | N/A               |
| Yes E   | B 1 Extended Press Feature?     | Yes N/A | B 2 Extended Press Feature?     | N/A | No B 1 DistanceTo Curb (in)  | 125.0 N              | N/A               | B 2 DistanceTo Curb (in)  | N/A               |
|   |                                 |         |                                 |     |  |                      |                   |   |                   |

N/A

Yes B 1 Diameter (in)