


Possible Solutions: Replace Signal Push Button With APS Button on New Post. Remove & Relocate Sign.

Surveyor Notes: N/A

PROW/ADA: TMUTCD 4e.08, R404.2, R404.3, R406.2, R404.7.3, R209.1, MUTCD 4e.10

Total Cost: \$ 650.00



APS Compliance			
Is Button 1 APS or Non-APS?	APS	Is Button 2 APS or Non-APS?	N/A
Yes B 1 VibroTact Arrow?	Yes	N/A B 2 VibroTact Arrow?	N/A
Yes B 1 VibroTact Parallel to Xing?	Yes	N/A B 2 VibroTact Parallel to Xing?	N/A
Yes B 1 VibroTact Contrast	Yes	N/A B 2 VibroTact Contrast	N/A
Yes B 1 Pilot Light?	Yes	N/A B 2 Pilot Light?	N/A
Yes B 1 Pilot Light Illumination?	Yes	N/A B 2 Pilot Light Illumination?	N/A
No B 1 Verbal Walk Cycle?	Yes	N/A B 2 Verbal Walk Cycle?	N/A
N/A B 1 Verbal Message Audible?	Yes	N/A B 2 Verbal Message Audible?	N/A
Yes B 1 Locator Tone?	Yes	N/A B 2 Locator Tone?	N/A
Yes B 1 Percussive Walk Cycle?	Yes	N/A B 2 Percussive Walk Cycle?	N/A
Yes B 1 Extended Press Feature?	Yes	N/A B 2 Extended Press Feature?	N/A
Yes B 1 Tone Audible Range?	Yes	N/A B 2 Tone Audible Range?	N/A

MUTCD Compliance			
Yes B 1 Clear Xing Direction?	ClearlyMarked	N/A B 2 Clear Xing Direction?	N/A
B 1 Crossing Direction	To S	B 2 Crossing Direction	N/A
Yes B 1 DistanceTo XWalk (in)	0.0	N/A B 2 DistanceTo XWalk (in)	N/A
No B 1 DistanceTo Curb (in)	80.0	N/A B 2 DistanceTo Curb (in)	N/A
Yes B 1 Diameter (in)	2.0	N/A B 2 Diameter (in)	N/A