

## Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A

No

N/A

Intersection ID: N/A Main Street: Cross Street: N/A Location: N/A

ADA ID: FA46889FC719 Signal Type: One Push Button-Non APS Overall Compliance: No Severity Score: BTN 1:N/A BTN 2: N/A No BTN: N/A

Compliance Description

N/A Signal Buttons Required?

Additional Button Present?

How Many Ped Street Xings?

No B 1 Sign Lettering & Contrast?

N/A B 1 FWD Approach Constrained?

No B 1 FWD Approach Reach (in)

N/A B 1 FWD Approach Width (in)

N/A B 1 PARA Approach?

**N/A** B 1 FWD Approach Obstruction?

**N/A** B 1 FWD Approach Obstruction Dist (in)

**Button Count** 

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

Yes B 1 Parallel To XWalk?

Yes B 1 Clear Floor Space?

N/A B 1 FWD Approach?

Yes B 1 PAR to Button?

Yes B 1 PAR to XWalk?

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Compliance Description

**Button1 N/A** Distant to Additional Button (in)

Yes N/A B 2 Sign Present?

Yes N/A B 2 Sign Purpose?

Yes N/A B 2 PAR to Button?

Yes N/A B 2 PAR to XWalk?

Yes N/A B 2 FWD Approach?

Yes N/A B 2 PARA Approach?

Yes N/A B 2 Parallel To XWalk?

Yes N/A B 2 Clear Floor Space?

Additional Button ID

N/A N/A Additional Ped Posts Required

No N/A B 2 Sign Lettering & Contrast?

**No N/A** B 2 FWD Approach Constrained?

6.0 N/A B 2 FWD Approach Reach (in)

6.0 N/A B 2 FWD Approach Width (in)

Yes N/A B 2 FWD Approach Obstruction?

**6.0** N/A B 2 FWD Approach ObstructionDist (in)

Located In An Island/Median?

Data



Possible Solutions: Remove & Replace Sign. Provide Push Button Extension. Remove and Replace Clear Space.

Surveyor Notes: TEXT HT 5/16

PROW/ADA: R410.6, R404.2, R406.2

Total Cost:

	\$	1150.00
/ - [	1	

				N/A B 1 PARA Approach Constrained?	No No	N/A	B 2 PARA Approach Constrained?	N/A
	1 1			Yes B 1 PARA Approach Reach (in)	6.0	N/A	B 2 PARA Approach Reach (in)	N/A
				N/A B 1 PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)	N/A
				N/A B 1 PARA Approach Obstruction?	Yes	N/A	B 2 PARA Approach Obstruction?	N/A
APS Compliance			N/A B 1 PARA Approach Obstruction D	Dist (in) <b>6.0</b>	N/A	B 2 PARA Approach ObstructionDist (in	) <b>N/A</b>	
Is Button 1 APS or Non-APS?	NonAPS	Is Button 2 APS or Non-APS?	N/A	Yes B 1 Clear Floor Space Slope (%)	5.2	N/A	B 2 Clear Floor Space Slope (%)	N/A
N/A B 1 VibroTact Arrow?	N/A N/A	B 2 VibroTact Arrow?	N/A	No B 1 Clear Floor Space XSlope (%)	) 3.3	N/A	B 2 Clear Floor Space XSlope (%)	N/A
N/A B 1 VibroTact Parallel to Xing?	N/A N/A	B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	7.2	N/A	B 2 PAR Slope (%)	N/A
N/A B 1 VibroTact Contrast	N/A N/A	B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	34.5	N/A	B 2 Height (in)	N/A
N/A B 1 Pilot Light?	N/A N/A	B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	2.0	N/A	B 2 Pressure (#)	N/A
N/A B 1 Pilot Light Illumination?	N/A N/A	B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	N/A
N/A B 1 Verbal Walk Cycle?	N/A N/A	B 2 Verbal Walk Cycle?	N/A	MUTCD Compliance				
N/A B 1 Verbal Message Audible?	N/A N/A	B 2 Verbal Message Audible?	N/A	Yes B 1 Clear Xing Direction? C	learlyMarked	N/A	B 2 Clear Xing Direction?	N/A
N/A B 1 Locator Tone?	N/A N/A	B 2 Locator Tone?	N/A	B 1 Crossing Direction	To SW		B 2 Crossing Direction	N/A
N/A B 1 Percussive Walk Cycle?	N/A N/A	B 2 Percussive Walk Cycle?	N/A	Yes B 1 DistanceTo XWalk (in)	0.0	N/A	B 2 DistanceTo XWalk (in)	N/A
N/A B 1 Extended Press Feature?	N/A N/A	B 2 Extended Press Feature?	N/A	Yes B 1 DistanceTo Curb (in)	43.0	N/A	B 2 DistanceTo Curb (in)	N/A
N/A B 1 Tone Audible Range?	N/A N/A	B 2 Tone Audible Range?	N/A	Yes B 1 Diameter (in)	2.0	N/A	B 2 Diameter (in)	N/A