


Access Compliance Report

Public Rights-of-Way

(Island Curb Cuts)

Intersection ID: 8289	Main Street: GRIER_RD	Cross Street: NEWELL-HICKORY_GROVE_RD	Location: SE
ADA ID: 7AED33E252EB	Curb Cut Type: MedianRefuge2	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 1.25	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Refuge.		Yes	Refuge 1 Length (In)	42.5	N/A	Gutter 1 Ponding?	N/A
			Yes	Refuge 1 Width (In)	96.0	N/A	Gutter 1 Lip Ht (In)	N/A
			Yes	Refuge 1 Slope (%)	2.0	N/A	Gutter 1 Slope (%)	N/A
			Yes	Refuge 1 X Slope (%)	2.9	N/A	Gutter 1 X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	DWS 1 Provided?	N/A
			N/A	X Walk 1 Direction	To W	N/A	DWS 1 Contrast?	N/A
			N/A	X Walk 1 Width (In)	N/A	N/A	DWS 1 Length (In)	N/A
			N/A	Road 1 Slope (%)	1.5	N/A	DWS 1 Full Width?	N/A
			N/A	Road 1 X Slope (%)	1.0	N/A	DWS 1 Offset (In)	N/A
Surveyor Notes: N/A			Yes	Refuge 2 Length (In)	42.5	N/A	Gutter 2 Ponding?	N/A
			Yes	Refuge 2 Width (In)	96.0	N/A	Gutter 2 Lip Ht (In)	N/A
			Yes	Refuge 2 Slope (%)	4.8	N/A	Gutter 2 Slope (%)	N/A
			Yes	Refuge 2 X Slope (%)	3.8	N/A	Gutter 2 X Slope (%)	N/A
			N/A	Painted X Walk2?	No	N/A	DWS 2 Provided?	N/A
			N/A	X Walk 2 Direction	To E	N/A	DWS 2 Contrast?	N/A
			N/A	X Walk 2 Width (In)	N/A	N/A	DWS 2 Length (In)	N/A
			N/A	Road 2 Slope (%)	2.5	N/A	DWS 2 Full Width?	N/A
			N/A	Road 2 X Slope (%)	2.4	N/A	DWS 2 Offset (In)	N/A
			N/A	Refuge 3 Length (in)	N/A	N/A	Gutter 3 Ponding?	N/A
PROW/ADA: N/A			N/A	Refuge 3 Width (in)	N/A	N/A	Gutter 3 Lip Ht (in)	N/A
			N/A	Refuge 3 Slope (%)	N/A	N/A	Gutter 3 Slope (%)	N/A
			N/A	Refuge 3 XSlope (%)	N/A	N/A	Gutter 3 XSlope (%)	N/A
			N/A	Painted X Walk3?	No	N/A	DWS 3 Provided?	N/A
			N/A	X Walk 3 Direction	N/A	N/A	DWS 3 Contrast?	N/A
			N/A	X Walk 3 Width (in)	N/A	N/A	DWS 3 Length (in)	N/A
			N/A	Road 3 Slope (%)	N/A	N/A	DWS 3 Full Width?	N/A
			N/A	Road 3 XSlope (%)	N/A	N/A	DWS 3 Offset (in)	N/A
			Yes	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
			N/A	Obstruction Type		N/A	Storm Grate/Utility Type	
Total Cost: \$ 3000.00					N/A			N/A
			N/A	Surface Condition	Good			
